

ID No. 738 <b>Proc</b>	duct/Process Change Notification	Date 17.01.2020
Product	Ordering Code	
BGS5	L30960N3300Ax00	
	L30960N3300B100	
	L30960N3300C100	
Ordering Code changes:	☐ Yes	
New Ordering Code:		
eason of Change:		
Technical requirement	☐ Change of production proces	s/logistical changes
Customer requirement	Location of production moved	
· ⊠ Quality improvement	☐ Other:	
Description of change:	Introduction of minor modifications on Java embedd The implemented change improves the directory parainternal flash file system, which can store application needed for customer Java applications, TLS and OT All changes are not approval relevant and done on a	th access check of n-specific data or da FAP functionality.
	For identification of improved firmware a new applic (ARN) will be introduced and shared together with ti shipments in a separate follow up PCN In case of further questions our Technical Sales tea comprehensive support.	ation revision number ming note for first
Schedule details:		
Availability of SW for evaluation:	Q1 2020, details follow in separate PCN update	
Availability of modules ex Thales warehouse:	Q1 2020, details follow in separate PCN update	
Timing note:	If Thales does not receive a notification to the contra 6 weeks, Thales assumes that the customer agrees	
Quality assurance measurements:	The new version fulfils all internal test requirements Quality Management process and philosophy.	according to our
ttachments: one		
17.0	1.2020 1	7.01.2020

X i.V. S. Cumar

Product Lifecycle Manager Signed by: Armin Dimai 10015210 X i. for Augun

Vice President Quality Management Signed by: ERDMANN Joerg