	HF14FF Series Vent hole sealing change	Versions: 2
		Date: 24.06.2020
	PMI 202012-01	Page 1 / of 2

Subject of Change

HF14FF series vent hole sealing method change

Affected Products


HF14FF series products.

Reason for Change

HF14FF series vent hole sealing method change

Change detail:

The plastic sealing of the base is replaced by the hot riveting plastic sealing of the shell






HF14FF Series Vent hole sealing change

Versions: 2

Date: 24.06.2020

PMI 202012-01

Page 2 / of 2



Time Schedule for Change:

March 2021