



## PRODUCT CHANGE NOTIFICATION

Date: September 18, 2015  
PCN: PCN LEDIL 109 a, b, c, d

---

**Subject:** PCN 109.b – Change of assembly instructions

**Description:** As part of our continuous improvement process regarding the quality of our products LEDiL has updated C13806\_MIRELLA-XW-PF assembly instructions to include glue for fastening.

**Time line:** This change is valid immediately

**Affected products:** C13806\_MIRELLA-XW-PF

**Included in assemblies:** CN14209\_MIRELLA-XW-PF-VER013  
CN14211\_MIRELLA-XW-CL-PF-VER013  
CN14212\_MIRELLA-XW-DL-PF-VER013  
CN14568\_MIRELLA-XW-DL-PF  
CN14572\_MIRELLA-XW-CL-PF  
CN14576\_MIRELLA-XW-RZL-PF  
CN14755\_MIRELLA-XW-PF-XTM

**Changes:** C13806\_MIRELLA-XW-PF assembly instructions has been updated to include glue for fastening. This change does not have effect on optical performance of the products.

**Contact information:** Tero Mäkinen  
LEDIL Oy  
Salorankatu 10  
24240 SALO, FINLAND  
tero.makinen@ledil.com