

## Product Code Change

Keyboard Switch

Issue Date  
August,17,2020

No. AMP-Z-2007029

### Notice of product code change due to change of country of origin for Keyboard switch (B3K)

#### Effective Date

Effective since October,1,2020.

#### Changes

| Models     | Old Product Code | New Product Code |
|------------|------------------|------------------|
| B3K-L135   | B3K 0032E        | B3K 0100C        |
| B3K-T135   | B3K 0020A        | B3K 0101A        |
| B3K-T135-L | B3K 0021M        | B3K 0102M        |
| B3K-T135C  | B3K 0018M        | B3K 0103H        |



#### Other Changes

| Before the change                                                                                                                                        | After the change                                                                                                                                          |
|----------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p><b>The country of origin</b><br/>Japan</p> <p><b>Display of the country of origin.</b><br/>MADE IN JAPAN<br/>LOT No.: □□□□R□</p> <p>MADE IN JAPAN</p> | <p><b>The country of origin.</b><br/>China</p> <p><b>Display of the country of origin.</b><br/>MADE IN CHINA<br/>LOT No.: □□□□C□</p> <p>MADE IN CHINA</p> |

Specifications in this product news are as of the issue date and are subject to change without notice.  
Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.