

Product change notification (PCN)

Title / short description	HMI VISU+ 2.53 RELEASE
Affected article category	HMIs and industrial PCs
Change category	Production start, Software modification
Change number	CDR190065-04

Purpose/objective of the change

New software package

Detailed description of the change

1. Adjustment of 1GHz CPU Voltage
 2. Bugfix - frequent access to the RTC out of the application
 3. New Drivers released:
 a. Modbus TCP-Server for Windows CE
 b. IEC 61870-104 Server for Windows CE
 Bugfix and maintenance

Identifying characteristics

Software update

Start of Production (SOP)	-	Last Time Delivery (LTD)	-
Effective date (EOP)	2020-04-07	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|--|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure | <input checked="" type="checkbox"/> Product improvement with customer benefits | |
| <input type="checkbox"/> Others | | |

Attachments

- CDR190065 - HMI VISU+ 2.53 RELEASE - Impacted Articles (1).pdf
- Material_list.csv
- PCN-CDR190065-04 _DE
- PCN-CDR190065-04 HMI VISU+ 2.53 RELEASE_EN

Material list

Item	Article Type	Revision/production batch		Item	Substitute item Type
		old	new		
2402629	TP 3043W	03	04		
2402630	TP 3090W	03	04		
2402631	TP 3154W	03	04		
2403459	TP 3070W/P	03	04		
2403460	TP 3090W/P	03	04		
2403461	TP 3120W/P	03	04		
1090070	TP 3057V/WT SER	01	02		
1090071	TP 3070W/WT SER	01	02		
1090373	TPM090STW-10/200111201 S00122	01	02		
1102172	TPM121STM-10/200111201 S00122	01	02		
1029281	TP 3150S/WT	01	02		
1029308	TP 3120W/WT	01	02		
1029309	TP 3150S/WT-65	01	02		
1029343	TP 3121S/WT-65	01	02		
1029352	TP 3120W/WT-65	01	02		
1034352	TP 3070W/WT-65 SER	01	02		
1034400	TP 3070W SER	01	02		
1044266	TP 3070W/WT-65	01	02		
1044278	TP 3057V/WT-65	01	02		
1051756	TP 3121S/WT-65 SER	01	02		
1053257	TP 3070W SER IT 00	01	02		
2400453	TP 3057V	04	05		
2400454	TP 3070W	04	05		
2400455	TP 3105S	04	05		
2400457	TP 3120W	04	05		
2400458	TP 3150S	05	06		
2401615	TP 3057Q LOGO	04	05		
2401693	TPM 3120 331	02	03		
1082740	TP090SKW/200114031 S00122	01	02		
2400452	TP 3057Q	04	05		
2401693	TPM 3120 331	02	03		
2403465	TP 3070W/WT	02	03		
2403466	TP 3121S/WT	02	03		
2403862	TP 3185W/P	03	04		
2404286	TP 3043W/WT	03	04		
2404516	TPM 3043	-	-		
2404517	TPM 3057	-	-		
2404518	TPM 3070	-	-		

Item	Article Type	Revision/production batch		Item	Substitute item Type
		old	new		
2404519	TPM 3090	-	-		
2404520	TPM 3105	-	-		
2404521	TPM 3121	-	-		
2404522	TPM 3120	-	-		
2404524	TPM 3150	-	-		
2404525	TPM 3154	-	-		
1086928	TP 3090H/P/WT KR 01	00	01		
1046666	BTP 2070W	06	08		
1046667	BTP 2102W	06	08		
1050387	BTP 2043W	07	08		
2400456	TP 3121S	04	05		
2403464	TP 3057V/WT	03	04		
2403462	TP 3156W/P	04	05		

Article	Description	Site
1029281	TP 3150S/WT	Phoenix Contact HMI-IPC Technology GmbH
1029308	TP 3120W/WT	Phoenix Contact HMI-IPC Technology GmbH
1029309	TP 3150S/WT-65	Phoenix Contact HMI-IPC Technology GmbH
1029343	TP 3121S/WT-65	Phoenix Contact HMI-IPC Technology GmbH
1029352	TP 3120W/WT-65	Phoenix Contact HMI-IPC Technology GmbH
1034352	TP 3070W/WT-65 SER	Phoenix Contact HMI-IPC Technology GmbH
1034400	TP 3070W SER	Phoenix Contact HMI-IPC Technology GmbH
1044266	TP 3070W/WT-65	Phoenix Contact HMI-IPC Technology GmbH
1044278	TP 3057V/WT-65	Phoenix Contact HMI-IPC Technology GmbH
1046666	BTP 2070W	Phoenix Contact Development and Manufacturing
1046667	BTP 2102W	Phoenix Contact Development and Manufacturing
1050387	BTP 2043W	Phoenix Contact Development and Manufacturing
1051756	TP 3121S/WT-65 SER	Phoenix Contact HMI-IPC Technology GmbH
1053257	TP 3070W SER IT 00	Phoenix Contact HMI-IPC Technology GmbH
2400452	TP 3057Q	Phoenix Contact HMI-IPC Technology GmbH
2400453	TP 3057V	Phoenix Contact HMI-IPC Technology GmbH
2400454	TP 3070W	Phoenix Contact HMI-IPC Technology GmbH
2400455	TP 3105S	Phoenix Contact HMI-IPC Technology GmbH
2400456	TP 3121S	Phoenix Contact HMI-IPC Technology GmbH
2400457	TP 3120W	Phoenix Contact HMI-IPC Technology GmbH
2400458	TP 3150S	Phoenix Contact HMI-IPC Technology GmbH
2401433	TP121SKM/200614041 S00066	Phoenix Contact HMI-IPC Technology GmbH
2401615	TP 3057Q LOGO	Phoenix Contact HMI-IPC Technology GmbH
2401693	TPM 3120 331	Phoenix Contact HMI-IPC Technology GmbH
2402629	TP 3043W	Phoenix Contact HMI-IPC Technology GmbH
2402630	TP 3090W	Phoenix Contact HMI-IPC Technology GmbH
2402631	TP 3154W	Phoenix Contact HMI-IPC Technology GmbH
2403459	TP 3070W/P	Phoenix Contact HMI-IPC Technology GmbH
2403460	TP 3090W/P	Phoenix Contact HMI-IPC Technology GmbH
2403461	TP 3120W/P	Phoenix Contact HMI-IPC Technology GmbH
2403462	TP 3156W/P	Phoenix Contact HMI-IPC Technology GmbH
2403464	TP 3057V/WT	Phoenix Contact HMI-IPC Technology GmbH
2403465	TP 3070W/WT	Phoenix Contact HMI-IPC Technology GmbH