

## 1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
01	002	041	0000000532	0751.0056	Circuit protection	OG Clip 5x20/6.3x32 tinned bronze	n/a
				0751.0141		OG Clip 5x20/6.3x32 tinned bronze	n/a
				0751.0142		OG Clip 5x20/6.3x32 tinned brass	n/a
				0751.0099		OG Clip 5x20/6.3x32 tinned bronze	n/a
				0751.0100		OG Clip 5x20/6.3x32 tinned brass	n/a



\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

## 2 Type of change

- Changed inscription

## 3 Detailed description of change

Updated approval marks on the metal fuse clip.

Old product marking	New product marking
	

## 4 Reason of change

Product improvement acc. to approvals.

## 5 Release date

The change will be rolled-out starting ww 45/2017 (Date code 1745 or higher on label)

## 6 Impact of change and recommended action

Form	Yes	Inscription on clip changed
Fit	No	No change for dimension
Function	No	No functional change
Production Site	No	No change of the production site
Product Label	No	No change on the label
Packaging	No	No change in packaging

## 7 Reference Documents / Attachments

Kind of document	Remarks
<a href="#">Data sheet</a>	Fuse clip <i>OG Clip 5x20 / 6.3x32</i>

Product Change Notification					OG Clip 5x20/6.3x32 inscription		
owner	creation date	release date	released by	change order no	rev	page	D10-017-786
dislercy	07.08.2017	19.10.2017	nowakfr	2012544	A	1 of 1	