

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	007	003	0000002362	See list below	Connectors	1624	n/a





*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected				
6163.0010	6163.0011	6163.0012	6163.0013	6163.0014
6163.0023	6163.0024	6163.0026	6163.0027	6163.0028
6163.0031	6163.0036			

2 Type of change

Change of approval markings on product and packaging label.

3 Detailed description of change

Old product approval	New product approval
	
Old label	New label
	

4 Reason of change

New Chinese CCC Approval certificate for the product type 1624.

5 Release date

The change will be rolled-out starting ww39/2019 (Date code 1939 or higher on label) and lasts approx. 6 months depending on the variant.

Product Change Notification					1624 change of marking		
owner	creation date	release date	released by	change order no	rev	page	D10-038-530
sariogar	25.07.2019	23.09.2019	limachcl	2018079	A	1 of 2	

6 Impact of change and recommended action

Form	Yes	New CCC approvals marking added to molding body
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	Yes	Approvals markings added to packaging label
Packaging	No	-

7 Reference Documents / Attachments

Kind of document	Remarks
Data sheet 1624	

Product Change Notification					1624 change of marking		
owner	creation date	release date	released by	change order no	rev	page	D10-038-530
sariogar	25.07.2019	23.09.2019	limachcl	2018079	A	2 of 2	