

### 1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	007	042	0000002281	See list below	Connectors	4781	
02	007	042	0000002282	See list below	Connectors	4782	

\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected					
4781.0000	4781.0100	3-122-692	3-122-693	3-122-696	3-122-697
4782.0000	4782.0100	3-122-694	3-122-695	3-122-698	3-122-699

### 2 Type of change

- Change of approval markings
- New material for cable guard

### 3 Detailed description of change

Old label		New label	
4781	4782	4781	4782
Old product approval		New product approval	
4781	4782	4781	4782
Old material of cable guard		New material of cable guard	
PVC		Silicone	

### 4 Reason of change

- New with Japanese approval (including importer)
- Cable guard material is new halogen free.

### 5 Release date

The change will be rolled-out starting ww 32/2020 (Date code 2032 or higher on label). Those changes do have no effect on the validity of the approval certificates.

### 6 Impact of change and recommended action

Form	Yes	New appearance of approval markings and new material of cable guard
Fit	No	No change for dimension
Function	No	No change in function
Manufacturing	No	No change for manufacturing site
Label	Yes	Label new with Japanese approval (including importer)

Product Change Notification					PCN 4781/4782		
owner	creation date	release date	released by	change order no	rev	page	D10-045-213
huberth	10.07.2020	10.07.2020	muehlema	2020297	B	1 of 2	

Packaging                      No            No change in packaging

**7    Reference Documents / Attachments**

Kind of document	Remarks
<a href="#">Data Sheet 4781</a>	
<a href="#">Data Sheet 4782</a>	

Product Change Notification					PCN 4781/4782		
owner	creation date	release date	released by	change order no	rev	page	D10-045-213
huberth	10.07.2020	10.07.2020	muehlema	2020297	B	2 of 2	