

## 1 Products affected

Product hierarchy no. *	Part no.	SBU	Type / Description	Customer part no.		
SBU PG PUG Type				·		
01 001 025 UST 1206	See list below	Circuit Protection	UST 1206 Chip Fuse			
*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)						

List of part numbers affected					
3413.0326.xx	3413.0327.xx	3413.0328.xx	3413.0329.xx	3413.0330.xx	
3413.0331.xx	3413.0332.xx				

# 2 Type of change

Modified breaking capacity rating

# 3 Detailed description of change

Modified electrical rating of breaking capacity of 400A@32VDC

Old product rating	New product rating
150A@24VDC	400A@32VDC tau <0.1ms

### 4 Reason of change

New evaluation through UL (Underwriters Laboratories).

#### 5 Release date

The change took effect in ww 17/2018 (Date code 1817 or higher on label).

# 6 Impact of change and recommended action

Form No No change in form
Fit No No change for dimension

Function Yes Re-evaluation of new breaking capacity rating

Manufacturing No No change for manufacturing site

Label No No change on label
Packaging No No change in packaging

#### 7 Reference Documents / Attachments

Kind of document	Remarks
<u>Datasheet</u>	

Product Change Notification				PCN UST 1206 400A@32VDC					
owner		creation date	release date	released by	change order no	rev	page	D40 00F 244	
schmidre	)	09.05.2018	09.05.2018	haeckima	2015362	В	1 of 1	D10-025-314	