

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	
1	1. Discontinue Items																	
2																		
3																		
4																		
5			FD	group code	P/N	Product code	Report to Marketing group	Discontinue	1:before Phase-Out 1	2:this time Phase-Out 2	1:before Obsolete 1	2:this time Obsolete 2	Substitution Level	ReplacementP/N Company name	ReplacementP/N	Reason	Marketing group	Engineering DEPT.
6																		
7	N255	X35	QFSCB1	MP4202(DNSO)	38146143	A		200610		200801		200804	1	TOSHIBA	MP4210	Chip Shrink	(P-D-EI)	[P-OU-GI]
8	N256	X35	QFSCB2	MP4203(DNSO)	38146144	A		200610		200801		200804	1	TOSHIBA	MP4211	Chip Shrink	(P-D-EI)	[P-OU-GI]
9	N257	X35	QFTCBE	MP4801(LBTEC)	36403721	A		200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
10	N258	X35	QFTCBB	MP6403	36405315	A		200610		200801		200804	1	TOSHIBA	MP6404	Chip Shrink	(P-D-EI)	[P-OU-GI]
11	N259	X35	QFTCBB	MP6403(LB1)	36405317	A		200610		200801		200804	1	TOSHIBA	MP6404	Chip Shrink	(P-D-EI)	[P-OU-GI]
12	N260	X35	QFTCBB	MP6403(LBSAN)	36405319	A		200610		200801		200804	1	TOSHIBA	MP6404	Chip Shrink	(P-D-EI)	[P-OU-GI]
13	N261	X35	QFTCBB	MP6403(Q)	38146151	A		200610		200801		200804	1	TOSHIBA	MP6404	Chip Shrink	(P-D-EI)	[P-OU-GI]
14	N262	X35	QF3	MP6631(Q)	38146153	A		200610		200801		200804	3	TOSHIBA	2SK3562	No Order Forecast	(P-D-EI)	[P-OU-GI]
15	N263	X35	QYT	S6A14J(K)	38139001	A		200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
16	N264	X35	QCW	2SC5129(LBSONY,A,F	38151600	A		200610		200801		200804	1	TOSHIBA	SC5129(LBSONY,A	Integration of products	(P-D-EI)	[O-GI-NI]
17	N265	X35	QCW	2SC5129(LBT TOKU,AF	38151977	A		200610		200801		200804	1	TOSHIBA	C5129(LBT TOKU,A	Integration of products	(P-D-EI)	[O-GI-NI]
18	N266	X35	QCW	2SC5129(TEM,F)	38151676	A		200610		200801		200804	1	TOSHIBA	2SC5129(TEM,Q)	Integration of products	(P-D-EI)	[O-GI-NI]
19	N267	X35	QCW	2SC5143(TEM,F)	38151678	A		200610		200801		200804	1	TOSHIBA	2SC5143(TEM,Q)	Integration of products	(P-D-EI)	[O-GI-NI]
20	N268	X35	QCW	2SC5150(TEM,F)	38151911	A		200610		200801		200804	1	TOSHIBA	2SC5150(TEM,Q)	Integration of products	(P-D-EI)	[O-GI-NI]
21	N269	X35	QCW	2SC5339(TEM,F)	38152118	A		200610		200801		200804	1	TOSHIBA	2SC5339(TEM,Q)	Integration of products	(P-D-EI)	[O-GI-NI]
22	N270	X35	QCW	2SC5386(TEM,F)	38151679	A		200610		200801		200804	1	TOSHIBA	2SC5386(TEM,Q)	Integration of products	(P-D-EI)	[O-GI-NI]
23	N271	X35	QCW	2SC5411(TEM,F)	38151912	A		200610		200801		200804	1	TOSHIBA	2SC5411(TEM,Q)	Integration of products	(P-D-EI)	[O-GI-NI]
24	N272	X35	QCW	2SC5716(LBSONY,A,F	38151613	A		200610		200801		200804	1	TOSHIBA	5C5716(LBSONY,A	Integration of products	(P-D-EI)	[O-GI-NI]
25	N273	X35	QCW	2SC5855(TEM,F)	38151617	A		200610		200801		200804	1	TOSHIBA	2SC5855(TEM,Q)	Integration of products	(P-D-EI)	[O-GI-NI]
26	N274	X35	QCW	2SC5856(TEM,F)	38151619	A		200610		200801		200804	1	TOSHIBA	2SC5856(TEM,Q)	Integration of products	(P-D-EI)	[O-GI-NI]
27	N275	X35	QCW	2SC6041(LBSAN,A,F)	38151630	A		200610		200801		200804	1	TOSHIBA	SC6041(LBSAN,A,C	Integration of products	(P-D-EI)	[O-GI-NI]
28	N276	X35	QCW	2SC6041(TEM,F)	38151629	A		200610		200801		200804	1	TOSHIBA	2SC6041(TEM,Q)	Integration of products	(P-D-EI)	[O-GI-NI]
29	N277	X35	QCW	2SD2499(FA,TEM,F)	38151871	A		200610		200801		200804	1	TOSHIBA	2SD2499(FA,TEM,Q	Integration of products	(P-D-EI)	[O-GI-NI]
30	N278	X35	QCW	2SD2499(LBMA,TEM,F	38151682	A		200610		200801		200804	1	TOSHIBA	D2499(LBMA,TEM	Integration of products	(P-D-EI)	[O-GI-NI]
31	N279	X35	QCW	2SD2499(LBMBSK,A,F	38151730	A		200610		200801		200804	1	TOSHIBA	D2499(LBMBSK,A	Integration of products	(P-D-EI)	[O-GI-NI]
32	N280	X35	QCW	2SD2499(TEM,F)	38151680	A		200610		200801		200804	1	TOSHIBA	2SD2499(TEM,Q)	Integration of products	(P-D-EI)	[O-GI-NI]
33	N281	X35	QCW	2SD2500(LBSHRPD,AF	38151636	A		200610		200801		200804	1	TOSHIBA	D2500(LBSHRPD,A	Integration of products	(P-D-EI)	[O-GI-NI]
34	N282	X35	QCW	2SD2539(FA,TEM,F)	38151685	A		200610		200801		200804	1	TOSHIBA	2SD2539(FA,TEM,Q	Integration of products	(P-D-EI)	[O-GI-NI]
35	N283	X35	QCW	2SD2539(LBMBSK,A,F	38151731	A		200610		200801		200804	1	TOSHIBA	D2539(LBMBSK,A	Integration of products	(P-D-EI)	[O-GI-NI]
36	N284	X35	QCW	2SD2539(LBSONY,A,F	38151642	A		200610		200801		200804	1	TOSHIBA	D2539(LBSONY,A	Integration of products	(P-D-EI)	[O-GI-NI]
37	N285	X35	QCW	2SD2539(TEM,F)	38151684	A		200610		200801		200804	1	TOSHIBA	2SD2539(TEM,Q)	Integration of products	(P-D-EI)	[O-GI-NI]
38	N286	X35	QCW	2SD2553(FA,TEM,F)	38151872	A		200610		200801		200804	1	TOSHIBA	2SD2553(FA,TEM,Q	Integration of products	(P-D-EI)	[O-GI-NI]
39	N287	X35	QCW	2SD2553(LB306MA,AF	38151687	A		200610		200801		200804	1	TOSHIBA	D2553(LB306MA,A	Integration of products	(P-D-EI)	[O-GI-NI]
40	N288	X35	QCW	2SD2553(LB306MA1AF	38151916	A		200610		200801		200804	1	TOSHIBA	D2553(LB306MA1A	Integration of products	(P-D-EI)	[O-GI-NI]
41	N289	X35	QCW	2SD2553(LB324MELAF	38151688	A		200610		200801		200804	1	TOSHIBA	D2553(LB324MELA	Integration of products	(P-D-EI)	[O-GI-NI]
42	N290	X35	QCW	2SD2553(LBJVC,A,F)	38151647	A		200610		200801		200804	1	TOSHIBA	SD2553(LBJVC,A,C	Integration of products	(P-D-EI)	[O-GI-NI]
43	N291	X35	QCW	2SD2553(LBMA,A,F)	38152006	A		200610		200801		200804	1	TOSHIBA	SD2553(LBMA,A,C	Integration of products	(P-D-EI)	[O-GI-NI]
44	N292	X35	QCW	2SD2553(LBMBSK,A,F	38151732	A		200610		200801		200804	1	TOSHIBA	D2553(LBMBSK,A	Integration of products	(P-D-EI)	[O-GI-NI]
45	N293	X35	QCW	2SD2559(LBSAN,TEMF	38151689	A		200610		200801		200804	1	TOSHIBA	D2559(LBSAN,TEM	Integration of products	(P-D-EI)	[O-GI-NI]
46	N294	X35	QCW	2SD2586(LBKOTOB,AF	38151690	A		200610		200801		200804	1	TOSHIBA	D2586(LBKOTOB,A	Integration of products	(P-D-EI)	[O-GI-NI]
47	N295	X35	QCW	2SD2586(LBSHRPD,AF	38151651	A		200610		200801		200804	1	TOSHIBA	D2586(LBSHRPD,A	Integration of products	(P-D-EI)	[O-GI-NI]
48	N296	X35	QCW	2SD2586(TEM,F)	38152007	A		200610		200801		200804	1	TOSHIBA	2SD2586(TEM,Q)	Integration of products	(P-D-EI)	[O-GI-NI]
49	N297	X35	QCW	2SD2599(FA,TEM,F)	38151873	A		200610		200801		200804	1	TOSHIBA	2SD2599(FA,TEM,Q	Integration of products	(P-D-EI)	[O-GI-NI]
50	N298	X35	QCW	2SD2599(TEM,F)	38151691	A		200610		200801		200804	1	TOSHIBA	2SD2599(TEM,Q)	Integration of products	(P-D-EI)	[O-GI-NI]
51	N299	X35	QCW	2SD2638(LBKOTOB,AF	381518													

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q
86	N334	X35	QKTDE1	GT15Q311	38145030	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[O-GI-NI]
87	N335	X35	QKTDA3	GT30J311	36022370	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[O-GI-NI]
88	N336	X35	QEFCDF	KTK2312	36070248	A	200610		200801		200804	1	TOSHIBA	2SK2312(F)	Integration of products	(P-D-EI)	[O-GI-NI]
89	N337	X35	QEFCXC	KTK2662	38140079	A	200610		200801		200804	1	TOSHIBA	2SK2662(Q)	Integration of products	(P-D-EI)	[O-GI-NI]
90	N338	X35	QEFC5C	KTK2700	38140019	A	200610		200801		200804	1	TOSHIBA	2SK2700(Q)	Integration of products	(P-D-EI)	[O-GI-NI]
91	N339	X35	QELC5G	KTK2749	38140030	A	200610		200801		200804	1	TOSHIBA	2SK2749(F)	Integration of products	(P-D-EI)	[O-GI-NI]
92	N340	X35	QELC5H	KTK2611	38140031	A	200610		200801		200804	1	TOSHIBA	2SK2611(F)	Integration of products	(P-D-EI)	[O-GI-NI]
93	N341	X35	QEICDA	KTK2314	36070287	A	200610		200801		200804	1	TOSHIBA	2SK2314(F)	Integration of products	(P-D-EI)	[O-GI-NI]
94	N342	X35	QEICXC	KTK2661	36073481	A	200610		200801		200804	1	TOSHIBA	2SK2661(F)	Integration of products	(P-D-EI)	[O-GI-NI]
95	N343	X35	QEAC	2SK3565(ES)	38141121	A	200610		200801		200804	1	TOSHIBA	2SK3565(Q)	Integration of products	(P-D-EI)	[O-GI-NI]
96	N344	X35	QEFC8	2SK3742	38141772	A	200610		200801		200804	1	TOSHIBA	2SK3742(Q)	Integration of products	(P-D-EI)	[O-GI-NI]
97	N345	X35	QEFC8	2SK3742(STA4)	38141773	A	200610		200801		200804	1	TOSHIBA	2SK3742(STA4,Q)	Integration of products	(P-D-EI)	[O-GI-NI]
98	N346	X35	QEMC4D	2SK1365(MDNSI,F)	38141624	A	200610		200801		200804	1	TOSHIBA	2SK1365(F)	Integration of products	(P-D-EI)	[O-GI-NI]
99	N347	X35	QELC5J	2SK2613(MDNSI,F)	38141614	A	200610		200801		200804	1	TOSHIBA	2SK2613(F)	Integration of products	(P-D-EI)	[O-GI-NI]
100	N348	X35	QELCXB	2SK2698(MDNSI,F)	38141761	A	200610		200801		200804	1	TOSHIBA	2SK2698(F)	Integration of products	(P-D-EI)	[O-GI-NI]
101	N349	X35	QELC5C	2SK2746(DNSO,F)	38151258	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
102	N350	X35	QEMCNB	2SK2995(MDNSI,F)	38141623	A	200610		200801		200804	1	TOSHIBA	2SK2995(F)	Integration of products	(P-D-EI)	[O-GI-NI]
103	N351	X35	QELCUE	2SK789(MDNSI,F)	38141743	A	200610		200801		200804	2	TOSHIBA	2SK2698(F)	Integration of products	(P-D-EI)	[O-GI-NI]
104	N352	X35	QELCLB	2SK1529-Y(SONY,F)	38141603	A	200610		200801		200804	2	TOSHIBA	2SK1529-Y(F)	Discontinuation of Assembly Machine	(P-D-EI)	[O-GI-NI]
105	N353	X35	QEUCLD	2SK1530(MATUS)	36067221	A	200610		200801		200804	2	TOSHIBA	2SK1530(F)	Discontinuation of Assembly Machine	(P-D-EI)	[O-GI-NI]
106	N354	X35	QEUCLD	2SK1530(MATUS,F)	38141725	A	200610		200801		200804	2	TOSHIBA	2SK1530(F)	Discontinuation of Assembly Machine	(P-D-EI)	[O-GI-NI]
107	N355	X35	QELCCA	2SK1879(LBMBSH1)	36068626	A	200610		200801		200804	2	TOSHIBA	2SK2398(F)	Discontinuation of Assembly Machine	(P-D-EI)	[O-GI-NI]
108	N356	X35	QELCLC	2SJ200-Y(SONY,F)	38141604	A	200610		200801		200804	2	TOSHIBA	2SJ200-Y(F)	Discontinuation of Assembly Machine	(P-D-EI)	[O-GI-NI]
109	N357	X35	QEUCLC	2SJ201(MATUS)	36041299	A	200610		200801		200804	2	TOSHIBA	2SJ201-Y(F)	Discontinuation of Assembly Machine	(P-D-EI)	[O-GI-NI]
110	N358	X35	QEUCLC	2SJ201(MATUS,F)	38141727	A	200610		200801		200804	2	TOSHIBA	2SJ201-Y(F)	Discontinuation of Assembly Machine	(P-D-EI)	[O-GI-NI]
111	N359	X35	QEB	ES2Z21-A1S(MAT-DA)	39187014	A	200610		200801		200804	0			Integration of products	(P-D-EI)	[O-GI-NI]
112	N360	X35	QEB	ES2Z22-A1S(MAT-DA)	39187015	A	200610		200801		200804	0			Integration of products	(P-D-EI)	[O-GI-NI]
113	N361	X35	QEAE	TK15A60S(Q)	38151483	A	200610		200801		200804	3	TOSHIBA	2SK3911(Q)	Discontinuation of Assembly Machine	(P-D-EI)	[O-GI-NI]
114	N362	X35	QEAE	TK15A60S(STA4,Q)	38151484	A	200610		200801		200804	3	TOSHIBA	2SK3911(Q)	Discontinuation of Assembly Machine	(P-D-EI)	[O-GI-NI]
115	N363	X35	QHC	TA7805S	40371000	A	200610		200801		200804	1	TOSHIBA	TA7805SB	Integration of products	(P-D-EI)	[P-OU-GI]
116	N364	X35	QHC	TA78057S	40372830	A	200610		200801		200804	1	TOSHIBA	TA78057SB	Integration of products	(P-D-EI)	[P-OU-GI]
117	N365	X35	QHC	TA7806S	40371010	A	200610		200801		200804	1	TOSHIBA	TA7806SB	Integration of products	(P-D-EI)	[P-OU-GI]
118	N366	X35	QHC	TA7807S	40371115	A	200610		200801		200804	1	TOSHIBA	TA7807SB	Integration of products	(P-D-EI)	[P-OU-GI]
119	N367	X35	QHC	TA7808S	40371020	A	200610		200801		200804	1	TOSHIBA	TA7808SB	Integration of products	(P-D-EI)	[P-OU-GI]
120	N368	X35	QHC	TA7809S	40371030	A	200610		200801		200804	1	TOSHIBA	TA7809SB	Integration of products	(P-D-EI)	[P-OU-GI]
121	N369	X35	QHC	TA7810S	40371040	A	200610		200801		200804	1	TOSHIBA	TA7810SB	Integration of products	(P-D-EI)	[P-OU-GI]
122	N370	X35	QHC	TA7812S	40371050	A	200610		200801		200804	1	TOSHIBA	TA7812SB	Integration of products	(P-D-EI)	[P-OU-GI]
123	N371	X35	QHC	TA7815S	40371060	A	200610		200801		200804	1	TOSHIBA	TA7815SB	Integration of products	(P-D-EI)	[P-OU-GI]
124	N372	X35	QHC	TA7818S	40371070	A	200610		200801		200804	1	TOSHIBA	TA7818SB	Integration of products	(P-D-EI)	[P-OU-GI]
125	N373	X35	QHC	TA7820S	40371080	A	200610		200801		200804	1	TOSHIBA	TA7820SB	Integration of products	(P-D-EI)	[P-OU-GI]
126	N374	X35	QHC	TA7824S	40371090	A	200610		200801		200804	1	TOSHIBA	TA7824SB	Integration of products	(P-D-EI)	[P-OU-GI]
127	N375	X35	QHC	TA78M05S	40374825	A	200610		200801		200804	1	TOSHIBA	TA78M05SB	Integration of products	(P-D-EI)	[P-OU-GI]
128	N376	X35	QHC	TA78M06S	40374830	A	200610		200801		200804	1	TOSHIBA	TA78M06SB	Integration of products	(P-D-EI)	[P-OU-GI]
129	N377	X35	QHC	TA78M08S	40374835	A	200610		200801		200804	1	TOSHIBA	TA78M08SB	Integration of products	(P-D-EI)	[P-OU-GI]
130	N378	X35	QHC	TA78M09S	40374840	A	200610		200801		200804	1	TOSHIBA	TA78M09SB	Integration of products	(P-D-EI)	[P-OU-GI]
131	N379	X35	QHC	TA78M10S	40374845	A	200610		200801		200804	1	TOSHIBA	TA78M10SB	Integration of products	(P-D-EI)	[P-OU-GI]
132	N380	X35	QHC	TA78M12S	40374850	A	200610		200801		200804	1	TOSHIBA	TA78M12SB	Integration of products	(P-D-EI)	[P-OU-GI]
133	N381	X35	QHC	TA78M15S	40374855	A	200610		200801		200804	1	TOSHIBA	TA78M15SB	Integration of products	(P-D-EI)	[P-OU-GI]
134	N382	X35	QHC	TA78M18S	40374860	A	200610		200801		200804	1	TOSHIBA	TA78M18SB	Integration of products	(P-D-EI)	[P-OU-GI]
135	N383	X35	QHC	TA78M20S	40374865	A	200610		200801		200804	1	TOSHIBA	TA78M20SB	Integration of products	(P-D-EI)	[P-OU-GI]
136	N384	X35	QHC	TA78M24S	40374870	A	200610		200801		200804	1	TOSHIBA	TA78M24SB	Integration of products	(P-D-EI)	[P-OU-GI]
137	N385	X35	QHC	TA78DM05S	40375100	A	200610		200801		200804	2	TOSHIBA	TA58M05S	Integration of products	(P-D-EI)	[P-OU-GI]
138	N386	X35	QHC	TA78DM08S	40375105	A	200610		200801		200804	2	TOSHIBA	TA58M08S	Integration of products	(P-D-EI)	[P-OU-GI]
139	N387	X35	QHC	TA78DM09S	40375110	A	200610		200801		200804	2	TOSHIBA	TA58M09S	Integration of products	(P-D-EI)	[P-OU-GI]
140	N388	X35	QHC	TA78DM12S	40375115	A	200610		200801		200804	2	TOSHIBA	TA58M12S	Integration of products	(P-D-EI)	[P-OU-GI]
141	N389	X35	QHC	TA79005S	40374955	A	200610		200801		200804	1	TOSHIBA	TA79005SB	Integration of products	(P-D-EI)	[P-OU-GI]
142	N390	X35	QHC	TA79006S	40374965	A	200610		200801		200804	1	TOSHIBA	TA79006SB	Integration of products	(P-D-EI)	[P-OU-GI]
143	N391	X35	QHC	TA79007S	40374940	A	200610		200801		200804	1	TOSHIBA	TA79007SB	Integration of products	(P-D-EI)	[P-OU-GI]
144	N392	X35	QHC	TA79008S	40374975	A	200610		200801		200804	1	TOSHIBA	TA79008SB	Integration of products	(P-D-EI)	[P-OU-GI]
145	N393	X35	QHC	TA79009S	40374985	A	200610		200801		200804	1	TOSHIBA	TA79009SB	Integration of products	(P-D-EI)	[P-OU-GI]
146	N394	X35	QHC	TA79010S	40374995	A	200610		200801		200804	1	TOSHIBA	TA79010SB	Integration of products	(P-D-EI)	[P-OU-GI]
147	N395	X35	QHC	TA79012S	40375005	A	200610		200801		200804	1	TOSHIBA	TA79012SB	Integration of products	(P-D-EI)	[P-OU-GI]
148	N396	X35	QHC	TA79015S	40375015	A	200610		200801		200804	1	TOSHIBA	TA79015SB	Integration of products	(P-D-EI)	[P-OU-GI]
149	N397	X35	QHC	TA79018S	40375025	A	200610		200801		200804	1	TOSHIBA	TA79018SB	Integration of products	(P-D-EI)	[P-OU-GI]
150	N398	X35	QHC	TA79020S	40375035	A	200610		200801		200804	1	TOSHIBA	TA79020SB	Integration of products	(P-D-EI)	[P-OU-GI]
151	N399	X35	QHC	TA79024S	40375045	A	200610		200801		200804	1	TOSHIBA	TA79024SB	Integration of products	(P-D-EI)	[P-OU-GI]
152	N400	X35	QL7E	U05GH44	37571120	A	200610		200801		200804	3	TOSHIBA	CRF03	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
153	N401	X35	QL7E	U05JH44	37670060	A	200610		200801		200804	3	TOSHIBA	CRF03	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
154	N402	X35	QL7E	U05NH44	37670065	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
155	N403	X35	QL7E	U05TH44	37670070	A	200610		200801		200804	2	VISHAY	BYG10Y	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
156	N404	X35	QL7E	U05NU44	37670015	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
157	N405	X35	QL7E	U1GU44	37579830	A	200610		200801		200804	3	TOSHIBA	CMF01	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
158	N406	X35	QL7E	U1JU44	37579840	A	200610		200801		200804	3	TOSHIBA	CMF01	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
159	N407	X35	QL7G	U1ZB7.5	37270340	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
160	N408	X35	QL7G	U1ZB8.2	37270390	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
161	N409	X35	QL7G	U1ZB10	37270470	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
162	N410	X35	QL7G	U1ZB11	37270530	A	200610		200801		200804	3	TOSHIBA	CRZ11	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
163	N411	X35	QL7G	U1ZB12	37271835												

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q
171	N419	X35	QL1G	1ZC12	37270565	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
172	N420	X35	QL4G	1Z6.2	37270200	A	200610		200801		200804	3	TOSHIBA	CRY62	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
173	N421	X35	QL4G	1Z6.8	37270250	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
174	N422	X35	QL4G	1Z6.8A	37270260	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
175	N423	X35	QL4G	1Z7.5	37270300	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
176	N424	X35	QL4G	1Z7.5A	37270305	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
177	N425	X35	QL4G	1Z8.2	37270350	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
178	N426	X35	QL4G	1Z8.2A	37270360	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
179	N427	X35	QL4G	1Z9.1	37270400	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
180	N428	X35	QL4G	1Z9.1A	37270410	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
181	N429	X35	QL4G	1Z10	37270450	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
182	N430	X35	QL4G	1Z10A	37270451	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
183	N431	X35	QL4G	1Z11	37270500	A	200610		200801		200804	3	TOSHIBA	CRZ11	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
184	N432	X35	QL4G	1Z12	37270550	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
185	N433	X35	QL4G	1Z12A	37270580	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
186	N434	X35	QL5G	2Z12	37111110	A	200610		200801		200804	3	TOSHIBA	CMZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
187	N435	X35	QL2E	S5566B(TPA3CANO,F)	38131525	A	200610		200801		200804	1	TOSHIBA	5566B(TPA3CANO,F)	Integration of products	(P-D-EI)	[TSM-OU-GI]
188	N436	X35	QL2E	S5566J(TPA3CANO,F)	38131526	A	200610		200801		200804	1	TOSHIBA	5566J(TPA3CANO,F)	Integration of products	(P-D-EI)	[TSM-OU-GI]
189	N437	X35	QL1E	S5688B(TPA3CANO,F)	38131524	A	200610		200801		200804	1	TOSHIBA	5688B(TPA3CANO,F)	Integration of products	(P-D-EI)	[TSM-OU-GI]
190	N438	X35	QL1E	TFR8T(TPA3FUJIF,F)	38131483	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[TSM-OU-GI]
191	N439	X35	QLFJ	10FL2CZ47A(LB182,Q	38133372	A	200610		200801		200804	1	TOSHIBA	0FL2CZ47A(LB182,Q	Integration of products	(P-D-EI)	[TSM-OU-GI]
192	N440	X35	QLFE	5THZ47	37680575	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
193	N441	X35	QLFE	5TUZ47	37680596	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
194	N442	X35	QLFE	5TUZ47C	37680597	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
195	N443	X35	QLFE	5VUZ47	37680520	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
196	N444	X35	QL7E	U05GH44(Q)	38132371	A	200610		200801		200804	3	TOSHIBA	CRF03	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
197	N445	X35	QL7E	U05GH44(TE12L)	37571121	A	200610		200801		200804	3	TOSHIBA	CRF03	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
198	N446	X35	QL7E	U05GH44(TE12L,Q)	38132372	A	200610		200801		200804	3	TOSHIBA	CRF03	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
199	N447	X35	QL7E	U05GH44(TE12R)	37571122	A	200610		200801		200804	3	TOSHIBA	CRF03	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
200	N448	X35	QL7E	U05GH44(TE12R,Q)	38132373	A	200610		200801		200804	3	TOSHIBA	CRF03	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
201	N449	X35	QL7E	U05JH44(Q)	38132374	A	200610		200801		200804	3	TOSHIBA	CRF03	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
202	N450	X35	QL7E	U05JH44(TE12L)	37670061	A	200610		200801		200804	3	TOSHIBA	CRF03	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
203	N451	X35	QL7E	U05JH44(TE12L,Q)	38132375	A	200610		200801		200804	3	TOSHIBA	CRF03	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
204	N452	X35	QL7E	U05NH44(L,MITSUBA)	38131446	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
205	N453	X35	QL7E	U05NH44(LMITSUBA,Q	38132370	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
206	N454	X35	QL7E	U05NH44(Q)	38132376	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
207	N455	X35	QL7E	U05NH44(T12R,MATUD	37670069	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
208	N456	X35	QL7E	U05NH44(T2RMATUD,Q	38131709	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
209	N457	X35	QL7E	U05NH44(TE12L)	37670066	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
210	N458	X35	QL7E	U05NH44(TE12L,Q)	38132377	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
211	N459	X35	QL7E	U05NH44(TE12R)	37670068	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
212	N460	X35	QL7E	U05NH44(TE12R,Q)	38132378	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
213	N461	X35	QL7E	U05TH44(12L,CANO)	38131042	A	200610		200801		200804	2	VISHAY	BYG10Y	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
214	N462	X35	QL7E	U05TH44(2LCANO-O,Q	38131711	A	200610		200801		200804	2	VISHAY	BYG10Y	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
215	N463	X35	QL7E	U05TH44(Q)	38132379	A	200610		200801		200804	2	VISHAY	BYG10Y	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
216	N464	X35	QL7E	U05TH44(T12R,MATUD	37670036	A	200610		200801		200804	2	VISHAY	BYG10Y	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
217	N465	X35	QL7E	U05TH44(T2LCANO,Q)	38131708	A	200610		200801		200804	2	VISHAY	BYG10Y	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
218	N466	X35	QL7E	U05TH44(T2RMATUD,Q	38131710	A	200610		200801		200804	2	VISHAY	BYG10Y	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
219	N467	X35	QL7E	U05TH44(TE12L)	37670035	A	200610		200801		200804	2	VISHAY	BYG10Y	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
220	N468	X35	QL7E	U05TH44(TE12L,Q)	38132380	A	200610		200801		200804	2	VISHAY	BYG10Y	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
221	N469	X35	QL7E	U05TH44(TE12R,Q)	38132381	A	200610		200801		200804	2	VISHAY	BYG10Y	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
222	N470	X35	QL7E	U05NU44(12L,DENSO)	38133873	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
223	N471	X35	QL7E	U05NU44(12L,NANAO)	38131066	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
224	N472	X35	QL7E	U05NU44(12LNANAO,Q	38132393	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
225	N473	X35	QL7E	U05NU44(L,DSL800,Q	38135429	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
226	N474	X35	QL7E	U05NU44(L,WAKOD,Q)	38135219	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
227	N475	X35	QL7E	U05NU44(Q)	38132392	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
228	N476	X35	QL7E	U05NU44(R,MDNSI,Q)	38135013	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
229	N477	X35	QL7E	U05NU44(T2L,ORIONQ	38135396	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
230	N478	X35	QL7E	U05NU44(T2R,HIT,Q)	38133936	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
231	N479	X35	QL7E	U05NU44(TE12L)	37670016	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
232	N480	X35	QL7E	U05NU44(TE12L,PP)	38133712	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
233	N481	X35	QL7E	U05NU44(TE12L,Q)	38131715	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
234	N482	X35	QL7E	U05NU44(TE12R)	37670017	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
235	N483	X35	QL7E	U05NU44(TE12R,Q)	38132394	A	200610		200801		200804	2	VISHAY	BYG10M	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
236	N484	X35	QL7E	U1GU44(12R,NANAO)	38131067	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
237	N485	X35	QL7E	U1GU44(12R,NANAO,Q	38132383	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
238	N486	X35	QL7E	U1GU44(L,WAKOD,Q)	38135225	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
239	N487	X35	QL7E	U1GU44(Q)	38132382	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
240	N488	X35	QL7E	U1GU44(T12R,DENSO)	38133875	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
241	N489	X35	QL7E	U1GU44(T2RTORIKA,Q	38135266	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
242	N490	X35	QL7E	U1GU44(TE12L)	37579832	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
243	N491	X35	QL7E	U1GU44(TE12L,HIT)	38131058	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
244	N492	X35	QL7E	U1GU44(TE12L,HIT,Q	38132384	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
245	N493	X35	QL7E	U1GU44(TE12L,KD,Q)	38135415	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
246	N494	X35	QL7E	U1GU44(TE12L,Q)	38131712	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P	

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q
256	N504	X35	QL7E	U1JU44(R,MURATA,Q)	38135182	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
257	N505	X35	QL7E	U1JU44(T2L,KEHIN,Q	38135081	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
258	N506	X35	QL7E	U1JU44(T2L,CANO,Q)	38133465	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
259	N507	X35	QL7E	U1JU44(T2L,SBKW,Q)	38133466	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
260	N508	X35	QL7E	U1JU44(T2R,MURATA)	38135156	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
261	N509	X35	QL7E	U1JU44(T2R,PAIO,Q)	38133859	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
262	N510	X35	QL7E	U1JU44(T2R,MATUD,Q)	38131713	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
263	N511	X35	QL7E	U1JU44(TE12L)	38131202	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
264	N512	X35	QL7E	U1JU44(TE12L,Q)	38132388	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
265	N513	X35	QL7E	U1JU44(TE12L,YAZK)	38135076	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
266	N514	X35	QL7E	U1JU44(TE12R)	37579842	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
267	N515	X35	QL7E	U1JU44(TE12R,HIT)	38131062	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
268	N516	X35	QL7E	U1JU44(TE12R,HIT,Q	38132390	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
269	N517	X35	QL7E	U1JU44(TE12R,MATUD	37579843	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
270	N518	X35	QL7E	U1JU44(TE12R,PAIO)	38133858	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
271	N519	X35	QL7E	U1JU44(TE12R,Q)	38132389	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
272	N520	X35	QL7E	U1JU44(TE12R,ROM)	38133906	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
273	N521	X35	QL7E	U1JU44(TE12R,ROM,Q	38133907	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
274	N522	X35	QL7E	U1JU44(TE12R,SIND)	38131472	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
275	N523	X35	QL7E	U1JU44(TE12RSIND,Q	38132391	A	200610		200801		200804	3	TOSHIBA	CMF02	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
276	N524	X35	QL7G	U1ZB6.8(L,PULSMO,Q	38133646	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
277	N525	X35	QL7G	U1ZB6.8(L,SERCO,Q)	38135046	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
278	N526	X35	QL7G	U1ZB6.8(Q)	38135320	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
279	N527	X35	QL7G	U1ZB6.8(TE12L)	37271740	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
280	N528	X35	QL7G	U1ZB6.8(TE12L,PP)	38133688	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
281	N529	X35	QL7G	U1ZB6.8(TE12L,Q)	38133128	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
282	N530	X35	QL7G	U1ZB7.5(L,SERCO,Q)	38135047	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
283	N531	X35	QL7G	U1ZB7.5(Q)	38133129	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
284	N532	X35	QL7G	U1ZB7.5(T2RNILES,Q	38133130	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
285	N533	X35	QL7G	U1ZB7.5(TE12L)	37270341	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
286	N534	X35	QL7G	U1ZB7.5(TE12L,PP,Q	38135255	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
287	N535	X35	QL7G	U1ZB7.5(TE12L,Q)	38133131	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
288	N536	X35	QL7G	U1ZB7.5(TE12R)	37270342	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
289	N537	X35	QL7G	U1ZB7.5(TE12R,Q)	38133132	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
290	N538	X35	QL7G	U1ZB8.2(Q)	38133133	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
291	N539	X35	QL7G	U1ZB8.2(T2L,BSHA,Q	38135008	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
292	N540	X35	QL7G	U1ZB8.2(TE12L)	37270391	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
293	N541	X35	QL7G	U1ZB8.2(TE12L,Q)	38133134	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
294	N542	X35	QL7G	U1ZB8.2(TE12R)	37270392	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
295	N543	X35	QL7G	U1ZB8.2(TE12R,Q)	38133135	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
296	N544	X35	QL7G	U1ZB9.1(TE12L)	37270436	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
297	N545	X35	QL7G	U1ZB9.1(TE12L,Q)	38133136	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
298	N546	X35	QL7G	U1ZB10(Q)	38133137	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
299	N547	X35	QL7G	U1ZB10(TE12L)	37270471	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
300	N548	X35	QL7G	U1ZB10(TE12L,Q)	38133138	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
301	N549	X35	QL7G	U1ZB10(TE12R)	37270472	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
302	N550	X35	QL7G	U1ZB10(TE12R,Q)	38133139	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
303	N551	X35	QL7G	U1ZB11(Q)	38133140	A	200610		200801		200804	3	TOSHIBA	CRZ11	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
304	N552	X35	QL7G	U1ZB11(TE12L)	37270531	A	200610		200801		200804	3	TOSHIBA	CRZ11	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
305	N553	X35	QL7G	U1ZB11(TE12L,Q)	38133141	A	200610		200801		200804	3	TOSHIBA	CRZ11	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
306	N554	X35	QL7G	U1ZB11(TE12R)	37270532	A	200610		200801		200804	3	TOSHIBA	CRZ11	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
307	N555	X35	QL7G	U1ZB11(TE12R,Q)	38133142	A	200610		200801		200804	3	TOSHIBA	CRZ11	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
308	N556	X35	QL7G	U1ZB12(Q)	38133151	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
309	N557	X35	QL7G	U1ZB12(TE12L)	37271834	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
310	N558	X35	QL7G	U1ZB12(TE12L,DENSO	38133905	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
311	N559	X35	QL7G	U1ZB12(TE12L,HIT,Q	38133975	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
312	N560	X35	QL7G	U1ZB12(TE12L,ND)	37271898	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
313	N561	X35	QL7G	U1ZB12(TE12L,ND,Q)	38133153	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
314	N562	X35	QL7G	U1ZB12(TE12L,Q)	38133152	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
315	N563	X35	QL7G	U1ZB12(TE12R)	37271836	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
316	N564	X35	QL7G	U1ZB12(TE12R,HIT,Q	38133940	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
317	N565	X35	QL7G	U1ZB12(TE12R,NALD)	38131140	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
318	N566	X35	QL7G	U1ZB12(TE12R,Q)	38133154	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
319	N567	X35	QL7G	U1ZB12(TE12RNALD,Q	38133155	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
320	N568	X35	QL1G	1ZB6.8(DZF6.8-A1,Q	38132613	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
321	N569	X35	QL1G	1ZB6.8(DZF6.8-AT1)	37270289	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
322	N570	X35	QL1G	1ZB6.8(Q)	38132612	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
323	N571	X35	QL1G	1ZB6.8(TPA2)	37270292	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
324	N572	X35	QL1G	1ZB6.8(TPA2,Q)	38132614	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
325	N573	X35	QL1G	1ZB6.8(TPA3)	37270290	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
326	N574	X35	QL1G	1ZB6.8(TPA3,IKEDA)	37270293	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
327	N575	X35	QL1G	1ZB6.8(TPA3,Q)	38132615	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
328	N576	X35	QL1G	1ZB6.8(TPA3IKEDA,Q	38132616	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
329	N577	X35	QL1G	1ZB6.8(TPB5)	37270287	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
330	N578	X35	QL1G	1ZB6.8(TPB5,OKI)	37270286	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
331	N579	X35	QL1G	1ZB6.8(TPB5,OK													

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q
341	N589	X35	QL1G	1ZB7.5(TPA3,PP,Q)	38133825	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
342	N590	X35	QL1G	1ZB7.5(TPA3,Q)	38132622	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
343	N591	X35	QL1G	1ZB7.5(TPA3NANAO,Q	38132623	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
344	N592	X35	QL1G	1ZB7.5(TPB5)	38131387	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
345	N593	X35	QL1G	1ZB7.5(TPB5,MDNSI2	38131393	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
346	N594	X35	QL1G	1ZB7.5(TPB5,PP,Q)	38135389	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
347	N595	X35	QL1G	1ZB7.5(TPB5,Q)	38132624	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
348	N596	X35	QL1G	1ZB7.5A(TPA3)	37270161	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
349	N597	X35	QL1G	1ZB7.5A(TPA3,Q)	38132644	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
350	N598	X35	QL1G	1ZB8.2(IKEDA)	37270386	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
351	N599	X35	QL1G	1ZB8.2(IKEDA,Q)	38132626	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
352	N600	X35	QL1G	1ZB8.2(Q)	38132625	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
353	N601	X35	QL1G	1ZB8.2(TPA3)	37270381	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
354	N602	X35	QL1G	1ZB8.2(TPA3,FT)	38133995	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
355	N603	X35	QL1G	1ZB8.2(TPA3,Q)	38132627	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
356	N604	X35	QL1G	1ZB8.2(TPA3,SIND)	38133460	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
357	N605	X35	QL1G	1ZB8.2(TPA3,SIND,Q	38135185	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
358	N606	X35	QL1G	1ZB8.2(TPB5)	37270383	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
359	N607	X35	QL1G	1ZB8.2(TPB5,Q)	38132628	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
360	N608	X35	QL1G	1ZB9.1(Q)	38132629	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
361	N609	X35	QL1G	1ZB9.1(TPA2)	37270422	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
362	N610	X35	QL1G	1ZB9.1(TPA2,Q)	38132630	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
363	N611	X35	QL1G	1ZB9.1(TPA3)	37270424	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
364	N612	X35	QL1G	1ZB9.1(TPA3,FT)	38133996	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
365	N613	X35	QL1G	1ZB9.1(TPA3,Q)	38132631	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
366	N614	X35	QL1G	1ZB9.1(TPB5)	37270423	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
367	N615	X35	QL1G	1ZB9.1(TPB5,IKEDA)	37270426	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
368	N616	X35	QL1G	1ZB9.1(TPB5,Q)	38132632	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
369	N617	X35	QL1G	1ZB9.1(TPB5IKEDA,Q	38132633	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
370	N618	X35	QL1G	1ZB9.1A(B5,NSEIKI)	38131278	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
371	N619	X35	QL1G	1ZB9.1A(B5NSEIKI,Q	38132645	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
372	N620	X35	QL1G	1ZB9.1A(TPA3KOJP,Q	38132646	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
373	N621	X35	QL1G	1ZB10(Q)	38132634	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
374	N622	X35	QL1G	1ZB10(TPA2)	37270491	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
375	N623	X35	QL1G	1ZB10(TPA2,Q)	38132635	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
376	N624	X35	QL1G	1ZB10(TPA3)	37270492	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
377	N625	X35	QL1G	1ZB10(TPA3,Q)	38132636	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
378	N626	X35	QL1G	1ZB10(TPA3,RICOK)	37270495	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
379	N627	X35	QL1G	1ZB10(TPA3RICOK,Q	38132637	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
380	N628	X35	QL1G	1ZB10(TPB5)	37270493	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
381	N629	X35	QL1G	1ZB10(TPB5,Q)	38132638	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
382	N630	X35	QL1G	1ZB11(B5MDNSI,Q)	38131617	A	200610		200801		200804	3	TOSHIBA	CRZ11	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
383	N631	X35	QL1G	1ZB11(DZF11-AT1)	37270522	A	200610		200801		200804	3	TOSHIBA	CRZ11	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
384	N632	X35	QL1G	1ZB11(DZF11-AT1,Q)	38132640	A	200610		200801		200804	3	TOSHIBA	CRZ11	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
385	N633	X35	QL1G	1ZB11(Q)	38132639	A	200610		200801		200804	3	TOSHIBA	CRZ11	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
386	N634	X35	QL1G	1ZB11(TPA2)	37270523	A	200610		200801		200804	3	TOSHIBA	CRZ11	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
387	N635	X35	QL1G	1ZB11(TPA2,Q)	38132641	A	200610		200801		200804	3	TOSHIBA	CRZ11	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
388	N636	X35	QL1G	1ZB11(TPB5)	37270524	A	200610		200801		200804	3	TOSHIBA	CRZ11	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
389	N637	X35	QL1G	1ZB11(TPB5,Q)	38132642	A	200610		200801		200804	3	TOSHIBA	CRZ11	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
390	N638	X35	QL1G	1ZB12(IKEDA)	37270595	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
391	N639	X35	QL1G	1ZB12(IKEDA,Q)	38132659	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
392	N640	X35	QL1G	1ZB12(Q)	38132658	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
393	N641	X35	QL1G	1ZB12(TPA2)	37270593	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
394	N642	X35	QL1G	1ZB12(TPA2,IKEDA)	38131142	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
395	N643	X35	QL1G	1ZB12(TPA2,IKEDA,Q	38132661	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
396	N644	X35	QL1G	1ZB12(TPA2,Q)	38132660	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
397	N645	X35	QL1G	1ZB12(TPA3)	37270592	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
398	N646	X35	QL1G	1ZB12(TPA3,CANO)	38131021	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
399	N647	X35	QL1G	1ZB12(TPA3,Q)	38132662	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
400	N648	X35	QL1G	1ZB12(TPA3CANO,Q)	38131619	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
401	N649	X35	QL1G	1ZB12(TPB5)	37270591	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
402	N650	X35	QL1G	1ZB12(TPB5,KOJP)	37270594	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
403	N651	X35	QL1G	1ZB12(TPB5,KOJP,Q)	38132664	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
404	N652	X35	QL1G	1ZB12(TPB5,Q)	38132663	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
405	N653	X35	QL1G	1ZC12(DZF12-AT1)	37270567	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
406	N654	X35	QL1G	1ZC12(DZF12-AT1,Q)	38132518	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
407	N655	X35	QL1G	1ZC12(Q)	38132517	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
408	N656	X35	QL1G	1ZC12(TPA2)	37270569	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
409	N657	X35	QL1G	1ZC12(TPA2,Q)	38132519	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
410	N658	X35	QL1G	1ZC12(TPA3)	37270568	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
411	N659	X35	QL1G	1ZC12(TPA3,Q)	38132520	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
412	N660	X35	QL1G	1ZC12(TPB5)	37270573	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
413	N661	X35	QL1G	1ZC12(TPB5,Q)	38132521	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
414	N662	X35	QL1G	1ZC12A(TPA3)	37270572	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
415	N663	X35	QL1G	1ZC12A(TPA3,Q)	38132587	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
416	N664	X35	QL1G	1ZC12A(TPB5)	37270574	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
417	N665	X35															

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q
426	N674	X35	QL4G	1Z6.2(TPA2)	37272101	A	200610		200801		200804	3	TOSHIBA	CRY62	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
427	N675	X35	QL4G	1Z6.2(TPA2,OLP)	38131501	A	200610		200801		200804	3	TOSHIBA	CRY62	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
428	N676	X35	QL4G	1Z6.2(TPA2,OLP,Q)	38132938	A	200610		200801		200804	3	TOSHIBA	CRY62	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
429	N677	X35	QL4G	1Z6.2(TPA2,PP)	38133676	A	200610		200801		200804	3	TOSHIBA	CRY62	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
430	N678	X35	QL4G	1Z6.2(TPA2,PP,Q)	38135054	A	200610		200801		200804	3	TOSHIBA	CRY62	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
431	N679	X35	QL4G	1Z6.2(TPA2,Q)	38131738	A	200610		200801		200804	3	TOSHIBA	CRY62	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
432	N680	X35	QL4G	1Z6.2(TPA3,PP)	38133677	A	200610		200801		200804	3	TOSHIBA	CRY62	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
433	N681	X35	QL4G	1Z6.8(Q)	38132939	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
434	N682	X35	QL4G	1Z6.8(RICOK)	37270252	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
435	N683	X35	QL4G	1Z6.8(RICOK,Q)	38132940	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
436	N684	X35	QL4G	1Z6.8(TPA1)	37270254	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
437	N685	X35	QL4G	1Z6.8(TPA1,Q)	38132941	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
438	N686	X35	QL4G	1Z6.8(TPA2)	37270253	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
439	N687	X35	QL4G	1Z6.8(TPA2,Q)	38132942	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
440	N688	X35	QL4G	1Z6.8A(DZB6.8C,Q)	38132958	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
441	N689	X35	QL4G	1Z6.8A(Q)	38132957	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
442	N690	X35	QL4G	1Z6.8A,(DZB6.8C)	37270261	A	200610		200801		200804	3	TOSHIBA	CRY68	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
443	N691	X35	QL4G	1Z7.5(Q)	38132943	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
444	N692	X35	QL4G	1Z7.5(TPA2)	37270309	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
445	N693	X35	QL4G	1Z7.5(TPA2,Q)	38132944	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
446	N694	X35	QL4G	1Z7.5A(DZB7.5C,Q)	38132960	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
447	N695	X35	QL4G	1Z7.5A(Q)	38132959	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
448	N696	X35	QL4G	1Z7.5A,(DZB7.5C)	37270306	A	200610		200801		200804	3	TOSHIBA	CRY75	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
449	N697	X35	QL4G	1Z8.2(LC7)	37270353	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
450	N698	X35	QL4G	1Z8.2(LC7,Q)	38132946	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
451	N699	X35	QL4G	1Z8.2(Q)	38132945	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
452	N700	X35	QL4G	1Z8.2(TPA2)	37270354	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
453	N701	X35	QL4G	1Z8.2(TPA2,Q)	38132947	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
454	N702	X35	QL4G	1Z8.2A(LC7)	37270363	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
455	N703	X35	QL4G	1Z8.2A(LC7,Q)	38132962	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
456	N704	X35	QL4G	1Z8.2A(Q)	38132961	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
457	N705	X35	QL4G	1Z8.2A(TPA2)	37270362	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
458	N706	X35	QL4G	1Z8.2A(TPA2,Q)	38132963	A	200610		200801		200804	3	TOSHIBA	CRY82	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
459	N707	X35	QL4G	1Z9.1(Q)	38132948	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
460	N708	X35	QL4G	1Z9.1(TPA2)	38131510	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
461	N709	X35	QL4G	1Z9.1(TPA2,Q)	38132949	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
462	N710	X35	QL4G	1Z9.1A(DZB9.1C)	37270411	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
463	N711	X35	QL4G	1Z9.1A(DZB9.1C,Q)	38132965	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
464	N712	X35	QL4G	1Z9.1A(Q)	38132964	A	200610		200801		200804	3	TOSHIBA	CRY91	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
465	N713	X35	QL4G	1Z10(LC5)	37270460	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
466	N714	X35	QL4G	1Z10(LC5,Q)	38132951	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
467	N715	X35	QL4G	1Z10(LC6)	37270461	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
468	N716	X35	QL4G	1Z10(LC6,Q)	38132952	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
469	N717	X35	QL4G	1Z10(LC7)	37270455	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
470	N718	X35	QL4G	1Z10(LC7,Q)	38132953	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
471	N719	X35	QL4G	1Z10(Q)	38132950	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
472	N720	X35	QL4G	1Z10(TPA2)	37270459	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
473	N721	X35	QL4G	1Z10(TPA2,Q)	38132954	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
474	N722	X35	QL4G	1Z10A(Q)	38132966	A	200610		200801		200804	3	TOSHIBA	CRZ10	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
475	N723	X35	QL4G	1Z11(Q)	38132955	A	200610		200801		200804	3	TOSHIBA	CRZ11	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
476	N724	X35	QL4G	1Z11(TPA2)	37270503	A	200610		200801		200804	3	TOSHIBA	CRZ11	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
477	N725	X35	QL4G	1Z11(TPA2,Q)	38132956	A	200610		200801		200804	3	TOSHIBA	CRZ11	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
478	N726	X35	QL4G	1Z12(LC5)	37270556	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
479	N727	X35	QL4G	1Z12(LC5,Q)	38132976	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
480	N728	X35	QL4G	1Z12(LC7)	37270555	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
481	N729	X35	QL4G	1Z12(LC7,Q)	38132977	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
482	N730	X35	QL4G	1Z12(Q)	38132975	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
483	N731	X35	QL4G	1Z12(TPA1)	37270554	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
484	N732	X35	QL4G	1Z12(TPA1,Q)	38132978	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
485	N733	X35	QL4G	1Z12(TPA2)	37270552	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
486	N734	X35	QL4G	1Z12A(DZB12C)	37270581	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
487	N735	X35	QL4G	1Z12A(DZB12C,Q)	38133047	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
488	N736	X35	QL4G	1Z12A(Q)	38133046	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
489	N737	X35	QL4G	1Z12A(TPA2)	37270585	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
490	N738	X35	QL4G	1Z12A(TPA2,Q)	38135419	A	200610		200801		200804	3	TOSHIBA	CRZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
491	N739	X35	QL5G	2Z12(Q)	38133097	A	200610		200801		200804	3	TOSHIBA	CMZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
492	N740	X35	QL5G	2Z12(TPA2)	37111109	A	200610		200801		200804	3	TOSHIBA	CMZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
493	N741	X35	QL5G	2Z12(TPA2,Q)	38133098	A	200610		200801		200804	3	TOSHIBA	CMZ12	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
494	N742	X35	QLFE	5THZ47(F)	38133608	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
495	N743	X35	QLFE	5THZ47(Q)	38132499	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
496	N744	X35	QLFE	5TUZ47(F)	38133609	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
497	N745	X35	QLFE	5TUZ47(LB,IYAM)	37680601	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
498	N746	X35	QLFE	5TUZ47(LB,IYAM,F)	38133610	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
499	N747	X35	QLFE	5TUZ47(LB,IYAM,Q)	38132501	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
500	N748	X35	QLFE	5TUZ47(MAG)	37680602	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
501	N749	X35	QLFE	5TUZ47(MAG,F)	38133611	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
502	N750	X35	QLFE	5TUZ47(MAG,Q)	38132502	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
503	N751	X35	QLFE	5TUZ47(Q)	38132500</												

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q
511	N759	X35	QLFE	5TUZ47C(LB,IYAM,F)	38133615	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
512	N760	X35	QLFE	5TUZ47C(LB,IYAM,Q)	38132506	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
513	N761	X35	QLFE	5TUZ47C(MAT)	37680613	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
514	N762	X35	QLFE	5TUZ47C(MAT,F)	38133593	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
515	N763	X35	QLFE	5TUZ47C(MAT,Q)	38131612	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
516	N764	X35	QLFE	5TUZ47C(Q)	38132503	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
517	N765	X35	QLFE	5TUZ47C(S4HYUNDAI)	37680599	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
518	N766	X35	QLFE	5TUZ47C(S4HYUNDAIF)	38133616	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
519	N767	X35	QLFE	5TUZ47C(S4HYUNDAIQ)	38132507	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
520	N768	X35	QLFE	5VUZ47(F)	38133617	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
521	N769	X35	QLFE	5VUZ47(LB,IYAM)	37680522	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
522	N770	X35	QLFE	5VUZ47(LB,IYAM,F)	38133618	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
523	N771	X35	QLFE	5VUZ47(LB,IYAM,Q)	38132509	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
524	N772	X35	QLFE	5VUZ47(Q)	38132508	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
525	N773	X35	QFUE00	MP4501(MBS-H)	38146138	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
526	N774	X35	QFUE20	MP4504(MBS-H)	38146139	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
527	N775	X35	QFUE40	MP4507(Q)	38146134	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
528	N776	X35	QFUE40	MP4507(MBS-H)	38146140	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
529	N777	X35	QFUE40	MP4507(DNSO)	38146145	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
530	N778	X35	QFUE95	MP4514(FUJT,Q)	38146150	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
531	N779	X35	QLW	U5ZA27	37111375	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
532	N780	X35	QLW	U5ZA27(Q)	38130028	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
533	N781	X35	QLW	U5ZA27(TE24L)	37111376	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
534	N782	X35	QLW	U5ZA27(TE24L,DENSO)	38133880	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
535	N783	X35	QLW	U5ZA27(TE24L,Q)	38130029	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
536	N784	X35	QLW	U5ZA27(Z)	37111379	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
537	N785	X35	QLW	U5ZA27(Z,24L,FJTN)	38131051	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
538	N786	X35	QLW	U5ZA27(Z,24L,FJTN,Q)	38130031	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
539	N787	X35	QLW	U5ZA27(Z,Q)	38130030	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
540	N788	X35	QLW	U5ZA27(Z,T4LBSH,Q)	38130033	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
541	N789	X35	QLW	U5ZA27(Z,TE24L)	37111380	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
542	N790	X35	QLW	U5ZA27(Z,TE24L,BSH)	37111382	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
543	N791	X35	QLW	U5ZA27(Z,TE24L,Q)	38130032	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
544	N792	X35	QLW	U5ZA27(Z,TE24R)	37111381	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
545	N793	X35	QLW	U5ZA27(Z,TE24R,Q)	38130034	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
546	N794	X35	QLW	U5ZA27C	37111400	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
547	N795	X35	QLW	U5ZA27C(24L,AISIN)	38130007	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
548	N796	X35	QLW	U5ZA27C(24L,ALPINE)	38131050	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
549	N797	X35	QLW	U5ZA27C(24L,ALPSTK)	38133489	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
550	N798	X35	QLW	U5ZA27C(24L,FURUKA)	38130015	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
551	N799	X35	QLW	U5ZA27C(24L,HLS,Q)	38130057	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
552	N800	X35	QLW	U5ZA27C(24L,MATUD)	38130052	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
553	N801	X35	QLW	U5ZA27C(24L,NIKKI)	38130053	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
554	N802	X35	QLW	U5ZA27C(24L,NSEIKI)	38130076	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
555	N803	X35	QLW	U5ZA27C(24L,SUMID)	38130000	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
556	N804	X35	QLW	U5ZA27C(24L,TORIKA)	38131481	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
557	N805	X35	QLW	U5ZA27C(24L,TOYOG)	38130005	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
558	N806	X35	QLW	U5ZA27C(24L,XNV,Q)	38130058	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
559	N807	X35	QLW	U5ZA27C(24LAISIN,Q)	38130036	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
560	N808	X35	QLW	U5ZA27C(24LALPINEQ)	38130037	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
561	N809	X35	QLW	U5ZA27C(24LFURUKAQ)	38130038	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
562	N810	X35	QLW	U5ZA27C(24LSUMID,Q)	38130039	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
563	N811	X35	QLW	U5ZA27C(24LTORIKAQ)	38130040	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
564	N812	X35	QLW	U5ZA27C(24LTOYOG,Q)	38130041	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
565	N813	X35	QLW	U5ZA27C(L,DAIHAT,Q)	38130069	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
566	N814	X35	QLW	U5ZA27C(L,DAIHATU)	38133491	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
567	N815	X35	QLW	U5ZA27C(L,FURUKA,Q)	38130063	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
568	N816	X35	QLW	U5ZA27C(L,H,DENSO)	38133881	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
569	N817	X35	QLW	U5ZA27C(L,MATUD,Q)	38130068	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
570	N818	X35	QLW	U5ZA27C(L,MATUS,Q)	38130071	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
571	N819	X35	QLW	U5ZA27C(L,MITSUBA)	38133620	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
572	N820	X35	QLW	U5ZA27C(L,SHINA,Q)	38130064	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
573	N821	X35	QLW	U5ZA27C(L,SUMIS,Q)	38133909	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
574	N822	X35	QLW	U5ZA27C(L,YAZB,Q)	38130072	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
575	N823	X35	QLW	U5ZA27C(PEV)	38130055	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
576	N824	X35	QLW	U5ZA27C(Q)	38130035	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
577	N825	X35	QLW	U5ZA27C(T24L,BSH,Q)	38130046	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
578	N826	X35	QLW	U5ZA27C(T24L,DENSO)	37111405	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
579	N827	X35	QLW	U5ZA27C(T24L,DNSO2)	38130017	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
580	N828	X35	QLW	U5ZA27C(T24L,KEHIN)	38131416	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
581	N829	X35	QLW	U5ZA27C(T24L,MBS-H)	38130003	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
582	N830	X35	QLW	U5ZA27C(T24L,MOT,Q)	38130060	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
583	N831	X35	QLW	U5ZA27C(T24L,PEW,Q)	38130074	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
584	N832	X35	QLW	U5ZA27C(T24L,SUMID)	38133896	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
585	N833	X35	QLW	U5ZA27C(T4L,FJTN,Q)	38130047	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
586	N834	X35	QLW	U5ZA27C(T4L,PAIO,Q)	38130075	A	200610										

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q
596	N844	X35	QLW	U5ZA27C(TE24L,H,Q)	38130048	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
597	N845	X35	QLW	U5ZA27C(TE24L,HLS)	38133490	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
598	N846	X35	QLW	U5ZA27C(TE24L,NAL)	37111403	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
599	N847	X35	QLW	U5ZA27C(TE24L,PEV)	38130056	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
600	N848	X35	QLW	U5ZA27C(TE24L,Q)	38130018	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
601	N849	X35	QLW	U5ZA27C(TE24L,NAL,Q)	38130049	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
602	N850	X35	QLW	U5ZA27C(TE24R)	37111402	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
603	N851	X35	QLW	U5ZA27C(TE24R,Q)	38130050	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
604	N852	X35	QLW	U5ZA27L(Z,L,DNSO,Q)	38130067	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
605	N853	X35	QLW	U5ZA27L(Z,L,TOYK,Q)	38130066	A	200610		200801		200804	1	SANKEN	SZ-10N27	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
606	N854	X35	QLW	U5ZA40C(24L,DENSO)	38130014	A	200610		200801		200804	1	SANKEN	SN10N40	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
607	N855	X35	QLW	U5ZA40C(24L,MOT,Q)	38130077	A	200610		200801		200804	1	SANKEN	SN10N40	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
608	N856	X35	QLW	U5ZA40C(24L,VISTE)	38130016	A	200610		200801		200804	1	SANKEN	SN10N40	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
609	N857	X35	QLW	U5ZA40C(24LDENSO,Q)	38130019	A	200610		200801		200804	1	SANKEN	SN10N40	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
610	N858	X35	QLW	U5ZA40C(24LTORIKAQ)	38130073	A	200610		200801		200804	1	SANKEN	SN10N40	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
611	N859	X35	QLW	U5ZA40C(24LVISTE,Q)	38130020	A	200610		200801		200804	1	SANKEN	SN10N40	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
612	N860	X35	QLW	U5ZA40C(L,HINOJ,Q)	38130065	A	200610		200801		200804	1	SANKEN	SN10N40	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
613	N861	X35	QLW	U5ZA40C(R,CLAR,Q)	38130062	A	200610		200801		200804	1	SANKEN	SN10N40	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
614	N862	X35	QLW	U5ZA40C(T4L,HITJ,Q)	38130022	A	200610		200801		200804	1	SANKEN	SN10N40	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
615	N863	X35	QLW	U5ZA40C(T4L,HKM,Q)	38130061	A	200610		200801		200804	1	SANKEN	SN10N40	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
616	N864	X35	QLW	U5ZA40C(T4L,JIDO,Q)	38130023	A	200610		200801		200804	1	SANKEN	SN10N40	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
617	N865	X35	QLW	U5ZA40C(TE24L)	38130009	A	200610		200801		200804	1	SANKEN	SN10N40	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
618	N866	X35	QLW	U5ZA40C(TE24L,HITJ)	38130013	A	200610		200801		200804	1	SANKEN	SN10N40	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
619	N867	X35	QLW	U5ZA40C(TE24L,JIDO)	38131498	A	200610		200801		200804	1	SANKEN	SN10N40	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
620	N868	X35	QLW	U5ZA40C(TE24L,Q)	38130021	A	200610		200801		200804	1	SANKEN	SN10N40	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
621	N869	X35	QLW	U5ZA48C(24L,DENSO)	38130011	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
622	N870	X35	QLW	U5ZA48C(24L,MOT,Q)	38130078	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
623	N871	X35	QLW	U5ZA48C(24L,NIKKI)	38133828	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
624	N872	X35	QLW	U5ZA48C(24LDENSO,Q)	38130024	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
625	N873	X35	QLW	U5ZA48C(L,AISIN,Q)	38130054	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
626	N874	X35	QLW	U5ZA48C(L,FTBDK,Q)	38130059	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
627	N875	X35	QLW	U5ZA48C(TE24L)	38130010	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
628	N876	X35	QLW	U5ZA48C(TE24L,Q)	38130025	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
629	N877	X35	QLW	U5ZA53C(L,AISIN,Q)	38130070	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
630	N878	X35	QLW	U5ZA53C(L,MATUD,Q)	38130079	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
631	N879	X35	QLW	U5ZA53C(TE24L)	38131334	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
632	N880	X35	QLW	U5ZA53C(TE24L,Q)	38130026	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
633	N881	X35	QLW	U5ZA53C(TE24R)	38131335	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
634	N882	X35	QLW	U5ZA53C(TE24R,Q)	38130027	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
635	N883	X35	QAD	2SD880-Y(MURATA2)	38151332	A	200610		200801		200804	2	TOSHIBA	2SD2012	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
636	N884	X35	QAE	2SD1415(LB,MBS-H4)	36868462	A	200610		200801		200804	2	TOSHIBA	2SD1415A	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
637	N885	X35	QAE	2SD1415(LB,MBS-H2)	38151531	A	200610		200801		200804	2	TOSHIBA	2SD1415A	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
638	N886	X35	QAE	2SB1017-Y(LBMBS-H3)	38151805	A	200610		200801		200804	2	TOSHIBA	2SB1642	Discontinuation of Assembly Machine	(P-D-EI)	[TSM-OU-GI]
639	N887	X35	QAU	2SD2384(LBKENW1)	36873136	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
640	N888	X35	QAU	2SD2384(LBKENW2)	36873137	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
641	N889	X35	QAU	2SD2384-A	36873130	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
642	N890	X35	QAU	2SD2384-A(F)	38150034	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
643	N891	X35	QAU	2SD2384-B	36873131	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
644	N892	X35	QAU	2SD2384-C	36873132	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
645	N893	X35	QAL	2SD2386-A1	38152134	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
646	N894	X35	QAL	2SD2386-A1(F)	38152128	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
647	N895	X35	QAL	2SD2386-O(ONK)	36873174	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
648	N896	X35	QAL	2SD2386-R(ONK)	36873173	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
649	N897	X35	QAU	2SD2385(KENW1)	36873157	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
650	N898	X35	QAU	2SD2385(KENW2)	36873158	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
651	N899	X35	QAU	2SD2385-B	38151758	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
652	N900	X35	QAL	2SD2387-B1	38152136	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
653	N901	X35	QAL	2SD2387-O(ONK)	36873194	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
654	N902	X35	QAL	2SD2387-R(ONK)	36873193	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
655	N903	X35	QAU	2SD2449	38151153	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
656	N904	X35	QAU	2SD2449(LBKENW3)	36873298	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
657	N905	X35	QAU	2SD2449(LBKENW4)	36873299	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
658	N906	X35	QAU	2SB1555(LBKENW1)	36640267	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
659	N907	X35	QAU	2SB1555(LBKENW2)	36640268	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
660	N908	X35	QAU	2SB1555-A	36640261	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
661	N909	X35	QAU	2SB1555-B	36640262	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
662	N910	X35	QAL	2SB1557-A1	38152131	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
663	N911	X35	QAL	2SB1557-O(ONK)	36640305	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
664	N912	X35	QAL	2SB1557-R(ONK)	36640304	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
665	N913	X35	QAU	2SB1556(KENW1)	36640287	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
666	N914	X35	QAU	2SB1556(KENW1,F)	38150016	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
667	N915	X35	QAU	2SB1556(KENW2)	36640288	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
668	N916	X35	QAU	2SB1556-A	36640280	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
669	N917	X35	QAU	2SB1556-B	36640281	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
670	N918	X35	QAU	2SB1556-C	36640282	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
671	N919	X35	QAL	2SB1558-A1	38152130	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
672	N920	X35	QAL	2SB1558-B1	38152137	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
673	N921	X35	QAL	2SB1558-B1(F)	38152125	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[O-GI-NI]
674	N922	X35	QAL	2SB1558-O(ONK)	36640325	A											

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q
681	N929	X35	QAJ	2SC4754	36369275	A	200610		200801		200804	3	TOSHIBA	2SC5548A	Integration of products	(P-D-EI)	[O-GI-NI]
682	N930	X35	QAJ	2SC4754(Q)	38141344	A	200610		200801		200804	3	TOSHIBA	2SC5548A	Integration of products	(P-D-EI)	[O-GI-NI]
683	N931	X35	QA5	2SC5075(TP)	36370351	A	200610		200801		200804	1	TOSHIBA	2SC5075(TP,Q)	Integration of products	(P-D-EI)	[O-GI-NI]
684	N932	X35	QA5	2SC5075(TPMATUD)	36370352	A	200610		200801		200804	1	TOSHIBA	2SC5075(TPMATUD)	Integration of products	(P-D-EI)	[O-GI-NI]
685	N933	X35	QA2	2SC5279(TP)	26372511	A	200610		200801		200804	3	TOSHIBA	2SC5548A	Integration of products	(P-D-EI)	[O-GI-NI]
686	N934	X35	QA2	2SC5279(TPSANYD)	38141183	A	200610		200801		200804	3	TOSHIBA	2SC5548A	Integration of products	(P-D-EI)	[O-GI-NI]
687	N935	X35	QA2	2SC5279(TPSANYD,Q)	38141958	A	200610		200801		200804	3	TOSHIBA	2SC5548A	Integration of products	(P-D-EI)	[O-GI-NI]
688	N936	X35	QA2	2SC5279(TP,Q)	38142934	A	200610		200801		200804	3	TOSHIBA	2SC5548A	Integration of products	(P-D-EI)	[O-GI-NI]
689	N937	X35	QAL	2SC3657	36363500	A	200610		200801		200804	1	TOSHIBA	2SC5354	Integration of products	(P-D-EI)	[O-GI-NI]
690	N938	X35	QAL	2SC3657(NKEM)	36363502	A	200610		200801		200804	1	TOSHIBA	2SC5354	Integration of products	(P-D-EI)	[O-GI-NI]
691	N939	X35	QAL	2SC3657(N-JRC)	36363503	A	200610		200801		200804	1	TOSHIBA	2SC5354	Integration of products	(P-D-EI)	[O-GI-NI]
692	N940	X35	QAL	2SC3657(ORIG)	36363504	A	200610		200801		200804	1	TOSHIBA	2SC5354	Integration of products	(P-D-EI)	[O-GI-NI]
693	N941	X35	QAL	2SC3657(F)	38150134	A	200610		200801		200804	1	TOSHIBA	2SC5354	Integration of products	(P-D-EI)	[O-GI-NI]
694	N942	X35	QAL	2SC4157	36365750	A	200610		200801		200804	2	TOSHIBA	2SC5352	Integration of products	(P-D-EI)	[O-GI-NI]
695	N943	X35	QAL	2SC4157(F)	38150135	A	200610		200801		200804	2	TOSHIBA	2SC5352	Integration of products	(P-D-EI)	[O-GI-NI]
696	N944	X35	QAP	2SC2880-Q(Te12L,C)	36342319	A	200610		200801		200804	2	TOSHIBA	2SC2881	Integration of products	(P-D-EI)	[O-GI-NI]
697	N945	X35	QAP	2SC2880-Y(C)	36342328	A	200610		200801		200804	2	TOSHIBA	2SC2881	Integration of products	(P-D-EI)	[O-GI-NI]
698	N946	X35	QAP	2SC2880-Y(Te12L,C)	36342329	A	200610		200801		200804	2	TOSHIBA	2SC2881	Integration of products	(P-D-EI)	[O-GI-NI]
699	N947	X35	QAP	2SC2880-Y(Te12R,C)	36342330	A	200610		200801		200804	2	TOSHIBA	2SC2881	Integration of products	(P-D-EI)	[O-GI-NI]
700	N948	X35	QAP	2SC2880-Y(Te12L,CF)	38142558	A	200610		200801		200804	2	TOSHIBA	2SC2881	Integration of products	(P-D-EI)	[O-GI-NI]
701	N949	X35	QAP	2SC2880-Q(T2LSONYF)	38151440	A	200610		200801		200804	2	TOSHIBA	2SC2881	Integration of products	(P-D-EI)	[O-GI-NI]
702	N950	X35	QAP	2SA1200-Y(C)	36543074	A	200610		200801		200804	2	TOSHIBA	2SA1201	Integration of products	(P-D-EI)	[O-GI-NI]
703	N951	X35	QAP	2SA1200-Y(Te12L,C)	36543075	A	200610		200801		200804	2	TOSHIBA	2SA1201	Integration of products	(P-D-EI)	[O-GI-NI]
704	N952	X35	QAP	2SA1200-Y(Te12R,C)	36543076	A	200610		200801		200804	2	TOSHIBA	2SA1201	Integration of products	(P-D-EI)	[O-GI-NI]
705	N953	X35	QAP	2SA1200-Y(Te12L,CF)	38150572	A	200610		200801		200804	2	TOSHIBA	2SA1201	Integration of products	(P-D-EI)	[O-GI-NI]
706	N954	X35	QLLJ	20DL2C41A	37681175	A	200610		200801		200804	2	TOSHIBA	20DL2C41A-1	Integration of products	(P-D-EI)	[O-GI-NI]
707	N955	X35	QAP	2SC4539(Te12L)	36368501	A	200610		200801		200804	2	TOSHIBA	2SC5810	Integration of products	(P-D-EI)	[O-GI-NI]
708	N956	X35	QAP	2SC4539(Te12L,F)	38142588	A	200610		200801		200804	2	TOSHIBA	2SC5810	Integration of products	(P-D-EI)	[O-GI-NI]
709	N957	X35	QAP	2SC4539(T2LPP,F)	38151992	A	200610		200801		200804	2	TOSHIBA	2SC5810	Integration of products	(P-D-EI)	[O-GI-NI]
710	N958	X35	QAL	2SD1662	36871500	A	200610		200801		200804	1	TOSHIBA	2SD1662-1	Integration of products	(P-D-EI)	[O-GI-NI]
711	N959	X35	QAL	2SD1662(F)	38150151	A	200610		200801		200804	1	TOSHIBA	2SD1662-1(F)	Integration of products	(P-D-EI)	[O-GI-NI]
712	N960	X35	QWR	TSA3100J(D)	38147233	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
713	N961	X35	QA3	2SA1357-O(H)	H1050017	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
714	N962	X35	QA3	2SA1357-O(Q,H)	H1050033	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
715	N963	X35	QA3	2SA1357-Y(H)	H1050006	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
716	N964	X35	QA3	2SA1357-Y(Q,H)	H1050034	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
717	N965	X35	QA3	2SA1358-O(H)	H1050018	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
718	N966	X35	QA3	2SA1358-O(Q,H)	H1050037	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
719	N967	X35	QA3	2SA1358-Y(H)	H1050009	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
720	N968	X35	QA3	2SA1358-Y(Q,H)	H1050038	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
721	N969	X35	QA3	2SA1359-O(H)	H1050019	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
722	N970	X35	QA3	2SA1359-O(Q,H)	H1050041	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
723	N971	X35	QA3	2SA1359-Y(H)	H1050011	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
724	N972	X35	QA3	2SA1359-Y(Q,H)	H1050042	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
725	N973	X35	QA3	2SA1360-O(H)	H1050004	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
726	N974	X35	QA3	2SA1360-O(Q,H)	H1050031	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
727	N975	X35	QA3	2SA1360-Y(H)	H1050020	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
728	N976	X35	QA3	2SA1360-Y(Q,H)	H1050032	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
729	N977	X35	QA3	2SB1067(CANO,Q,H)	H1050050	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
730	N978	X35	QA3	2SB1067(H)	H1050012	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
731	N979	X35	QA3	2SB1067(Q,H)	H1050046	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
732	N980	X35	QA3	2SC3420-BL(H)	H1050002	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
733	N981	X35	QA3	2SC3420-BL(Q,H)	H1050026	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
734	N982	X35	QA3	2SC3420-GR(H)	H1050001	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
735	N983	X35	QA3	2SC3420-GR(Q,H)	H1050027	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
736	N984	X35	QA3	2SC3420-Y(H)	H1050021	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
737	N985	X35	QA3	2SC3420-Y(Q,H)	H1050028	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
738	N986	X35	QA3	2SC3421-O(H)	H1050007	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
739	N987	X35	QA3	2SC3421-O(Q,H)	H1050035	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
740	N988	X35	QA3	2SC3421-Y(H)	H1050008	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
741	N989	X35	QA3	2SC3421-Y(Q,H)	H1050036	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
742	N990	X35	QA3	2SC3422-O(H)	H1050022	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
743	N991	X35	QA3	2SC3422-O(Q,H)	H1050039	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
744	N992	X35	QA3	2SC3422-Y(H)	H1050010	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
745	N993	X35	QA3	2SC3422-Y(Q,H)	H1050040	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
746	N994	X35	QA3	2SC3423-O(H)	H1050003	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
747	N995	X35	QA3	2SC3423-O(Q,H)	H1050029	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
748	N996	X35	QA3	2SC3423-Y(H)	H1050023	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
749	N997	X35	QA3	2SC3423-Y(Q,H)	H1050030	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
750	N998	X35	QA3	2SC3425(H)	H1050024	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
751	N999	X35	QA3	2SC3425(Q,H)	H1050048	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
752	N1000	X35	QA3	2SC3619(H)	H1050013	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
753	N1001	X35	QA3	2SC3619(Q,H)	H1050047	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
754	N1002	X35	QA3	2SC3621-O(H)	H1050005	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
755	N1003	X35	QA3	2SC5368(H)	H1050014	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
756	N1004	X35	QA3	2SC5368(Q,H)	H1050049	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
757	N1005	X35	QA3	S2Y51(SEP,H)	H1050015	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
758	N1006	X35	QA3	S2Y51(SEP,Q,H)	H1050043	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
759	N1007	X35	QA3	S2Y52(FUNAI,H)	H1050025	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
760	N1008	X35	QA3	S2Y52(FUNAI,Q,H)	H1050044	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-G

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q
766	N1014	X35	QE1AGD	TPC8203(T2LIBM1Q,M	M1TO0121	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
767	N1015	X35	QE1AGD	TPC8203(T2LIBM2,M)	M1TO0171	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
768	N1016	X35	QE1AGD	TPC8203(T2LIBM2Q,M	M1TO0172	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
769	N1017	X35	QE1AGD	TPC8203(TE12L,M)	M1TO0052	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
770	N1018	X35	QE1AGD	TPC8203(TE12L,Q,M)	M1TO0053	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
771	N1019	X35	QE1AGE	TPC8303(SCTE12L,M)	M1TO0147	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
772	N1020	X35	QE1AGE	TPC8303(TE12L,M)	M1TO0070	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
773	N1021	X35	QE1AGE	TPC8303(TE12L,Q,M)	M1TO0056	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
774	N1022	X35	QE1AGK	TPC8105-H(TE12L,M)	M1TO0076	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
775	N1023	X35	QE1AGK	TPC8105-H(TE12LQ,M	M1TO0063	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
776	N1024	X35	QE1AGM	TPC8104-H(T2LCANQM	M1TO0154	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
777	N1025	X35	QE1AGM	TPC8104-H(TE12L,M)	M1TO0075	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
778	N1026	X35	QE1AGM	TPC8104-H(TE12LQ,M	M1TO0062	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
779	N1027	X35	QE1AGN	TPC8401(TE12L,M)	M1TO0019	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
780	N1028	X35	QE1AGN	TPC8401(TE12L,Q,M)	M1TO0017	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
781	N1029	X35	QE1AGR	TPC8003(TE12L,M)	M1TO0116	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
782	N1030	X35	QE1AGR	TPC8003(TE12L,Q,M)	M1TO0058	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
783	N1031	X35	QE1AGT	TPC8305(TE12L,M)	M1TO0071	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
784	N1032	X35	QE1AGT	TPC8305(TE12L,Q,M)	M1TO0057	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
785	N1033	X35	QE1AGU	TPC8403(TE12L,M)	M1TO0030	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
786	N1034	X35	QE1AGU	TPC8403(TE12L,Q,M)	M1TO0032	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
787	N1035	X35	QE1AGV	TPC8402(T2LCANO,M)	M1TO0148	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
788	N1036	X35	QE1AGV	TPC8402(TE12L,M)	M1TO0029	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
789	N1037	X35	QE1AGV	TPC8402(TE12L,Q,M)	M1TO0031	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
790	N1038	X35	QE1AH	TPC8206(TE12L,M)	M1TO0079	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
791	N1039	X35	QE1AHA	TPC8009-H(T2LOM1QM	M1TO0001	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
792	N1040	X35	QE1AHA	TPC8009-H(T2LOME1M	M1TO0023	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
793	N1041	X35	QE1AHA	TPC8009-H(TE12L,M)	M1TO0013	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
794	N1042	X35	QE1AHA	TPC8009-H(TE12LQ,M	M1TO0020	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
795	N1043	X35	QE1AHB	TPC8013-H(TE12L,M)	M1TO0072	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
796	N1044	X35	QE1AHB	TPC8013-H(TE12LQ,M	M1TO0059	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
797	N1045	X35	QE1BHB	TPC8010-H(T2IBM2M)	M1TO0173	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
798	N1046	X35	QE1BHB	TPC8010-H(T2IBM2QM	M1TO0174	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
799	N1047	X35	QE1BHB	TPC8010-H(T2LIB1QM	M1TO0143	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
800	N1048	X35	QE1BHB	TPC8010-H(T2LIBM1M	M1TO0142	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
801	N1049	X35	QE1BHB	TPC8010-H(T2LOM1QM	M1TO0002	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
802	N1050	X35	QE1BHB	TPC8010-H(T2LOME1M	M1TO0024	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
803	N1051	X35	QE1BHB	TPC8010-H(TE12L,M)	M1TO0014	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
804	N1052	X35	QE1BHB	TPC8010-H(TE12LQ,M	M1TO0021	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
805	N1053	X35	QE1Z9B	TPC8108(TE12L,M)	M1TO0018	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
806	N1054	X35	QE1Z9B	TPC8108(TE12L,Q,M)	M1TO0016	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
807	N1055	X35	QE3AGO	TPCS8102(TE12L,M)	M1TU0025	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
808	N1056	X35	QE3AGO	TPCS8102(TE12L,Q,M	M1TU0026	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
809	N1057	X35	QEVCSBA	2SK940(TE6,M)	M1TS0018	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
810	N1058	X35	QEVCSBB	2SK941(F,M)	M1TS0022	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
811	N1059	X35	QEVCSBB	2SK941(TE6,F,M)	M1TS0007	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
812	N1060	X35	QEVCSBB	2SK941(TE6,M)	M1TS0013	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
813	N1061	X35	QHC	TA78033LS(M)	M1TK0055	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
814	N1062	X35	QHC	TA78033LS(Q,M)	M1TK0065	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
815	N1063	X35	QHC	TA78033LS(SONY,M)	M1TK0061	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
816	N1064	X35	QHC	TA78033LS(SONY,Q,M	M1TK0071	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
817	N1065	X35	QHC	TA7804LS(M)	M1TK0056	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
818	N1066	X35	QHC	TA7804LS(Q,M)	M1TK0066	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
819	N1067	X35	QHC	TA7804LS(SONY,M)	M1TK0062	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
820	N1068	X35	QHC	TA7804LS(SONY,Q,M)	M1TK0072	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
821	N1069	X35	QHC	TA78057S(M)	M1TK0002	A	200610		200801		200804	0			Integration of products	(P-D-EI)	[P-OU-GI]
822	N1070	X35	QHC	TA78057S(Q,M)	M1TK0033	A	200610		200801		200804	0			Integration of products	(P-D-EI)	[P-OU-GI]
823	N1071	X35	QHC	TA7805LS(M)	M1TK0057	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
824	N1072	X35	QHC	TA7805LS(Q,M)	M1TK0067	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
825	N1073	X35	QHC	TA7805LS(SONY,M)	M1TK0063	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
826	N1074	X35	QHC	TA7805LS(SONY,Q,M)	M1TK0073	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
827	N1075	X35	QHC	TA7805S(LBSONY,M)	M1TK0040	A	200610		200801		200804	1	TOSHIBA	TA7805SB	Integration of products	(P-D-EI)	[P-OU-GI]
828	N1076	X35	QHC	TA7805S(LBSONY,Q,M	M1TK0042	A	200610		200801		200804	1	TOSHIBA	TA7805SB	Integration of products	(P-D-EI)	[P-OU-GI]
829	N1077	X35	QHC	TA7805S(M)	M1TK0001	A	200610		200801		200804	1	TOSHIBA	TA7805SB	Integration of products	(P-D-EI)	[P-OU-GI]
830	N1078	X35	QHC	TA7805S(Q,M)	M1TK0023	A	200610		200801		200804	1	TOSHIBA	TA7805SB	Integration of products	(P-D-EI)	[P-OU-GI]
831	N1079	X35	QHC	TA7805S(SONY,Q,M)	M1TK0110	A	200610		200801		200804	1	TOSHIBA	TA7805SB	Integration of products	(P-D-EI)	[P-OU-GI]
832	N1080	X35	QHC	TA7807S(LBSONY,M)	M1TK0041	A	200610		200801		200804	1	TOSHIBA	TA7807SB	Integration of products	(P-D-EI)	[P-OU-GI]
833	N1081	X35	QHC	TA7807S(LBSONY,Q,M	M1TK0043	A	200610		200801		200804	1	TOSHIBA	TA7807SB	Integration of products	(P-D-EI)	[P-OU-GI]
834	N1082	X35	QHC	TA7807S(M)	M1TK0003	A	200610		200801		200804	1	TOSHIBA	TA7807SB	Integration of products	(P-D-EI)	[P-OU-GI]
835	N1083	X35	QHC	TA7807S(Q,M)	M1TK0024	A	200610		200801		200804	1	TOSHIBA	TA7807SB	Integration of products	(P-D-EI)	[P-OU-GI]
836	N1084	X35	QHC	TA7808S(M)	M1TK0004	A	200610		200801		200804	1	TOSHIBA	TA7808SB	Integration of products	(P-D-EI)	[P-OU-GI]
837	N1085	X35	QHC	TA7808S(Q,M)	M1TK0031	A	200610		200801		200804	1	TOSHIBA	TA7808SB	Integration of products	(P-D-EI)	[P-OU-GI]
838	N1086	X35	QHC	TA7809LS(M)	M1TK0058	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
839	N1087	X35	QHC	TA7809LS(Q,M)	M1TK0068	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
840	N1088	X35	QHC	TA7809LS(SONY,M)	M1TK0064	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
841	N1089	X35	QHC	TA7809LS(SONY,Q,M)	M1TK0074	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
842	N1090	X35	QHC	TA7809S(M)	M1TK0005	A	200610		200801		200804	1	TOSHIBA	TA7809SB	Integration of products	(P-D-EI)	[P-OU-GI]
843	N1091	X35	QHC	TA7809S(Q,M)	M1TK0026	A	200610		200801		200804	1	TOSHIBA	TA7809SB	Integration of products	(P-D-EI)	[P-OU-GI]
844	N1092	X35	QHC	TA7809S(SONY,Q,M)	M1TK0111	A	200610		200801		200804	1	TOSHIBA	TA7809SB	Integration of products	(P-D-EI)	[P-

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q
851	N1099	X35	QHC	TA78M08S(M)	M1TK0092	A	200610		200801		200804	1	TOSHIBA	TA78M08SB	Integration of products	(P-D-EI)	[P-OU-GI]
852	N1100	X35	QHC	TA78M08S(Q,M)	M1TK0089	A	200610		200801		200804	1	TOSHIBA	TA78M08SB	Integration of products	(P-D-EI)	[P-OU-GI]
853	N1101	X35	QHC	TA78M09S(M)	M1TK0060	A	200610		200801		200804	1	TOSHIBA	TA78M09SB	Integration of products	(P-D-EI)	[P-OU-GI]
854	N1102	X35	QHC	TA78M09S(Q,M)	M1TK0070	A	200610		200801		200804	1	TOSHIBA	TA78M09SB	Integration of products	(P-D-EI)	[P-OU-GI]
855	N1103	X35	QHC	TA78M12S(M)	M1TK0008	A	200610		200801		200804	1	TOSHIBA	TA78M12SB	Integration of products	(P-D-EI)	[P-OU-GI]
856	N1104	X35	QHC	TA78M12S(Q,M)	M1TK0027	A	200610		200801		200804	1	TOSHIBA	TA78M12SB	Integration of products	(P-D-EI)	[P-OU-GI]
857	N1105	X35	QHC	TA79005S(M)	M1TK0009	A	200610		200801		200804	1	TOSHIBA	TA79005SB	Integration of products	(P-D-EI)	[P-OU-GI]
858	N1106	X35	QHC	TA79005S(Q,M)	M1TK0028	A	200610		200801		200804	1	TOSHIBA	TA79005SB	Integration of products	(P-D-EI)	[P-OU-GI]
859	N1107	X35	QHC	TA79006S(M)	M1TK0100	A	200610		200801		200804	1	TOSHIBA	TA79006SB	Integration of products	(P-D-EI)	[P-OU-GI]
860	N1108	X35	QHC	TA79006S(Q,M)	M1TK0101	A	200610		200801		200804	1	TOSHIBA	TA79006SB	Integration of products	(P-D-EI)	[P-OU-GI]
861	N1109	X35	QHC	TA79007S(M)	M1TK0085	A	200610		200801		200804	1	TOSHIBA	TA79007SB	Integration of products	(P-D-EI)	[P-OU-GI]
862	N1110	X35	QHC	TA79007S(Q,M)	M1TK0081	A	200610		200801		200804	1	TOSHIBA	TA79007SB	Integration of products	(P-D-EI)	[P-OU-GI]
863	N1111	X35	QHC	TA79008S(M)	M1TK0102	A	200610		200801		200804	1	TOSHIBA	TA79008SB	Integration of products	(P-D-EI)	[P-OU-GI]
864	N1112	X35	QHC	TA79008S(Q,M)	M1TK0103	A	200610		200801		200804	1	TOSHIBA	TA79008SB	Integration of products	(P-D-EI)	[P-OU-GI]
865	N1113	X35	QHC	TA79009S(M)	M1TK0091	A	200610		200801		200804	1	TOSHIBA	TA79009SB	Integration of products	(P-D-EI)	[P-OU-GI]
866	N1114	X35	QHC	TA79009S(Q,M)	M1TK0090	A	200610		200801		200804	1	TOSHIBA	TA79009SB	Integration of products	(P-D-EI)	[P-OU-GI]
867	N1115	X35	QHC	TA79010S(M)	M1TK0086	A	200610		200801		200804	1	TOSHIBA	TA79010SB	Integration of products	(P-D-EI)	[P-OU-GI]
868	N1116	X35	QHC	TA79010S(Q,M)	M1TK0082	A	200610		200801		200804	1	TOSHIBA	TA79010SB	Integration of products	(P-D-EI)	[P-OU-GI]
869	N1117	X35	QHC	TA79012S(M)	M1TK0010	A	200610		200801		200804	1	TOSHIBA	TA79012SB	Integration of products	(P-D-EI)	[P-OU-GI]
870	N1118	X35	QHC	TA79012S(Q,M)	M1TK0029	A	200610		200801		200804	1	TOSHIBA	TA79012SB	Integration of products	(P-D-EI)	[P-OU-GI]
871	N1119	X35	QHC	TA79015S(M)	M1TK0011	A	200610		200801		200804	1	TOSHIBA	TA79015SB	Integration of products	(P-D-EI)	[P-OU-GI]
872	N1120	X35	QHC	TA79015S(Q,M)	M1TK0030	A	200610		200801		200804	1	TOSHIBA	TA79015SB	Integration of products	(P-D-EI)	[P-OU-GI]
873	N1121	X35	QHC	TA79018S(M)	M1TK0104	A	200610		200801		200804	1	TOSHIBA	TA79018SB	Integration of products	(P-D-EI)	[P-OU-GI]
874	N1122	X35	QHC	TA79018S(Q,M)	M1TK0105	A	200610		200801		200804	1	TOSHIBA	TA79018SB	Integration of products	(P-D-EI)	[P-OU-GI]
875	N1123	X35	QHC	TA79020S(M)	M1TK0106	A	200610		200801		200804	1	TOSHIBA	TA79020SB	Integration of products	(P-D-EI)	[P-OU-GI]
876	N1124	X35	QHC	TA79020S(Q,M)	M1TK0107	A	200610		200801		200804	1	TOSHIBA	TA79020SB	Integration of products	(P-D-EI)	[P-OU-GI]
877	N1125	X35	QHC	TA79024S(M)	M1TK0108	A	200610		200801		200804	1	TOSHIBA	TA79024SB	Integration of products	(P-D-EI)	[P-OU-GI]
878	N1126	X35	QHC	TA79024S(Q,M)	M1TK0109	A	200610		200801		200804	1	TOSHIBA	TA79024SB	Integration of products	(P-D-EI)	[P-OU-GI]
879	N1127	X35	QHV	TA76431AS(F,M)	M1TR0010	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
880	N1128	X35	QHV	TA76431AS(M)	M1TR0008	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
881	N1129	X35	QAC	2SA1837(T)	T1000671	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
882	N1130	X35	QAC	2SC4544(T)	T1000673	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
883	N1131	X35	QAC	2SC4793(T)	T1000674	A	200610		200801		200804	0			Discontinuation of Assembly Machine	(P-D-EI)	[P-OU-GI]
884	N1132	X35	QE2C	TPCA8006-H(T2LCOSQ	38152072	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[P-OU-GI]
885	N1133	X35	QEKAH	2SK3864(SM,Q)	38150670	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[P-OU-GI]
886	N1134	X35	QEKAH	2SK3864(T4LPAIO,Q)	38150703	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[P-OU-GI]
887	N1135	X35	QEKAH	2SK3864(TE24L,Q)	38150671	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[P-OU-GI]
888	N1136	X35	QEAC	2SK3937(Q)	38151534	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[P-OU-GI]
889	N1137	X35	QEAC	2SK3937(STA4,Q)	38151535	A	200610		200801		200804	0			No Order Forecast	(P-D-EI)	[P-OU-GI]