

OFFICIAL ANNOUNCEMENT
- Discontinuation Note -

TOSHIBA

Please find the **official announcement** that TOSHIBA, in line with previous information, will stop all promotion and sales activities for the following products:

Related products:

Product Group	Toshiba Partnumber	recommended replacement item	Reason
TOSLINK	TORX147(F,T)	no replacement	damaged by Thai flood
TOSLINK	TORX147BPL(F,T)	no replacement	damaged by Thai flood
TOSLINK	TORX147L(F,T)	no replacement	damaged by Thai flood
TOSLINK	TORX147PL(F,T)	no replacement	damaged by Thai flood
TOSLINK	TORX177(F,T)	no replacement	damaged by Thai flood
TOSLINK	TORX177L(F,T)	no replacement	damaged by Thai flood
TOSLINK	TORX177PL(F,T)	no replacement	damaged by Thai flood
TOSLINK	TOTX147(F,T)	no replacement	damaged by Thai flood
TOSLINK	TOTX147A(F,T)	no replacement	damaged by Thai flood
TOSLINK	TOTX147AL(F,T)	no replacement	damaged by Thai flood
TOSLINK	TOTX147APL(F,T)	no replacement	damaged by Thai flood
TOSLINK	TOTX147L(F,T)	no replacement	damaged by Thai flood
TOSLINK	TOTX147PL(F,T)	no replacement	damaged by Thai flood
TOSLINK	TOTX177(F,T)	no replacement	damaged by Thai flood
TOSLINK	TOTX177A(F,T)	no replacement	damaged by Thai flood
TOSLINK	TOTX177AL(F,T)	no replacement	damaged by Thai flood
TOSLINK	TOTX177APL(F,T)	no replacement	damaged by Thai flood
TOSLINK	TOTX177L(F,T)	no replacement	damaged by Thai flood
TOSLINK	TOTX177PL(F,T)	no replacement	damaged by Thai flood
Photo-IC	TPS851(E,T)	no replacement	damaged by Thai flood
Photo-IC	TPS852(T)	no replacement	damaged by Thai flood
Photo-IC	TPS859(T)	no replacement	damaged by Thai flood
LED	TLPGE1100B(T11TE1T)	no replacement	damaged by Thai flood
LED	TLPGE1100B(T11TEET)	no replacement	damaged by Thai flood
LED	TLRE1100B(T13MM1,T)	no replacement	damaged by Thai flood
LED	TLRE1100D(T13MM1,T)	no replacement	damaged by Thai flood
Photocoupler	TLP180(ABB-TPL,F,T)	TLP184(GB-TPL,E(O	damaged by Thai flood
Photocoupler	TLP180(F,T)	TLP184(E(O	damaged by Thai flood
Photocoupler	TLP180(GB,F,T)	TLP184(GB,E(O	damaged by Thai flood
Photocoupler	TLP180(GB-TPL,F)	TLP184(GB-TPL,E(O	
Photocoupler	TLP180(GB-TPL,F,T)	TLP184(GB-TPL,E(O	damaged by Thai flood
Photocoupler	TLP180(GB-TPR,F,T)	TLP184(GB-TPR,E(O	damaged by Thai flood
Photocoupler	TLP180(GR-TPL,F)	TLP184(GR-TPL,E(O	

Photocoupler	TLP180(TPL,F)	TLP184(TPL,E(O	
Photocoupler	TLP180(TPL,F,T)	TLP184(TPL,E(O	damaged by Thai flood
Photocoupler	TLP180(TPR,F,T)	TLP184(TPR,E(O	damaged by Thai flood
Photocoupler	TLP180(V4GB-TL,F,T)	TLP184(V4GB-TL,E(O	damaged by Thai flood
Photocoupler	TLP180(V4-GB-TPL,F	TLP184(V4GB-TL,E(O	
Photocoupler	TLP181(ABB-TPL,F)	TLP185(GB-TPL,E(O	
Photocoupler	TLP181(ABB-TPL,F,T)	TLP185(GB-TPL,E(O	damaged by Thai flood
Photocoupler	TLP181(BL-TPL,F)	TLP185(BLL-TPL,E(O	
Photocoupler	TLP181(BL-TPL,F,T)	TLP185(BLL-TPL,E(O	damaged by Thai flood
Photocoupler	TLP181(BL-TPR,F)	TLP185(BLL-TPR,E(O	
Photocoupler	TLP181(BL-TPR,F,T)	TLP185(BLL-TPR,E(O	damaged by Thai flood
Photocoupler	TLP181(F)	TLP185(E(O	
Photocoupler	TLP181(F,T)	TLP185(E(O	damaged by Thai flood
Photocoupler	TLP181(GB,F,T)	TLP185(GB,E(O	damaged by Thai flood
Photocoupler	TLP181(GB-TPL,F)	TLP185(GB-TPL,E(O	
Photocoupler	TLP181(GB-TPL,F,T)	TLP185(GB-TPL,E(O	damaged by Thai flood
Photocoupler	TLP181(GB-TPR,F)	TLP185(GB-TPR,E(O	
Photocoupler	TLP181(GB-TPR,F,T)	TLP185(GB-TPR,E(O	damaged by Thai flood
Photocoupler	TLP181(GR,F,T)	TLP185(GR,E(O	damaged by Thai flood
Photocoupler	TLP181(GRH-TPL,F)	TLP185(GRH-TPL,E(O	
Photocoupler	TLP181(GRH-TPL,F,T)	TLP185(GRH-TPL,E(O	damaged by Thai flood
Photocoupler	TLP181(GRL-TPL,F)	TLP185(GRL-TPL,E(O	
Photocoupler	TLP181(GRL-TPL,F,T)	TLP185(GRL-TPL,E(O	damaged by Thai flood
Photocoupler	TLP181(GRL-TPR,F,T)	TLP185(GRL-TPR,E(O	damaged by Thai flood
Photocoupler	TLP181(GR-TPL,F)	TLP185(GR-TPL,E(O	
Photocoupler	TLP181(GR-TPL,F,T)	TLP185(GR-TPL,E(O	damaged by Thai flood
Photocoupler	TLP181(GR-TPR,F)	TLP185(GR-TPR,E(O	
Photocoupler	TLP181(GR-TPR,F,T)	TLP185(GR-TPR,E(O	damaged by Thai flood
Photocoupler	TLP181(MAT-DD-TL,F		
Photocoupler	TLP181(TPL,F)	TLP185(TPL,E(O	
Photocoupler	TLP181(TPL,F,T)	TLP185(TPL,E(O	damaged by Thai flood
Photocoupler	TLP181(TPR,F)	TLP185(TPR,E(O	
Photocoupler	TLP181(TPR,F,T)	TLP185(TPR,E(O	damaged by Thai flood
Photocoupler	TLP181(V4BL-TL,F,T)	TLP185(V4B-TL,E(O	damaged by Thai flood
Photocoupler	TLP181(V4-BL-TPL,F	TLP185(V4B-TL,E(O	
Photocoupler	TLP181(V4GB-TL,F,T)	TLP185(V4GB-TL,E(O	damaged by Thai flood
Photocoupler	TLP181(V4-GB-TPL,F	TLP185(V4GB-TL,E(O	
Photocoupler	TLP181(V4-GB-TPR,F	TLP185(V4GB-TR,E(O	
Photocoupler	TLP181(V4GL-TR,F,T)	TLP185(V4GL-TR,E(O	damaged by Thai flood
Photocoupler	TLP181(V4-GR-TPL,F	TLP185(V4GR-TL,E(O	
Photocoupler	TLP181(V4-GR-TPR,F	TLP185(V4GR-TR,E(O	
Photocoupler	TLP181(Y,F)	TLP185(Y,E(O	
Photocoupler	TLP181(Y,F,T)	TLP185(Y,E(O	damaged by Thai flood
Photocoupler	TLP181(YAMTK-TPL,F		
Photocoupler	TLP181(Y-TPL,F)	TLP185(Y-TPL,E(O	
Photocoupler	TLP181(Y-TPL,F,T)	TLP185(Y-TPL,E(O	damaged by Thai flood
Photocoupler	TLP181(Y-TPR,F)	TLP185(Y-TPR,E(O	
Photocoupler	TLP181(Y-TPR,F,T)	TLP185(Y-TPR,E(O	damaged by Thai flood
Photocoupler	*TLP184(GB-TPL,E(T	TLP184(GB-TPL,E(O	damaged by Thai flood
Photocoupler	*TLP185(GB-TPL,E(T	TLP185(GB-TPL,E(O	damaged by Thai flood

Photocoupler	TLP280(F)	TLP290(E(O	
Photocoupler	TLP280(F,T)	TLP290(E(O	damaged by Thai flood
Photocoupler	TLP280(GB-TP,F)	TLP290(GB-TP,E(O	
Photocoupler	TLP280(GB-TP,F,T)	TLP290(GB-TP,E(O	damaged by Thai flood
Photocoupler	TLP281(BL-TP,F)	TLP291(BLL-TP,E(O	
Photocoupler	TLP281(BL-TP,F,T)	TLP291(BLL-TP,E(O	damaged by Thai flood
Photocoupler	TLP281(F)	TLP291(E(O	
Photocoupler	TLP281(F,T)	TLP291(E(O	damaged by Thai flood
Photocoupler	TLP281(GB,F)	TLP291(GB,E(O	
Photocoupler	TLP281(GB,F,T)	TLP291(GB,E(O	damaged by Thai flood
Photocoupler	TLP281(GB-TP,F)	TLP291(GB-TP,E(O	
Photocoupler	TLP281(GB-TP,F,T)	TLP291(GB-TP,E(O	damaged by Thai flood
Photocoupler	TLP281(GR,F,T)	TLP291(GR,E(O	damaged by Thai flood
Photocoupler	TLP281(GRH-TP,F)	TLP291(GRH-TP,E(O	
Photocoupler	TLP281(GRH-TP,F,T)	TLP291(GRH-TP,E(O	damaged by Thai flood
Photocoupler	TLP281(GRL-TP,F)	TLP291(GRL-TP,E(O	
Photocoupler	TLP281(GRL-TP,F,T)	TLP291(GRL-TP,E(O	damaged by Thai flood
Photocoupler	TLP281(GR-TP,F)	TLP291(GR-TP,E(O	
Photocoupler	TLP281(GR-TP,F,T)	TLP291(GR-TP,E(O	damaged by Thai flood
Photocoupler	TLP281(TP,F)	TLP291(TP,E(O	
Photocoupler	TLP281(TP,F,T)	TLP291(TP,E(O	damaged by Thai flood
Photocoupler	TLP281(V4-BL-TP,F)	TLP291(V4B-TP,E(O	
Photocoupler	TLP281(V4-GB-TP,F)	TLP291(V4GB-TP,E(O	
Photocoupler	TLP281(V4GB-TP,F,T)	TLP291(V4GB-TP,E(O	damaged by Thai flood
Photocoupler	TLP281(V4GL-TP,F,T)	TLP291(V4GL-TP,E(O	damaged by Thai flood
Photocoupler	TLP281(V4-GR-TP,F)	TLP291(V4GR-TP,E(O	
Photocoupler	TLP281(Y-TP,F,T)	TLP291(Y-TP,E(O	damaged by Thai flood
Photocoupler	TLP284(F)	TLP290(E(O	
Photocoupler	TLP285(BL-TPL,E,T)	TLP291(BLL-TP,E(O	damaged by Thai flood
Photocoupler	TLP285(GR,F,T)	TLP291(GR,E(O	damaged by Thai flood
Photocoupler	TLP285(GR-TP,F,T)	TLP291(GR-TP,E(O	damaged by Thai flood
Photocoupler	TLP285(TP,F,T)	TLP291(TP,E(O	damaged by Thai flood
Photocoupler	*TLP290-4(E(T	TLP290-4(E(O	damaged by Thai flood
Photocoupler	*TLP290-4(GB,E(T	TLP290-4(GB,E(O	damaged by Thai flood
Photocoupler	*TLP290-4(GB-TP,E(T	TLP290-4(GB-TP,E(O	damaged by Thai flood
Photocoupler	*TLP290-4(TP,E(T	TLP290-4(TP,E(O	damaged by Thai flood
Photocoupler	*TLP291-4(E(T	TLP291-4(E(O	damaged by Thai flood
Photocoupler	*TLP291-4(GB,E(T	TLP291-4(GB,E(O	damaged by Thai flood
Photocoupler	*TLP291-4(GB-TP,E(T	TLP291-4(GB-TP,E(O	damaged by Thai flood
Photocoupler	TLP3022(D4,S,F,T)	TLP3022(D4,S,F)	damaged by Thai flood
Photocoupler	TLP3022(D4T1,S,F,T)	TLP3022(D4-TP1,S,F)	damaged by Thai flood
Photocoupler	TLP3022(S,F,T)	TLP3022(S,F)	damaged by Thai flood
Photocoupler	TLP3023(S,F,T)	TLP3023(S,F)	damaged by Thai flood
Photocoupler	TLP3023(TP1,S,F,T)		damaged by Thai flood
Photocoupler	TLP3023F(S,F,T)	TLP3023F(S,F)	damaged by Thai flood
Photocoupler	TLP3041(S,C,F,T)	TLP3041(S,C,F)	damaged by Thai flood
Photocoupler	TLP3042(S,C,F,T)	TLP3042(S,C,F)	damaged by Thai flood
Photocoupler	TLP3043(S,C,F,T)	TLP3043(S,C,F)	damaged by Thai flood
Photocoupler	TLP3052(D4,S,C,F,T)	TLP3052(D4,S,C,F)	damaged by Thai flood
Photocoupler	TLP3052(S,C,F,T)	TLP3052(S,C,F)	damaged by Thai flood

Photocoupler	TLP3052(TP1,SC,F,T)		damaged by Thai flood
Photocoupler	TLP3052F(D4,SC,F,T)	TLP3052F(D4,S,C,F)	damaged by Thai flood
Photocoupler	TLP3052F(D4TP4SCFT)		damaged by Thai flood
Photocoupler	TLP3061(S,C,F,T)	TLP3061(S,C,F)	damaged by Thai flood
Photocoupler	TLP3062(D4,S,C,F,T)	TLP3062(D4,S,C,F)	damaged by Thai flood
Photocoupler	TLP3062(D4F2SC,F,T)	TLP3062(D4LF2S,C,F)	damaged by Thai flood
Photocoupler	TLP3062(LF1,SC,F,T)		damaged by Thai flood
Photocoupler	TLP3062(S,C,F,T)	TLP3062(S,C,F)	damaged by Thai flood
Photocoupler	TLP3062(TP1,SC,F,T)		damaged by Thai flood
Photocoupler	TLP3062F(D4T4SCF,T)	TLP3062F(D4TP4SC,F)	damaged by Thai flood
Photocoupler	TLP3063(D4,S,C,F,T)	TLP3063(D4,S,C,F)	damaged by Thai flood
Photocoupler	TLP3063(D4F2SC,F,T)	TLP3063(D4LF2S,C,F)	damaged by Thai flood
Photocoupler	TLP3063(D4T5SC,F,T)	TLP3063(D4TP5S,C,F)	damaged by Thai flood
Photocoupler	TLP3063(S,C,F,T)	TLP3063(S,C,F)	damaged by Thai flood
Photocoupler	TLP3063(TP1,SC,F,T)	TLP3063(TP1,S,C,F)	damaged by Thai flood
Photocoupler	TLP3063F(D4T4SCF,T)	TLP3063F(D4TP4SC,F)	damaged by Thai flood
Photocoupler	TLP3063F(S,C,F,T)	TLP3063F(S,C,F)	damaged by Thai flood
Photocoupler	TLP3064(D4,S,C,F,T)		damaged by Thai flood
Photocoupler	TLP361JF(D4TP4,F,T)		damaged by Thai flood
Photocoupler	*TLP3782(S,C,F,T)	TLP3782(S,C,F)	damaged by Thai flood
Photocoupler	*TLP3783(S,C,F,T)	TLP3783(S,C,F)	damaged by Thai flood
Photocoupler	*TLP3783F(D4F4SCF,T)	TLP3783F(D4LF4SC,F)	damaged by Thai flood
Photocoupler	TLP3783F(D4T4SCF,T)		damaged by Thai flood
Photocoupler	TLP521-1(A,F,T)	TLP785(GB,F(C	damaged by Thai flood
Photocoupler	TLP521-1(BL,F,T)	TLP785(BL,F(C	damaged by Thai flood
Photocoupler	TLP521-1(FA,F,T)	TLP785(GB,F(C	damaged by Thai flood
Photocoupler	TLP521-1(GB,F,T)	TLP785(GB,F(C	damaged by Thai flood
Photocoupler	TLP521-1(GR,F,T)	TLP785(GR,F(C	damaged by Thai flood
Photocoupler	TLP521-1(Y,F,T)	TLP785(Y,F(C	damaged by Thai flood
Photocoupler	TLP521-2(GB,F,T)	TLP785(GB,F(C	damaged by Thai flood
Photocoupler	TLP521-2(GR,F,T)	TLP785(GR,F(C	damaged by Thai flood
Photocoupler	TLP560G(F,T)		damaged by Thai flood
Photocoupler	TLP620(ABB-TP4,F,T)	TLP620(ABB-TP4,F)	damaged by Thai flood
Photocoupler	TLP620(D4-GB,F,T)	TLP620(D4-GB,F)	damaged by Thai flood
Photocoupler	TLP620(D4-GR,F,T)	TLP620(D4-GR,F)	damaged by Thai flood
Photocoupler	TLP620(D4GR-T4,F,T)	TLP620(D4-GR-TP4,F)	damaged by Thai flood
Photocoupler	TLP620(F,T)	TLP620(F)	damaged by Thai flood
Photocoupler	TLP620(GB,F,T)	TLP620(GB,F)	damaged by Thai flood
Photocoupler	TLP620(GR,F,T)	TLP620(GR,F)	damaged by Thai flood
Photocoupler	TLP620(TP1,F,T)	TLP620(TP1,F)	damaged by Thai flood
Photocoupler	TLP620-2(F,T)	TLP620-2(F)	damaged by Thai flood
Photocoupler	TLP620-2(GB,F,T)	TLP620-2(GB,F)	damaged by Thai flood
Photocoupler	TLP621(BL,F,T)	TLP785(BL,F(C	damaged by Thai flood
Photocoupler	TLP621(D4BL-T5,F,T)	TLP781(D4-BL-TP6,F)	damaged by Thai flood
Photocoupler	TLP621(D4-GB,F,T)	TLP785(D4-GB,F(C	damaged by Thai flood
Photocoupler	TLP621(D4GB-T1,F,T)	TLP785(D4GR-T6,F(C	damaged by Thai flood
Photocoupler	TLP621(D4GB-T5,F,T)	TLP785(D4GR-T6,F(C	damaged by Thai flood
Photocoupler	TLP621(D4-GR,F,T)	TLP785(D4-GR,F(C	damaged by Thai flood
Photocoupler	TLP621(D4GR-F2,F,T)	TLP781F(D4-GR,F)	damaged by Thai flood
Photocoupler	TLP621(D4-Y-F2,F,T)	TLP781F(D4-Y,F)	damaged by Thai flood

Photocoupler	TLP621(F,T)	TLP785(GB,F(C	damaged by Thai flood
Photocoupler	TLP621(GB,F,T)	TLP785(GB,F(C	damaged by Thai flood
Photocoupler	TLP621(GR,F,T)	TLP785(GR,F(C	damaged by Thai flood
Photocoupler	TLP621(GRH-TP1,F,T	TLP785(GRH-TP6,F(C	damaged by Thai flood
Photocoupler	TLP621(GR-LF2,F,T)	TLP781F(D4-GR,F)	damaged by Thai flood
Photocoupler	TLP621(GR-TP1,F,T)	TLP785(GR-TP6,F(C	damaged by Thai flood
Photocoupler	TLP621(TP1,F,T)	TLP785(TP6,F(C	damaged by Thai flood
Photocoupler	TLP621(Y,F,T)	TLP785(Y,F(C	damaged by Thai flood
Photocoupler	TLP621-2(D4GBF1F,T	TLP785(D4GR-T6,F(C	damaged by Thai flood
Photocoupler	TLP621-2(D4GBT1F,T	TLP785(D4GR-T6,F(C	damaged by Thai flood
Photocoupler	TLP621-2(F,T)	TLP785(GB,F(C	damaged by Thai flood
Photocoupler	TLP621-2(GR,F,T)	TLP785(GR,F(C	damaged by Thai flood
Photocoupler	TLP627(F,T)	TLP627(F)	damaged by Thai flood
Photocoupler	TLP627(TP1,F,T)	TLP627(TP1,F)	damaged by Thai flood
Photocoupler	TLP627-2(F,T)	TLP627-2(F)	damaged by Thai flood
Photocoupler	TLP627-2(TP1,F,T)	TLP627(TP1,F)	damaged by Thai flood
Photocoupler	*TLP669L(D4CGP5SCFT	TLP669L(D4CGP5SC,F	damaged by Thai flood

* Note: Partnumbers are promotional, only production location will move to Japan

Replacement Items

See table

Discontinuation schedule:

Official announcement to Customer

Date: December 2011

For all above items, new orders can not be accepted any more.

For items with reason “damaged by Thai flood” existing backlog can not be supported any more. Please cancel your related backlog and move your orders where possible to recommended replacement items.

Date: 20.12.2011

generated by M. Diephaus – Senior Manager

Toshiba Electronics Europe GmbH.....

(document transmitted by E-Mail, valid without signature)