

05 September 2016

Dear Customer

We have been advised by the INVAC factory that they will no longer be able to produce DIL type bridge rectifiers. The reason for this is due to increased production costs and declining sales, which has made this product type not commercially viable.

List of part numbers affected by this EOL notice

EOL Part Number	Description	EOL Part Number	Description
DI100	1A 50V DIL BRIDGE (GP)	DI150	1.5A 50V DIL BRIDGE (GP)
DI101	1A 100V DIL BRIDGE (GP)	DI151	1.5A 100V DIL BRIDGE (GP)
DI102	1A 200V DIL BRIDGE (GP)	DI152	1.5A 200V DIL BRIDGE (GP)
DI104	1A 400V DIL BRIDGE (GP)	DI154	1.5A 400V DIL BRIDGE (GP)
DI106	1A 600V DIL BRIDGE (GP)	DI156	1.5A 600V DIL BRIDGE (GP)
DI108	1A 800V DIL BRIDGE (GP)	DI158	1.5A 800V DIL BRIDGE (GP)
DI1010	1A 1000V DIL BRIDGE (GP)	DI1510	1.5A 1000V DIL BRIDGE (GP)

There is no direct alternative available for this package type from INVAC but we are able to recommend the DFxxM series from Diode Zetex as a suitable alternative, please contact our sales desk if you require samples or data of the recommended alternative.

There is a last time buy opportunity for the INVAC part up until the 21st of October 2016. Please contact our sales desk with your requirement ASAP and make the relevant person(s) in your purchasing and engineering departments aware of this change to prevent disruption to your production schedule.

Yours Sincerely

Anglia