

## Obsolete Product Notification from Harwin

| Part number being made obsolete | Drawing for obsolete product         | Last Time buy date | Alternative product     | Drawing for alternative product |
|---------------------------------|--------------------------------------|--------------------|-------------------------|---------------------------------|
| M80-080                         | <a href="#">M80-080_obsolete.pdf</a> | 7th September 2018 | <a href="#">M80-001</a> | <a href="#">M80-001.pdf</a>     |
| B5743-102-M-T-R                 | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520242             | <a href="#">M80-852.pdf</a>     |
| B5743-103-M-T-R                 | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520342             | <a href="#">M80-852.pdf</a>     |
| B5743-104-M-T-R                 | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520442             | <a href="#">M80-852.pdf</a>     |
| B5743-105-M-T-R                 | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520542             | <a href="#">M80-852.pdf</a>     |
| B5743-106-M-T-R                 | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520642             | <a href="#">M80-852.pdf</a>     |
| B5743-107-M-T-R                 | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520742             | <a href="#">M80-852.pdf</a>     |
| B5743-117-M-T-R                 | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8521742             | <a href="#">M80-852.pdf</a>     |
| B5743-204-M-T-R                 | <a href="#">M80-815_obsolete.pdf</a> | 7th September 2018 | M80-8540442             | <a href="#">M80-854.pdf</a>     |
| B5743-206-M-T-R                 | <a href="#">M80-815_obsolete.pdf</a> | 7th September 2018 | M80-8540642             | <a href="#">M80-854.pdf</a>     |
| B5743-208-M-T-R                 | <a href="#">M80-815_obsolete.pdf</a> | 7th September 2018 | M80-8540842             | <a href="#">M80-854.pdf</a>     |
| B5743-210-M-T-R                 | <a href="#">M80-815_obsolete.pdf</a> | 7th September 2018 | M80-8541042             | <a href="#">M80-854.pdf</a>     |
| B5743-212-M-T-R                 | <a href="#">M80-815_obsolete.pdf</a> | 7th September 2018 | M80-8541242             | <a href="#">M80-854.pdf</a>     |
| B5743-214-M-T-R                 | <a href="#">M80-815_obsolete.pdf</a> | 7th September 2018 | M80-8541442             | <a href="#">M80-854.pdf</a>     |
| B5743-216-M-T-R                 | <a href="#">M80-815_obsolete.pdf</a> | 7th September 2018 | M80-8541642             | <a href="#">M80-854.pdf</a>     |
| B5743-218-M-T-R                 | <a href="#">M80-815_obsolete.pdf</a> | 7th September 2018 | M80-8541842             | <a href="#">M80-854.pdf</a>     |
| B5743-220-M-T-R                 | <a href="#">M80-815_obsolete.pdf</a> | 7th September 2018 | M80-8542042             | <a href="#">M80-854.pdf</a>     |
| B5743-226-M-T-R                 | <a href="#">M80-815_obsolete.pdf</a> | 7th September 2018 | M80-8542642             | <a href="#">M80-854.pdf</a>     |
| B5743-234-M-T-R                 | <a href="#">M80-815_obsolete.pdf</a> | 7th September 2018 | M80-8543442             | <a href="#">M80-854.pdf</a>     |
| B5743-244-M-T-R                 | <a href="#">M80-815_obsolete.pdf</a> | 7th September 2018 | M80-8544442             | <a href="#">M80-854.pdf</a>     |
| M80-6670442                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6650442             | <a href="#">M80-665.pdf</a>     |
| M80-6670445                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6650445             | <a href="#">M80-665.pdf</a>     |
| M80-6670642                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6650642             | <a href="#">M80-665.pdf</a>     |
| M80-6670645                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6650645             | <a href="#">M80-665.pdf</a>     |
| M80-6670842                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6650842             | <a href="#">M80-665.pdf</a>     |
| M80-6670845                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6650845             | <a href="#">M80-665.pdf</a>     |
| M80-6671042                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6651042             | <a href="#">M80-665.pdf</a>     |
| M80-6671045                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6651045             | <a href="#">M80-665.pdf</a>     |
| M80-6671242                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6651242             | <a href="#">M80-665.pdf</a>     |
| M80-6671245                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6651245             | <a href="#">M80-665.pdf</a>     |
| M80-6671422                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6651442             | <a href="#">M80-665.pdf</a>     |
| M80-6671442                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6651442             | <a href="#">M80-665.pdf</a>     |
| M80-6671445                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6651445             | <a href="#">M80-665.pdf</a>     |
| M80-6671622                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6651642             | <a href="#">M80-665.pdf</a>     |
| M80-6671642                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6651642             | <a href="#">M80-665.pdf</a>     |
| M80-6671645                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6651645             | <a href="#">M80-665.pdf</a>     |
| M80-6671822                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6651842             | <a href="#">M80-665.pdf</a>     |
| M80-6671842                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6651842             | <a href="#">M80-665.pdf</a>     |
| M80-6671845                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6651845             | <a href="#">M80-665.pdf</a>     |
| M80-6672022                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6652042             | <a href="#">M80-665.pdf</a>     |
| M80-6672042                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6652042             | <a href="#">M80-665.pdf</a>     |
| M80-6672045                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6652045             | <a href="#">M80-665.pdf</a>     |
| M80-6672622                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6652642             | <a href="#">M80-665.pdf</a>     |
| M80-6672642                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6652642             | <a href="#">M80-665.pdf</a>     |
| M80-6672645                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6652645             | <a href="#">M80-665.pdf</a>     |
| M80-6673422                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6653442             | <a href="#">M80-665.pdf</a>     |
| M80-6673442                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6653442             | <a href="#">M80-665.pdf</a>     |
| M80-6673445                     | <a href="#">M80-667_obsolete.pdf</a> | 7th September 2018 | M80-6653445             | <a href="#">M80-665.pdf</a>     |
| M80-7480222                     | Contact technical@harwin.com         | 7th September 2018 | M80-8520242             | <a href="#">M80-852.pdf</a>     |
| M80-7480242                     | Contact technical@harwin.com         | 7th September 2018 | M80-8520242             | <a href="#">M80-852.pdf</a>     |
| M80-7480245                     | Contact technical@harwin.com         | 7th September 2018 | M80-8520245             | <a href="#">M80-852.pdf</a>     |
| M80-7480322                     | Contact technical@harwin.com         | 7th September 2018 | M80-8520342             | <a href="#">M80-852.pdf</a>     |
| M80-7480342                     | Contact technical@harwin.com         | 7th September 2018 | M80-8520342             | <a href="#">M80-852.pdf</a>     |
| M80-7480345                     | Contact technical@harwin.com         | 7th September 2018 | M80-8520345             | <a href="#">M80-852.pdf</a>     |
| M80-7480422                     | Contact technical@harwin.com         | 7th September 2018 | M80-8520442             | <a href="#">M80-852.pdf</a>     |
| M80-7480442                     | Contact technical@harwin.com         | 7th September 2018 | M80-8520442             | <a href="#">M80-852.pdf</a>     |
| M80-7480445                     | Contact technical@harwin.com         | 7th September 2018 | M80-8520445             | <a href="#">M80-852.pdf</a>     |

## Obsolete Product Notification from Harwin

| Part number being made obsolete | Drawing for obsolete product         | Last Time buy date | Alternative product | Drawing for alternative product |
|---------------------------------|--------------------------------------|--------------------|---------------------|---------------------------------|
| M80-7480522                     | Contact technical@harwin.com         | 7th September 2018 | M80-8520542         | <a href="#">M80-852.pdf</a>     |
| M80-7480542                     | Contact technical@harwin.com         | 7th September 2018 | M80-8520542         | <a href="#">M80-852.pdf</a>     |
| M80-7480545                     | Contact technical@harwin.com         | 7th September 2018 | M80-8520545         | <a href="#">M80-852.pdf</a>     |
| M80-7480622                     | Contact technical@harwin.com         | 7th September 2018 | M80-8520642         | <a href="#">M80-852.pdf</a>     |
| M80-7480642                     | Contact technical@harwin.com         | 7th September 2018 | M80-8520642         | <a href="#">M80-852.pdf</a>     |
| M80-7480645                     | Contact technical@harwin.com         | 7th September 2018 | M80-8520645         | <a href="#">M80-852.pdf</a>     |
| M80-7480722                     | Contact technical@harwin.com         | 7th September 2018 | M80-8520742         | <a href="#">M80-852.pdf</a>     |
| M80-7480742                     | Contact technical@harwin.com         | 7th September 2018 | M80-8520742         | <a href="#">M80-852.pdf</a>     |
| M80-7480745                     | Contact technical@harwin.com         | 7th September 2018 | M80-8520745         | <a href="#">M80-852.pdf</a>     |
| M80-7481722                     | Contact technical@harwin.com         | 7th September 2018 | M80-8521742         | <a href="#">M80-852.pdf</a>     |
| M80-7481742                     | Contact technical@harwin.com         | 7th September 2018 | M80-8521742         | <a href="#">M80-852.pdf</a>     |
| M80-7481745                     | Contact technical@harwin.com         | 7th September 2018 | M80-8521745         | <a href="#">M80-852.pdf</a>     |
| M80-7482222                     | Contact technical@harwin.com         | 7th September 2018 | M80-8542422         | <a href="#">M80-852.pdf</a>     |
| M80-7482242                     | Contact technical@harwin.com         | 7th September 2018 | M80-8542242         | <a href="#">M80-852.pdf</a>     |
| M80-7482245                     | Contact technical@harwin.com         | 7th September 2018 | M80-8542245         | <a href="#">M80-852.pdf</a>     |
| M80-7630422                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7540442         | <a href="#">M80-754.pdf</a>     |
| M80-7630442                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7540442         | <a href="#">M80-754.pdf</a>     |
| M80-7630445                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7540445         | <a href="#">M80-754.pdf</a>     |
| M80-7630622                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7540645         | <a href="#">M80-754.pdf</a>     |
| M80-7630642                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7540645         | <a href="#">M80-754.pdf</a>     |
| M80-7630645                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7540645         | <a href="#">M80-754.pdf</a>     |
| M80-7630822                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7540842         | <a href="#">M80-754.pdf</a>     |
| M80-7630842                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7540842         | <a href="#">M80-754.pdf</a>     |
| M80-7630845                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7540845         | <a href="#">M80-754.pdf</a>     |
| M80-7631022                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7541042         | <a href="#">M80-754.pdf</a>     |
| M80-7631042                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7541042         | <a href="#">M80-754.pdf</a>     |
| M80-7631045                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7541045         | <a href="#">M80-754.pdf</a>     |
| M80-7631222                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7541242         | <a href="#">M80-754.pdf</a>     |
| M80-7631242                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7541242         | <a href="#">M80-754.pdf</a>     |
| M80-7631245                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7541245         | <a href="#">M80-754.pdf</a>     |
| M80-7631422                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7541445         | <a href="#">M80-754.pdf</a>     |
| M80-7631442                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7541445         | <a href="#">M80-754.pdf</a>     |
| M80-7631445                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7541445         | <a href="#">M80-754.pdf</a>     |
| M80-7631622                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7541642         | <a href="#">M80-754.pdf</a>     |
| M80-7631642                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7541642         | <a href="#">M80-754.pdf</a>     |
| M80-7631645                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7541645         | <a href="#">M80-754.pdf</a>     |
| M80-7631822                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7541842         | <a href="#">M80-754.pdf</a>     |
| M80-7631842                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7541842         | <a href="#">M80-754.pdf</a>     |
| M80-7631845                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7541845         | <a href="#">M80-754.pdf</a>     |
| M80-7632022                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7542042         | <a href="#">M80-754.pdf</a>     |
| M80-7632042                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7542042         | <a href="#">M80-754.pdf</a>     |
| M80-7632045                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7542045         | <a href="#">M80-754.pdf</a>     |
| M80-7632622                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7542642         | <a href="#">M80-754.pdf</a>     |
| M80-7632642                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7542642         | <a href="#">M80-754.pdf</a>     |
| M80-7632645                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7542645         | <a href="#">M80-754.pdf</a>     |
| M80-7633422                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7543442         | <a href="#">M80-754.pdf</a>     |
| M80-7633442                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7543442         | <a href="#">M80-754.pdf</a>     |
| M80-7633445                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7543445         | <a href="#">M80-754.pdf</a>     |
| M80-7634422                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7544442         | <a href="#">M80-754.pdf</a>     |
| M80-7634442                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7544442         | <a href="#">M80-754.pdf</a>     |
| M80-7634445                     | <a href="#">M80-763_obsolete.pdf</a> | 7th September 2018 | M80-7544445         | <a href="#">M80-754.pdf</a>     |
| M80-7810222                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7520242         | <a href="#">M80-752.pdf</a>     |
| M80-7810242                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7520242         | <a href="#">M80-752.pdf</a>     |
| M80-7810245                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7520245         | <a href="#">M80-752.pdf</a>     |
| M80-7810322                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7520345         | <a href="#">M80-752.pdf</a>     |
| M80-7810342                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7520345         | <a href="#">M80-752.pdf</a>     |
| M80-7810345                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7520345         | <a href="#">M80-752.pdf</a>     |

## Obsolete Product Notification from Harwin

| Part number being made obsolete | Drawing for obsolete product         | Last Time buy date | Alternative product | Drawing for alternative product |
|---------------------------------|--------------------------------------|--------------------|---------------------|---------------------------------|
| M80-7810422                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7520445         | <a href="#">M80-752.pdf</a>     |
| M80-7810442                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7520445         | <a href="#">M80-752.pdf</a>     |
| M80-7810445                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7520445         | <a href="#">M80-752.pdf</a>     |
| M80-7810522                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7520542         | <a href="#">M80-752.pdf</a>     |
| M80-7810542                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7520542         | <a href="#">M80-752.pdf</a>     |
| M80-7810545                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7520545         | <a href="#">M80-752.pdf</a>     |
| M80-7810622                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7520642         | <a href="#">M80-752.pdf</a>     |
| M80-7810642                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7520642         | <a href="#">M80-752.pdf</a>     |
| M80-7810645                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7520645         | <a href="#">M80-752.pdf</a>     |
| M80-7810722                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7520742         | <a href="#">M80-752.pdf</a>     |
| M80-7810742                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7520742         | <a href="#">M80-752.pdf</a>     |
| M80-7810745                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7520745         | <a href="#">M80-752.pdf</a>     |
| M80-7811722                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7521742         | <a href="#">M80-752.pdf</a>     |
| M80-7811742                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7521742         | <a href="#">M80-752.pdf</a>     |
| M80-7811745                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7521745         | <a href="#">M80-752.pdf</a>     |
| M80-7812222                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7522242         | <a href="#">M80-752.pdf</a>     |
| M80-7812242                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7522242         | <a href="#">M80-752.pdf</a>     |
| M80-7812245                     | <a href="#">M80-781_obsolete.pdf</a> | 7th September 2018 | M80-7522245         | <a href="#">M80-752.pdf</a>     |
| M80-8040205                     | <a href="#">M80-804_obsolete.pdf</a> | 7th September 2018 | M80-8430245         | <a href="#">M80-843.pdf</a>     |
| M80-8040222                     | <a href="#">M80-804_obsolete.pdf</a> | 7th September 2018 | M80-8430242         | <a href="#">M80-843.pdf</a>     |
| M80-8040305                     | <a href="#">M80-804_obsolete.pdf</a> | 7th September 2018 | M80-8430345         | <a href="#">M80-843.pdf</a>     |
| M80-8040322                     | <a href="#">M80-804_obsolete.pdf</a> | 7th September 2018 | M80-8430342         | <a href="#">M80-843.pdf</a>     |
| M80-8040405                     | <a href="#">M80-804_obsolete.pdf</a> | 7th September 2018 | M80-8430445         | <a href="#">M80-843.pdf</a>     |
| M80-8040422                     | <a href="#">M80-804_obsolete.pdf</a> | 7th September 2018 | M80-8430442         | <a href="#">M80-843.pdf</a>     |
| M80-8040505                     | <a href="#">M80-804_obsolete.pdf</a> | 7th September 2018 | M80-8430545         | <a href="#">M80-843.pdf</a>     |
| M80-8040522                     | <a href="#">M80-804_obsolete.pdf</a> | 7th September 2018 | M80-8430542         | <a href="#">M80-843.pdf</a>     |
| M80-8040605                     | <a href="#">M80-804_obsolete.pdf</a> | 7th September 2018 | M80-8430645         | <a href="#">M80-843.pdf</a>     |
| M80-8040622                     | <a href="#">M80-804_obsolete.pdf</a> | 7th September 2018 | M80-8430642         | <a href="#">M80-843.pdf</a>     |
| M80-8040705                     | <a href="#">M80-804_obsolete.pdf</a> | 7th September 2018 | M80-8430745         | <a href="#">M80-843.pdf</a>     |
| M80-8040722                     | <a href="#">M80-804_obsolete.pdf</a> | 7th September 2018 | M80-8430742         | <a href="#">M80-843.pdf</a>     |
| M80-8041705                     | <a href="#">M80-804_obsolete.pdf</a> | 7th September 2018 | M80-8431745         | <a href="#">M80-843.pdf</a>     |
| M80-8041722                     | <a href="#">M80-804_obsolete.pdf</a> | 7th September 2018 | M80-8431742         | <a href="#">M80-843.pdf</a>     |
| M80-8042205                     | <a href="#">M80-804_obsolete.pdf</a> | 7th September 2018 | M80-8432245         | <a href="#">M80-843.pdf</a>     |
| M80-8042222                     | <a href="#">M80-804_obsolete.pdf</a> | 7th September 2018 | M80-8432242         | <a href="#">M80-843.pdf</a>     |
| M80-8050205                     | <a href="#">M80-805_obsolete.pdf</a> | 7th September 2018 | M80-8520245         | <a href="#">M80-852.pdf</a>     |
| M80-8050222                     | <a href="#">M80-805_obsolete.pdf</a> | 7th September 2018 | M80-8520242         | <a href="#">M80-852.pdf</a>     |
| M80-8050305                     | <a href="#">M80-805_obsolete.pdf</a> | 7th September 2018 | M80-8520345         | <a href="#">M80-852.pdf</a>     |
| M80-8050322                     | <a href="#">M80-805_obsolete.pdf</a> | 7th September 2018 | M80-8520342         | <a href="#">M80-852.pdf</a>     |
| M80-8050405                     | <a href="#">M80-805_obsolete.pdf</a> | 7th September 2018 | M80-8520445         | <a href="#">M80-852.pdf</a>     |
| M80-8050422                     | <a href="#">M80-805_obsolete.pdf</a> | 7th September 2018 | M80-8520442         | <a href="#">M80-852.pdf</a>     |
| M80-8050505                     | <a href="#">M80-805_obsolete.pdf</a> | 7th September 2018 | M80-8520545         | <a href="#">M80-852.pdf</a>     |
| M80-8050522                     | <a href="#">M80-805_obsolete.pdf</a> | 7th September 2018 | M80-8520542         | <a href="#">M80-852.pdf</a>     |
| M80-8050605                     | <a href="#">M80-805_obsolete.pdf</a> | 7th September 2018 | M80-8520645         | <a href="#">M80-852.pdf</a>     |
| M80-8050622                     | <a href="#">M80-805_obsolete.pdf</a> | 7th September 2018 | M80-8520642         | <a href="#">M80-852.pdf</a>     |
| M80-8050705                     | <a href="#">M80-805_obsolete.pdf</a> | 7th September 2018 | M80-8520745         | <a href="#">M80-852.pdf</a>     |
| M80-8050722                     | <a href="#">M80-805_obsolete.pdf</a> | 7th September 2018 | M80-8520742         | <a href="#">M80-852.pdf</a>     |
| M80-8051705                     | <a href="#">M80-805_obsolete.pdf</a> | 7th September 2018 | M80-8521745         | <a href="#">M80-852.pdf</a>     |
| M80-8051722                     | <a href="#">M80-805_obsolete.pdf</a> | 7th September 2018 | M80-8521742         | <a href="#">M80-852.pdf</a>     |
| M80-8052205                     | <a href="#">M80-805_obsolete.pdf</a> | 7th September 2018 | M80-8522245         | <a href="#">M80-852.pdf</a>     |
| M80-8052222                     | <a href="#">M80-805_obsolete.pdf</a> | 7th September 2018 | M80-8522242         | <a href="#">M80-852.pdf</a>     |
| M80-8140405                     | <a href="#">M80-814_obsolete.pdf</a> | 7th September 2018 | M80-8410445         | <a href="#">M80-841.pdf</a>     |
| M80-8140422                     | <a href="#">M80-814_obsolete.pdf</a> | 7th September 2018 | M80-8410442         | <a href="#">M80-841.pdf</a>     |
| M80-8140605                     | <a href="#">M80-814_obsolete.pdf</a> | 7th September 2018 | M80-8410645         | <a href="#">M80-841.pdf</a>     |
| M80-8140622                     | <a href="#">M80-814_obsolete.pdf</a> | 7th September 2018 | M80-8410642         | <a href="#">M80-841.pdf</a>     |
| M80-8140805                     | <a href="#">M80-814_obsolete.pdf</a> | 7th September 2018 | M80-8410845         | <a href="#">M80-841.pdf</a>     |
| M80-8140822                     | <a href="#">M80-814_obsolete.pdf</a> | 7th September 2018 | M80-8410842         | <a href="#">M80-841.pdf</a>     |
| M80-8141005                     | <a href="#">M80-814_obsolete.pdf</a> | 7th September 2018 | M80-8411045         | <a href="#">M80-841.pdf</a>     |

## Obsolete Product Notification from Harwin

| Part number being made obsolete | Drawing for obsolete product          | Last Time buy date | Alternative product | Drawing for alternative product |
|---------------------------------|---------------------------------------|--------------------|---------------------|---------------------------------|
| M80-8141022                     | <a href="#">M80-814_obsolete.pdf</a>  | 7th September 2018 | M80-8411042         | <a href="#">M80-841.pdf</a>     |
| M80-8141205                     | <a href="#">M80-814_obsolete.pdf</a>  | 7th September 2018 | M80-8411245         | <a href="#">M80-841.pdf</a>     |
| M80-8141222                     | <a href="#">M80-814_obsolete.pdf</a>  | 7th September 2018 | M80-8411242         | <a href="#">M80-841.pdf</a>     |
| M80-8141405                     | <a href="#">M80-814_obsolete.pdf</a>  | 7th September 2018 | M80-8411445         | <a href="#">M80-841.pdf</a>     |
| M80-8141422                     | <a href="#">M80-814_obsolete.pdf</a>  | 7th September 2018 | M80-8411442         | <a href="#">M80-841.pdf</a>     |
| M80-8141605                     | <a href="#">M80-814_obsolete.pdf</a>  | 7th September 2018 | M80-8411645         | <a href="#">M80-841.pdf</a>     |
| M80-8141622                     | <a href="#">M80-814_obsolete.pdf</a>  | 7th September 2018 | M80-8411642         | <a href="#">M80-841.pdf</a>     |
| M80-8141805                     | <a href="#">M80-814_obsolete.pdf</a>  | 7th September 2018 | M80-8411845         | <a href="#">M80-841.pdf</a>     |
| M80-8142005                     | <a href="#">M80-814_obsolete.pdf</a>  | 7th September 2018 | M80-8412045         | <a href="#">M80-841.pdf</a>     |
| M80-8142022                     | <a href="#">M80-814_obsolete.pdf</a>  | 7th September 2018 | M80-8412042         | <a href="#">M80-841.pdf</a>     |
| M80-8142605                     | <a href="#">M80-814_obsolete.pdf</a>  | 7th September 2018 | M80-8412645         | <a href="#">M80-841.pdf</a>     |
| M80-8142622                     | <a href="#">M80-814_obsolete.pdf</a>  | 7th September 2018 | M80-8412642         | <a href="#">M80-841.pdf</a>     |
| M80-8143405                     | <a href="#">M80-814_obsolete.pdf</a>  | 7th September 2018 | M80-8413445         | <a href="#">M80-841.pdf</a>     |
| M80-8143422                     | <a href="#">M80-814_obsolete.pdf</a>  | 7th September 2018 | M80-8413442         | <a href="#">M80-841.pdf</a>     |
| M80-8144405                     | <a href="#">M80-814_obsolete.pdf</a>  | 7th September 2018 | M80-8414445         | <a href="#">M80-841.pdf</a>     |
| M80-8144422                     | <a href="#">M80-814_obsolete.pdf</a>  | 7th September 2018 | M80-8414442         | <a href="#">M80-841.pdf</a>     |
| M80-8150405                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8540445         | <a href="#">M80-854.pdf</a>     |
| M80-8150422                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8540442         | <a href="#">M80-854.pdf</a>     |
| M80-8150605                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8540645         | <a href="#">M80-854.pdf</a>     |
| M80-8150622                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8540642         | <a href="#">M80-854.pdf</a>     |
| M80-8150805                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8540845         | <a href="#">M80-854.pdf</a>     |
| M80-8150822                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8540842         | <a href="#">M80-854.pdf</a>     |
| M80-8151005                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8541045         | <a href="#">M80-854.pdf</a>     |
| M80-8151022                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8541042         | <a href="#">M80-854.pdf</a>     |
| M80-8151205                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8541245         | <a href="#">M80-854.pdf</a>     |
| M80-8151222                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8541242         | <a href="#">M80-854.pdf</a>     |
| M80-8151405                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8541445         | <a href="#">M80-854.pdf</a>     |
| M80-8151422                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8541442         | <a href="#">M80-854.pdf</a>     |
| M80-8151605                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8541645         | <a href="#">M80-854.pdf</a>     |
| M80-8151622                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8541642         | <a href="#">M80-854.pdf</a>     |
| M80-8151805                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8541845         | <a href="#">M80-854.pdf</a>     |
| M80-8151822                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8541842         | <a href="#">M80-854.pdf</a>     |
| M80-8152005                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8542045         | <a href="#">M80-854.pdf</a>     |
| M80-8152022                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8542042         | <a href="#">M80-854.pdf</a>     |
| M80-8152605                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8542645         | <a href="#">M80-854.pdf</a>     |
| M80-8152622                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8542642         | <a href="#">M80-854.pdf</a>     |
| M80-8153405                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8543445         | <a href="#">M80-854.pdf</a>     |
| M80-8153422                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8543442         | <a href="#">M80-854.pdf</a>     |
| M80-8154405                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8544445         | <a href="#">M80-854.pdf</a>     |
| M80-8154422                     | <a href="#">M80-815_obsolete.pdf</a>  | 7th September 2018 | M80-8544442         | <a href="#">M80-854.pdf</a>     |
| M80-8160405                     | <a href="#">M80-816_obsolete.pdf</a>  | 7th September 2018 | M80-8120405         | <a href="#">M80-812.pdf</a>     |
| M80-8160605                     | <a href="#">M80-816_obsolete.pdf</a>  | 7th September 2018 | M80-8120605         | <a href="#">M80-812.pdf</a>     |
| M80-8160805                     | <a href="#">M80-816_obsolete.pdf</a>  | 7th September 2018 | M80-8120805         | <a href="#">M80-812.pdf</a>     |
| M80-8161005                     | <a href="#">M80-816_obsolete.pdf</a>  | 7th September 2018 | M80-8121005         | <a href="#">M80-812.pdf</a>     |
| M80-8161205                     | <a href="#">M80-816_obsolete.pdf</a>  | 7th September 2018 | M80-8121205         | <a href="#">M80-812.pdf</a>     |
| M80-8170405                     | <a href="#">M80-817_obsolete.pdf</a>  | 7th September 2018 | M80-8130405         | <a href="#">M80-813.pdf</a>     |
| M80-8170605                     | <a href="#">M80-817_obsolete.pdf</a>  | 7th September 2018 | M80-8130605         | <a href="#">M80-813.pdf</a>     |
| M80-8171205                     | <a href="#">M80-817_obsolete.pdf</a>  | 7th September 2018 | M80-8131205         | <a href="#">M80-813.pdf</a>     |
| M80-8270422P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8260442P        | <a href="#">M80-826P.pdf</a>    |
| M80-8270442                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8260442         | <a href="#">M80-826.pdf</a>     |
| M80-8270442P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8260442P        | <a href="#">M80-826P.pdf</a>    |
| M80-8270445                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8260445         | <a href="#">M80-826.pdf</a>     |
| M80-8270445P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8260445P        | <a href="#">M80-826P.pdf</a>    |
| M80-8270622                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8260642         | <a href="#">M80-826.pdf</a>     |
| M80-8270622P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8260642P        | <a href="#">M80-826P.pdf</a>    |
| M80-8270642                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8260642         | <a href="#">M80-826.pdf</a>     |
| M80-8270642P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8260642P        | <a href="#">M80-826P.pdf</a>    |

## Obsolete Product Notification from Harwin

| Part number being made obsolete | Drawing for obsolete product          | Last Time buy date | Alternative product | Drawing for alternative product |
|---------------------------------|---------------------------------------|--------------------|---------------------|---------------------------------|
| M80-8270645                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8260645         | <a href="#">M80-826.pdf</a>     |
| M80-8270645P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8260645P        | <a href="#">M80-826P.pdf</a>    |
| M80-8270822                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8260842         | <a href="#">M80-826.pdf</a>     |
| M80-8270822P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8260842P        | <a href="#">M80-826P.pdf</a>    |
| M80-8270842                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8260842         | <a href="#">M80-826.pdf</a>     |
| M80-8270842P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8260842P        | <a href="#">M80-826P.pdf</a>    |
| M80-8270845                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8260845         | <a href="#">M80-826.pdf</a>     |
| M80-8270845P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8260845P        | <a href="#">M80-826P.pdf</a>    |
| M80-8271022                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8261042         | <a href="#">M80-826.pdf</a>     |
| M80-8271022P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8261042P        | <a href="#">M80-826P.pdf</a>    |
| M80-8271042                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8261042         | <a href="#">M80-826.pdf</a>     |
| M80-8271042P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8261042P        | <a href="#">M80-826P.pdf</a>    |
| M80-8271045                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8261045         | <a href="#">M80-826.pdf</a>     |
| M80-8271045P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8261045P        | <a href="#">M80-826P.pdf</a>    |
| M80-8271222                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8261242         | <a href="#">M80-826.pdf</a>     |
| M80-8271222P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8261242P        | <a href="#">M80-826P.pdf</a>    |
| M80-8271242                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8261242         | <a href="#">M80-826.pdf</a>     |
| M80-8271242P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8261242P        | <a href="#">M80-826P.pdf</a>    |
| M80-8271245                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8261245         | <a href="#">M80-826.pdf</a>     |
| M80-8271245P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8261245P        | <a href="#">M80-826P.pdf</a>    |
| M80-8271422                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8261442         | <a href="#">M80-826.pdf</a>     |
| M80-8271422P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8261442P        | <a href="#">M80-826P.pdf</a>    |
| M80-8271442                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8261442         | <a href="#">M80-826.pdf</a>     |
| M80-8271442P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8261442P        | <a href="#">M80-826P.pdf</a>    |
| M80-8271445                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8261445         | <a href="#">M80-826.pdf</a>     |
| M80-8271445P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8261445P        | <a href="#">M80-826P.pdf</a>    |
| M80-8271622P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8261642P        | <a href="#">M80-826P.pdf</a>    |
| M80-8271642                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8261642         | <a href="#">M80-826.pdf</a>     |
| M80-8271642P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8261642P        | <a href="#">M80-826P.pdf</a>    |
| M80-8271645                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8261645         | <a href="#">M80-826.pdf</a>     |
| M80-8271645P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8261645P        | <a href="#">M80-826P.pdf</a>    |
| M80-8271822P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8261842P        | <a href="#">M80-826P.pdf</a>    |
| M80-8271842                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8261842         | <a href="#">M80-826.pdf</a>     |
| M80-8271842P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8261842P        | <a href="#">M80-826P.pdf</a>    |
| M80-8271845                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8261845         | <a href="#">M80-826.pdf</a>     |
| M80-8271845P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8261845P        | <a href="#">M80-826P.pdf</a>    |
| M80-8272022                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8262042         | <a href="#">M80-826.pdf</a>     |
| M80-8272022P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8262042P        | <a href="#">M80-826P.pdf</a>    |
| M80-8272042                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8262042         | <a href="#">M80-826.pdf</a>     |
| M80-8272042P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8262042P        | <a href="#">M80-826P.pdf</a>    |
| M80-8272045                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8262045         | <a href="#">M80-826.pdf</a>     |
| M80-8272045P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8262045P        | <a href="#">M80-826P.pdf</a>    |
| M80-8272622P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8262642P        | <a href="#">M80-826P.pdf</a>    |
| M80-8272642                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8262642         | <a href="#">M80-826.pdf</a>     |
| M80-8272642P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8262642P        | <a href="#">M80-826P.pdf</a>    |
| M80-8272645                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8262645         | <a href="#">M80-826.pdf</a>     |
| M80-8272645P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8262645P        | <a href="#">M80-826P.pdf</a>    |
| M80-8273422P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8263442P        | <a href="#">M80-826P.pdf</a>    |
| M80-8273442                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8263442         | <a href="#">M80-826.pdf</a>     |
| M80-8273442P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8263442P        | <a href="#">M80-826P.pdf</a>    |
| M80-8273445                     | <a href="#">M80-827_obsolete.pdf</a>  | 7th September 2018 | M80-8263445         | <a href="#">M80-826.pdf</a>     |
| M80-8273445P                    | <a href="#">M80-827P_obsolete.pdf</a> | 7th September 2018 | M80-8263445P        | <a href="#">M80-826P.pdf</a>    |
| M80-8350222                     | <a href="#">M80-835_obsolete.pdf</a>  | 7th September 2018 | M80-8370242         | <a href="#">M80-837.pdf</a>     |
| M80-8350242                     | <a href="#">M80-835_obsolete.pdf</a>  | 7th September 2018 | M80-8370242         | <a href="#">M80-837.pdf</a>     |
| M80-8350245                     | <a href="#">M80-835_obsolete.pdf</a>  | 7th September 2018 | M80-8370245         | <a href="#">M80-837.pdf</a>     |
| M80-8350322                     | <a href="#">M80-835_obsolete.pdf</a>  | 7th September 2018 | M80-8370342         | <a href="#">M80-837.pdf</a>     |
| M80-8350342                     | <a href="#">M80-835_obsolete.pdf</a>  | 7th September 2018 | M80-8370342         | <a href="#">M80-837.pdf</a>     |

## Obsolete Product Notification from Harwin

| Part number being made obsolete | Drawing for obsolete product         | Last Time buy date | Alternative product | Drawing for alternative product |
|---------------------------------|--------------------------------------|--------------------|---------------------|---------------------------------|
| M80-8350345                     | <a href="#">M80-835_obsolete.pdf</a> | 7th September 2018 | M80-8370345         | <a href="#">M80-837.pdf</a>     |
| M80-8350442                     | <a href="#">M80-835_obsolete.pdf</a> | 7th September 2018 | M80-8370442         | <a href="#">M80-837.pdf</a>     |
| M80-8350445                     | <a href="#">M80-835_obsolete.pdf</a> | 7th September 2018 | M80-8370445         | <a href="#">M80-837.pdf</a>     |
| M80-8350522                     | <a href="#">M80-835_obsolete.pdf</a> | 7th September 2018 | M80-8370542         | <a href="#">M80-837.pdf</a>     |
| M80-8350542                     | <a href="#">M80-835_obsolete.pdf</a> | 7th September 2018 | M80-8370542         | <a href="#">M80-837.pdf</a>     |
| M80-8350545                     | <a href="#">M80-835_obsolete.pdf</a> | 7th September 2018 | M80-8370545         | <a href="#">M80-837.pdf</a>     |
| M80-8350622                     | <a href="#">M80-835_obsolete.pdf</a> | 7th September 2018 | M80-8370642         | <a href="#">M80-837.pdf</a>     |
| M80-8350642                     | <a href="#">M80-835_obsolete.pdf</a> | 7th September 2018 | M80-8370642         | <a href="#">M80-837.pdf</a>     |
| M80-8350645                     | <a href="#">M80-835_obsolete.pdf</a> | 7th September 2018 | M80-8370645         | <a href="#">M80-837.pdf</a>     |
| M80-8350722                     | <a href="#">M80-835_obsolete.pdf</a> | 7th September 2018 | M80-8370742         | <a href="#">M80-837.pdf</a>     |
| M80-8350742                     | <a href="#">M80-835_obsolete.pdf</a> | 7th September 2018 | M80-8370742         | <a href="#">M80-837.pdf</a>     |
| M80-8350745                     | <a href="#">M80-835_obsolete.pdf</a> | 7th September 2018 | M80-8370745         | <a href="#">M80-837.pdf</a>     |
| M80-8351722                     | <a href="#">M80-835_obsolete.pdf</a> | 7th September 2018 | M80-8371742         | <a href="#">M80-837.pdf</a>     |
| M80-8351742                     | <a href="#">M80-835_obsolete.pdf</a> | 7th September 2018 | M80-8371742         | <a href="#">M80-837.pdf</a>     |
| M80-8351745                     | <a href="#">M80-835_obsolete.pdf</a> | 7th September 2018 | M80-8371745         | <a href="#">M80-837.pdf</a>     |
| M80-8352222                     | <a href="#">M80-835_obsolete.pdf</a> | 7th September 2018 | M80-8372242         | <a href="#">M80-837.pdf</a>     |
| M80-8352242                     | <a href="#">M80-835_obsolete.pdf</a> | 7th September 2018 | M80-8372242         | <a href="#">M80-837.pdf</a>     |
| M80-8352245                     | <a href="#">M80-835_obsolete.pdf</a> | 7th September 2018 | M80-8372245         | <a href="#">M80-837.pdf</a>     |
| M80-8390422                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8410442         | <a href="#">M80-841.pdf</a>     |
| M80-8390442                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8410442         | <a href="#">M80-841.pdf</a>     |
| M80-8390445                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8410445         | <a href="#">M80-841.pdf</a>     |
| M80-8390622                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8410642         | <a href="#">M80-841.pdf</a>     |
| M80-8390642                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8410642         | <a href="#">M80-841.pdf</a>     |
| M80-8390645                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8410645         | <a href="#">M80-841.pdf</a>     |
| M80-8390822                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8410842         | <a href="#">M80-841.pdf</a>     |
| M80-8390842                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8410842         | <a href="#">M80-841.pdf</a>     |
| M80-8390845                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8410845         | <a href="#">M80-841.pdf</a>     |
| M80-8391022                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8411042         | <a href="#">M80-841.pdf</a>     |
| M80-8391042                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8411042         | <a href="#">M80-841.pdf</a>     |
| M80-8391045                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8411045         | <a href="#">M80-841.pdf</a>     |
| M80-8391222                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8411242         | <a href="#">M80-841.pdf</a>     |
| M80-8391242                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8411242         | <a href="#">M80-841.pdf</a>     |
| M80-8391245                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8411245         | <a href="#">M80-841.pdf</a>     |
| M80-8391422                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8411442         | <a href="#">M80-841.pdf</a>     |
| M80-8391442                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8411442         | <a href="#">M80-841.pdf</a>     |
| M80-8391445                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8411445         | <a href="#">M80-841.pdf</a>     |
| M80-8391622                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8411642         | <a href="#">M80-841.pdf</a>     |
| M80-8391642                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8411642         | <a href="#">M80-841.pdf</a>     |
| M80-8391645                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8411645         | <a href="#">M80-841.pdf</a>     |
| M80-8391822                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8411842         | <a href="#">M80-841.pdf</a>     |
| M80-8391842                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8411842         | <a href="#">M80-841.pdf</a>     |
| M80-8391845                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8411845         | <a href="#">M80-841.pdf</a>     |
| M80-8392022                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8412042         | <a href="#">M80-841.pdf</a>     |
| M80-8392042                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8412042         | <a href="#">M80-841.pdf</a>     |
| M80-8392045                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8412045         | <a href="#">M80-841.pdf</a>     |
| M80-8392622                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8412642         | <a href="#">M80-841.pdf</a>     |
| M80-8392642                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8412642         | <a href="#">M80-841.pdf</a>     |
| M80-8392645                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8412645         | <a href="#">M80-841.pdf</a>     |
| M80-8393422                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8413442         | <a href="#">M80-841.pdf</a>     |
| M80-8393442                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8413442         | <a href="#">M80-841.pdf</a>     |
| M80-8393445                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8413445         | <a href="#">M80-841.pdf</a>     |
| M80-8394422                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8414442         | <a href="#">M80-841.pdf</a>     |
| M80-8394442                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8414442         | <a href="#">M80-841.pdf</a>     |
| M80-8394445                     | <a href="#">M80-839_obsolete.pdf</a> | 7th September 2018 | M80-8414445         | <a href="#">M80-841.pdf</a>     |
| M80-8460222                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8430242         | <a href="#">M80-843.pdf</a>     |
| M80-8460242                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8430242         | <a href="#">M80-843.pdf</a>     |
| M80-8460245                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8430245         | <a href="#">M80-843.pdf</a>     |

## Obsolete Product Notification from Harwin

| Part number being made obsolete | Drawing for obsolete product         | Last Time buy date | Alternative product | Drawing for alternative product |
|---------------------------------|--------------------------------------|--------------------|---------------------|---------------------------------|
| M80-8460322                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8430342         | <a href="#">M80-843.pdf</a>     |
| M80-8460342                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8430342         | <a href="#">M80-843.pdf</a>     |
| M80-8460345                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8430345         | <a href="#">M80-843.pdf</a>     |
| M80-8460422                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8430442         | <a href="#">M80-843.pdf</a>     |
| M80-8460442                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8430442         | <a href="#">M80-843.pdf</a>     |
| M80-8460445                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8430445         | <a href="#">M80-843.pdf</a>     |
| M80-8460522                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8430542         | <a href="#">M80-843.pdf</a>     |
| M80-8460542                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8430542         | <a href="#">M80-843.pdf</a>     |
| M80-8460545                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8430545         | <a href="#">M80-843.pdf</a>     |
| M80-8460622                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8430642         | <a href="#">M80-843.pdf</a>     |
| M80-8460642                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8430642         | <a href="#">M80-843.pdf</a>     |
| M80-8460645                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8430645         | <a href="#">M80-843.pdf</a>     |
| M80-8460722                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8430742         | <a href="#">M80-843.pdf</a>     |
| M80-8460742                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8430742         | <a href="#">M80-843.pdf</a>     |
| M80-8460745                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8430745         | <a href="#">M80-843.pdf</a>     |
| M80-8461722                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8431742         | <a href="#">M80-843.pdf</a>     |
| M80-8461742                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8431742         | <a href="#">M80-843.pdf</a>     |
| M80-8461745                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8431745         | <a href="#">M80-843.pdf</a>     |
| M80-8462222                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8432242         | <a href="#">M80-843.pdf</a>     |
| M80-8462242                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8432242         | <a href="#">M80-843.pdf</a>     |
| M80-8462245                     | <a href="#">M80-846_obsolete.pdf</a> | 7th September 2018 | M80-8432245         | <a href="#">M80-843.pdf</a>     |
| M80-8630422                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8540442         | <a href="#">M80-854.pdf</a>     |
| M80-8630442                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8540442         | <a href="#">M80-854.pdf</a>     |
| M80-8630445                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8540445         | <a href="#">M80-854.pdf</a>     |
| M80-8630622                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8540642         | <a href="#">M80-854.pdf</a>     |
| M80-8630642                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8540642         | <a href="#">M80-854.pdf</a>     |
| M80-8630645                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8540645         | <a href="#">M80-854.pdf</a>     |
| M80-8630822                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8540842         | <a href="#">M80-854.pdf</a>     |
| M80-8630842                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8540842         | <a href="#">M80-854.pdf</a>     |
| M80-8630845                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8540845         | <a href="#">M80-854.pdf</a>     |
| M80-8631022                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8541042         | <a href="#">M80-854.pdf</a>     |
| M80-8631042                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8541042         | <a href="#">M80-854.pdf</a>     |
| M80-8631045                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8541045         | <a href="#">M80-854.pdf</a>     |
| M80-8631222                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8541242         | <a href="#">M80-854.pdf</a>     |
| M80-8631242                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8541242         | <a href="#">M80-854.pdf</a>     |
| M80-8631245                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8541245         | <a href="#">M80-854.pdf</a>     |
| M80-8631422                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8541442         | <a href="#">M80-854.pdf</a>     |
| M80-8631442                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8541442         | <a href="#">M80-854.pdf</a>     |
| M80-8631445                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8541445         | <a href="#">M80-854.pdf</a>     |
| M80-8631622                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8541642         | <a href="#">M80-854.pdf</a>     |
| M80-8631642                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8541642         | <a href="#">M80-854.pdf</a>     |
| M80-8631645                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8541645         | <a href="#">M80-854.pdf</a>     |
| M80-8631822                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8541842         | <a href="#">M80-854.pdf</a>     |
| M80-8631842                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8541842         | <a href="#">M80-854.pdf</a>     |
| M80-8631845                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8541845         | <a href="#">M80-854.pdf</a>     |
| M80-8632022                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8542042         | <a href="#">M80-854.pdf</a>     |
| M80-8632042                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8542042         | <a href="#">M80-854.pdf</a>     |
| M80-8632045                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8542045         | <a href="#">M80-854.pdf</a>     |
| M80-8632622                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8542642         | <a href="#">M80-854.pdf</a>     |
| M80-8632642                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8542642         | <a href="#">M80-854.pdf</a>     |
| M80-8632645                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8542645         | <a href="#">M80-854.pdf</a>     |
| M80-8633422                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8543442         | <a href="#">M80-854.pdf</a>     |
| M80-8633442                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8543442         | <a href="#">M80-854.pdf</a>     |
| M80-8633445                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8543445         | <a href="#">M80-854.pdf</a>     |
| M80-8634422                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8544442         | <a href="#">M80-854.pdf</a>     |
| M80-8634442                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8544442         | <a href="#">M80-854.pdf</a>     |
| M80-8634445                     | <a href="#">M80-863_obsolete.pdf</a> | 7th September 2018 | M80-8544445         | <a href="#">M80-854.pdf</a>     |

## Obsolete Product Notification from Harwin

| Part number being made obsolete | Drawing for obsolete product         | Last Time buy date | Alternative product          | Drawing for alternative product |
|---------------------------------|--------------------------------------|--------------------|------------------------------|---------------------------------|
| M80-8810222                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520242                  | <a href="#">M80-852.pdf</a>     |
| M80-8810242                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520242                  | <a href="#">M80-852.pdf</a>     |
| M80-8810245                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520245                  | <a href="#">M80-852.pdf</a>     |
| M80-8810322                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520342                  | <a href="#">M80-852.pdf</a>     |
| M80-8810342                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520342                  | <a href="#">M80-852.pdf</a>     |
| M80-8810422                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520442                  | <a href="#">M80-852.pdf</a>     |
| M80-8810442                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520442                  | <a href="#">M80-852.pdf</a>     |
| M80-8810445                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520445                  | <a href="#">M80-852.pdf</a>     |
| M80-8810522                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520542                  | <a href="#">M80-852.pdf</a>     |
| M80-8810542                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520542                  | <a href="#">M80-852.pdf</a>     |
| M80-8810545                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520545                  | <a href="#">M80-852.pdf</a>     |
| M80-8810622                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520642                  | <a href="#">M80-852.pdf</a>     |
| M80-8810642                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520642                  | <a href="#">M80-852.pdf</a>     |
| M80-8810645                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520645                  | <a href="#">M80-852.pdf</a>     |
| M80-8810722                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520742                  | <a href="#">M80-852.pdf</a>     |
| M80-8810742                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520742                  | <a href="#">M80-852.pdf</a>     |
| M80-8810745                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8520745                  | <a href="#">M80-852.pdf</a>     |
| M80-8811722                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8521742                  | <a href="#">M80-852.pdf</a>     |
| M80-8811742                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8521742                  | <a href="#">M80-852.pdf</a>     |
| M80-8811745                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8521745                  | <a href="#">M80-852.pdf</a>     |
| M80-8812222                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8522242                  | <a href="#">M80-852.pdf</a>     |
| M80-8812242                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8522242                  | <a href="#">M80-852.pdf</a>     |
| M80-8812245                     | <a href="#">M80-881_obsolete.pdf</a> | 7th September 2018 | M80-8522245                  | <a href="#">M80-852.pdf</a>     |
| M80-8830205                     | <a href="#">M80-883_obsolete.pdf</a> | 7th September 2018 | M80-8080205                  | <a href="#">M80-808.pdf</a>     |
| M80-8830305                     | <a href="#">M80-883_obsolete.pdf</a> | 7th September 2018 | M80-8080305                  | <a href="#">M80-808.pdf</a>     |
| M80-8830405                     | <a href="#">M80-883_obsolete.pdf</a> | 7th September 2018 | M80-8080405                  | <a href="#">M80-808.pdf</a>     |
| M80-8830505                     | <a href="#">M80-883_obsolete.pdf</a> | 7th September 2018 | M80-8080505                  | <a href="#">M80-808.pdf</a>     |
| M80-8830605                     | <a href="#">M80-883_obsolete.pdf</a> | 7th September 2018 | M80-8080605                  | <a href="#">M80-808.pdf</a>     |
| M80-8830705                     | <a href="#">M80-883_obsolete.pdf</a> | 7th September 2018 | M80-8080705                  | <a href="#">M80-808.pdf</a>     |
| M80-8840205                     | <a href="#">M80-884_obsolete.pdf</a> | 7th September 2018 | M80-8090205                  | <a href="#">M80-809.pdf</a>     |
| M80-8840305                     | <a href="#">M80-884_obsolete.pdf</a> | 7th September 2018 | M80-8090305                  | <a href="#">M80-809.pdf</a>     |
| M80-8840405                     | <a href="#">M80-884_obsolete.pdf</a> | 7th September 2018 | M80-8090405                  | <a href="#">M80-809.pdf</a>     |
| M80-8840505                     | <a href="#">M80-884_obsolete.pdf</a> | 7th September 2018 | M80-8090505                  | <a href="#">M80-809.pdf</a>     |
| M80-8840605                     | <a href="#">M80-884_obsolete.pdf</a> | 7th September 2018 | M80-8090605                  | <a href="#">M80-809.pdf</a>     |
| M80-8840705                     | <a href="#">M80-884_obsolete.pdf</a> | 7th September 2018 | M80-8090705                  | <a href="#">M80-809.pdf</a>     |
| M80C108489C-04                  | Contact technical@harwin.com         | 7th September 2018 | Contact technical@harwin.com |                                 |
| M80C108489C-06                  | Contact technical@harwin.com         | 7th September 2018 | Contact technical@harwin.com |                                 |
| M80C108489C-08                  | Contact technical@harwin.com         | 7th September 2018 | Contact technical@harwin.com |                                 |
| M80C108489C-10                  | Contact technical@harwin.com         | 7th September 2018 | Contact technical@harwin.com |                                 |
| M80C108489C-12                  | Contact technical@harwin.com         | 7th September 2018 | Contact technical@harwin.com |                                 |
| M80C108489C-14                  | Contact technical@harwin.com         | 7th September 2018 | Contact technical@harwin.com |                                 |
| M80C108489C-16                  | Contact technical@harwin.com         | 7th September 2018 | Contact technical@harwin.com |                                 |
| M80C108489C-18                  | Contact technical@harwin.com         | 7th September 2018 | Contact technical@harwin.com |                                 |
| M80C108489C-20                  | Contact technical@harwin.com         | 7th September 2018 | Contact technical@harwin.com |                                 |
| M80C108489C-26                  | Contact technical@harwin.com         | 7th September 2018 | Contact technical@harwin.com |                                 |
| M80C108489C-34                  | Contact technical@harwin.com         | 7th September 2018 | Contact technical@harwin.com |                                 |
| M80C108489C-44                  | Contact technical@harwin.com         | 7th September 2018 | Contact technical@harwin.com |                                 |
| M80C109272C                     | Contact technical@harwin.com         | 7th September 2018 | Contact technical@harwin.com |                                 |
| M80C150147C                     | Contact technical@harwin.com         | 7th September 2018 | Contact technical@harwin.com |                                 |