## **Product Termination Notification**

October 22, 2024

Product Termination Notification #: 20241022T Subject: Lumileds announces product termination for ...

#### Overview

Lumileds is announcing the discontinuation of its LUXEON HL2X-Standard, HL2X-P, HL2X-D products. At this time, Lumileds is ready to proceed with the end of life for this product. The details and supporting documents are attached below.

Description of Change(s):	Product termination notification for LUXEON HL2X-Standard, HL2X-P, HL2X-D
Customer Impact and Recommended Actions:	Customer will no longer able to order these products after last order date. HL2X-E and HL2X-V are alternate replacement parts.
Products affected:	LUXEON HL2X-Standard, HL2X-P, HL2X-D
Reference Documents/Attachments:	Attachment A: Affected Part Number
Customer part number(s), if applicable:	See Attachment A for Affected Lumileds part numbers
Last order date, if necessary, of obsolesced product	14 January 2025
	*Lumileds reserves the right to accept orders subject to materials availability
Last ship date, if necessary, of obsolesced product	6 May 2025

### **Next Steps**

As a next step, please provide acknowledgement of receipt of this PTN and provide feedback along with any additional requests to your Lumileds Account Manager or Quality Manager no later than (effective date + 1 month).

#### Contact:

If you have any questions, or need any further assistance, please contact your Lumileds sales representative.

# **Attachments**

## **Attachment A: Affected part numbers**

L1HX-2770200000000		
L1HX-27702D0000000		
L1HX-27702P0000000		
L1HX-3070200000000		
L1HX-30702000BAY20		
L1HX-30702000LAJS0		
L1HX-30702D0000000		
L1HX-30702D0000320		
L1HX-30702D00BBR20		
L1HX-30702D00LANL0		
L1HX-30702P0000000		
L1HX-30702P00BBB40		
L1HX-3570200000000		
L1HX-35702D0000000		
L1HX-35702P0000000		
L1HX-4070200000000		
L1HX-40702000BAY20		
L1HX-40702000BBM20		
L1HX-40702000BBM30		
L1HX-40702000LAJS0		
L1HX-40702D0000000		
L1HX-40702D0000340		
L1HX-40702D00BBR20		
L1HX-40702D00LANL0		
L1HX-40702P0000000		
L1HX-40702P0000001		
L1HX-40702P00BBB20		
L1HX-40702P00LAMB0		
L1HX-5070200000000		
L1HX-50702000BAY20		
L1HX-50702D0000000		
L1HX-50702D00BBR20		
L1HX-50702P0000000		

L1HX-50702P0000001		
L1HX-5770200000000		
L1HX-57702D0000000		
L1HX-57702D0000340		
L1HX-57702D00BBR20		
L1HX-57702P0000000		
L1HX-6570200000000		
L1HX-65702000LAJS0		
L1HX-6570220000000		
L1HX-65702D0000000		
L1HX-65702D0000340		
L1HX-65702P0000000		
L1HX-18802D0000000		
L1HX-2780200000000		
L1HX-27802000LALN0		
L1HX-27802000LAMF0		
L1HX-27802000LARH0		
L1HX-3080200000000		
L1HX-30802000LALA0		
L1HX-30802000LALN0		
L1HX-30802000LAMF0		
L1HX-30802000LARH0		
L1HX-30802D0000000		
L1HX-30802P0000000		
L1HX-3580200000000		
L1HX-35802000LAMF0		
L1HX-4080200000000		
L1HX-40802000LALN0		
L1HX-40802000LALX0		
L1HX-40802000LAMF0		
L1HX-40802000LARH0		
L1HX-40802D0000000		
L1HX-40802P0000000		

L1HX-5080200000000
L1HX-50802000BBS20
L1HX-50802000LALA0
L1HX-50802D0000000
L1HX-50802D00LANM0
L1HX-50802P0000000
L1HX-5780200000000
L1HX-57802000BAY20
L1HX-57802D0000000
L1HX-57802P0000000
L1HX-2790200000000
L1HX-27902000LAMF0
L1HX-27902000LANF0
L1HX-3090200000000
L1HX-30902000LAMF0
L1HX-30902000LANF0
L1HX-30902D0000000
L1HX-30902P0000000
L1HX-3590200000000
L1HX-35902000LAMF0
L1HX-35902000LANF0
L1HX-4090200000000
L1HX-40902000LAMF0
L1HX-40902000LANF0
L1HX-40902D0000000
L1HX-40902P0000000
L1HX-5090200000000
L1HX-5790200000000
L1HX-57902D0000000
L1HX-57902P0000000
L1HX-2795200000000
L1HX-6595200000000

### **Attachment B: Replacement Option**

Part number	Replacement PN
L1HX-xxxx20xxxxxxx	L1HX-xxxx2Vxxxxxxx
L1HX-xxxx2Dxxxxxxx	L1HX-xxxx2Exxxxxxx
L1HX-xxxx2Pxxxxxxx	L1HX-xxxx2Exxxxxxx

The table above shows the closest match for the discontinued part numbers. Not all the discontinued part numbers have direct replacement. Please contact your Lumileds Sales representative if you need futher assistance