

Engineering/Process Change Notice

ECN/PCN No.: 4671

For Manufacturer					
Product Description:	Abracon Part Numbe	r / Part Series:	☐ Documentation only	⊠ Series	
Clam Shell Sockets	AXS	5	☐ ECN	☐ Part Number	
			⊠ EOL		
Affected Revision:	New Revision:		Application:	☐ Safety	
N/A	EOL	-		⋈ Non-Safety	
Prior to Change:					
Active AXS series					
After Change:					
EOL (Please see list in page 2)					
Cause/Reason for Change:					
Discontinuation of manufacturing capability.					
	Chang	e Plan			
Effective Date:	Additional Remarks:				
6/14/2023					
Change Declaration:					
Issued Date:	Issued By:		Issued Department:		
6/14/2023	Stephanie Lopez		Engineering		
Approval:	Approval:		Approval:		
Thomas Culhane	Reuben Quintanilla		Ying Huang		
Engineering Director	Quality Director		Purchasing Director		
For Abracon EOL only					
Last Time Buy (if applicable): None	Alternate Part Numb		per / Part Series: N/A		
Additional Approval:	Additional Approval:		Additional Approval:		
Customer Approval (If Applicable)					
Qualification Status:					
☐ Approved ☐ Not accepted					
Note: It is considered approved if there is no feedback from the customer 1 month after ECN/PCN is released.					
Customer Part Number:	Customer Project:				
Company Name:	Company Representative:		Representative Signature:		
Customer Remarks:		,			

Form #7020 | Rev. G | Effective: 02/22/2021 |













AXS-3225-04-06
AXS-2016-04-04
AXS-7050-04-01
AXS-2012-02-04
AXS-5032-04-02
AXS-7550-06-03
AXS-5032-04-04
AXS-2520-04-09
AXS-3215-02-01
AXS-3215-02-05
AXS-4918-02-11
AXS-3225-04-12
AXS-7050-04-12
AXS-3030-06-03
AXS-2520-04-01
AXS-7050-04-02
AXS-1612-04-01C
AXS-3225-04-10
AXS-3838-08-01
AXS-7050-06-13
AXS-3225-04-05
AXS-5032-06-08
AXS-2520-04-08
AXS-5032-04-06
AXS-3225-04-02
AXS-3225-04-04

AXS-1147-02-02 AXS-3838-06-01 AXS-3225-04-01 AXS-5032-02-06 AXS-5032-04-12 AXS-7550-06-05 AXS-5032-06-02 AXS-2016-04-04C AXS-1155-04-01 AXS-2520-04-05 AXS-3225-02-01 AXS-3225-04-07 AXS-3225-04-08 AXS-7050-04-17 AXS-8045-02-04 AXS-2520-04-07 AXS-5032-04-07 AXS-7050-06-07 AXS-2520-04-10 AXS-2520-04-11 AXS-1610-02-00	
AXS-3225-04-01 AXS-5032-02-06 AXS-5032-04-12 AXS-7550-06-05 AXS-5032-06-02 AXS-2016-04-04C AXS-1155-04-01 AXS-2520-04-05 AXS-3225-02-01 AXS-3225-04-07 AXS-3225-04-08 AXS-7050-04-17 AXS-8045-02-04 AXS-5032-04-07 AXS-5032-04-07 AXS-7050-06-07 AXS-2520-04-10 AXS-2520-04-11	AXS-1147-02-02
AXS-5032-02-06 AXS-5032-04-12 AXS-7550-06-05 AXS-5032-06-02 AXS-2016-04-04C AXS-1155-04-01 AXS-2520-04-05 AXS-3225-02-01 AXS-3225-04-07 AXS-3225-04-08 AXS-7050-04-17 AXS-8045-02-04 AXS-5032-04-07 AXS-5032-04-07 AXS-7050-06-07 AXS-2520-04-10 AXS-2520-04-11	AXS-3838-06-01
AXS-5032-04-12 AXS-7550-06-05 AXS-5032-06-02 AXS-2016-04-04C AXS-1155-04-01 AXS-2520-04-05 AXS-3225-02-01 AXS-3225-04-07 AXS-3225-04-08 AXS-7050-04-17 AXS-8045-02-04 AXS-2520-04-07 AXS-7050-06-07 AXS-2520-04-10 AXS-2520-04-11	AXS-3225-04-01
AXS-7550-06-05 AXS-5032-06-02 AXS-2016-04-04C AXS-1155-04-01 AXS-2520-04-05 AXS-3225-02-01 AXS-3225-04-07 AXS-3225-04-08 AXS-4115-02-06 AXS-7050-04-17 AXS-8045-02-04 AXS-5032-04-07 AXS-5032-04-07 AXS-7050-06-07 AXS-2520-04-10 AXS-2520-04-11	AXS-5032-02-06
AXS-5032-06-02 AXS-2016-04-04C AXS-1155-04-01 AXS-2520-04-05 AXS-3225-02-01 AXS-3225-04-07 AXS-3225-04-08 AXS-4115-02-06 AXS-7050-04-17 AXS-8045-02-04 AXS-5032-04-07 AXS-5032-04-07 AXS-7050-06-07 AXS-2520-04-10 AXS-2520-04-11	AXS-5032-04-12
AXS-2016-04-04C AXS-1155-04-01 AXS-2520-04-05 AXS-3225-02-01 AXS-3225-04-07 AXS-3225-04-08 AXS-4115-02-06 AXS-7050-04-17 AXS-8045-02-04 AXS-2520-04-07 AXS-7050-06-07 AXS-2520-04-10 AXS-2520-04-11	AXS-7550-06-05
AXS-1155-04-01 AXS-2520-04-05 AXS-3225-02-01 AXS-3225-04-07 AXS-3225-04-08 AXS-4115-02-06 AXS-7050-04-17 AXS-8045-02-04 AXS-2520-04-07 AXS-5032-04-07 AXS-7050-06-07 AXS-2520-04-10 AXS-2520-04-11	AXS-5032-06-02
AXS-2520-04-05 AXS-3225-02-01 AXS-3225-04-07 AXS-3225-04-08 AXS-4115-02-06 AXS-7050-04-17 AXS-8045-02-04 AXS-2520-04-07 AXS-7050-06-07 AXS-7050-06-07 AXS-2520-04-10 AXS-2520-04-11	AXS-2016-04-04C
AXS-3225-02-01 AXS-3225-04-07 AXS-3225-04-08 AXS-4115-02-06 AXS-7050-04-17 AXS-8045-02-04 AXS-2520-04-07 AXS-7050-06-07 AXS-7050-06-07 AXS-2520-04-10 AXS-2520-04-11	AXS-1155-04-01
AXS-3225-04-07 AXS-3225-04-08 AXS-4115-02-06 AXS-7050-04-17 AXS-8045-02-04 AXS-2520-04-07 AXS-7050-06-07 AXS-7050-06-07 AXS-2520-04-10 AXS-2520-04-11	AXS-2520-04-05
AXS-3225-04-08 AXS-4115-02-06 AXS-7050-04-17 AXS-8045-02-04 AXS-2520-04-07 AXS-5032-04-07 AXS-7050-06-07 AXS-2520-04-10 AXS-2520-04-11	AXS-3225-02-01
AXS-4115-02-06 AXS-7050-04-17 AXS-8045-02-04 AXS-2520-04-07 AXS-5032-04-07 AXS-7050-06-07 AXS-2520-04-10 AXS-2520-04-11	AXS-3225-04-07
AXS-7050-04-17 AXS-8045-02-04 AXS-2520-04-07 AXS-5032-04-07 AXS-7050-06-07 AXS-2520-04-10 AXS-2520-04-11	AXS-3225-04-08
AXS-8045-02-04 AXS-2520-04-07 AXS-5032-04-07 AXS-7050-06-07 AXS-2520-04-10 AXS-2520-04-11	AXS-4115-02-06
AXS-2520-04-07 AXS-5032-04-07 AXS-7050-06-07 AXS-2520-04-10 AXS-2520-04-11	AXS-7050-04-17
AXS-5032-04-07 AXS-7050-06-07 AXS-2520-04-10 AXS-2520-04-11	AXS-8045-02-04
AXS-7050-06-07 AXS-2520-04-10 AXS-2520-04-11	AXS-2520-04-07
AXS-2520-04-10 AXS-2520-04-11	AXS-5032-04-07
AXS-2520-04-11	AXS-7050-06-07
	AXS-2520-04-10
AXS-1610-02-00	AXS-2520-04-11
	AXS-1610-02-00