




# PRODUCT OBSOLESCENCE MEMO

## RESISTORS



## Select Bourns® Surface Mount Wirewound Resistors to be Discontinued

### Model PWR2010W, PWR2615W, PWR4318W, PWR4525W & PWR5322W Series

Riverside, California – February 23, 2024 - In accordance with our ongoing product life cycle management procedure, effective July 31, 2024, Bourns will transfer the Model [PWR2010W](#), [PWR2615W](#), [PWR4318W](#), [PWR4525W](#) and [PWR5322W](#) Series Surface Mount Wirewound Resistors to an End of Product Life status. A shortage of raw materials necessitates this action. A list of obsolete and replacement part numbers\* is included on page 2.

Customers may continue to purchase these part numbers during the End of Product Life transition period between now and July 31, 2024. Orders for these part numbers during this End of Product Life transition period will be considered noncancellable. Products purchased during this End of Product Life transition period will be considered nonreturnable and will be covered by Bourns' standard warranty.

#### Please plan for the following deadlines:

Last time buy date: **July 31, 2024**

Last time ship date: **December 31, 2024**

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

*\*In April 2023, Bourns acquired substantially all of the assets of Riedon, Inc. The replacement part numbers listed in this Product Obsolescence Memo, solely for ease of customer transition, currently maintain the part number designations previously used by Riedon, Inc. As of the date of this memo, these replacement parts can be ordered on [Riedon.com](#), through Bourns' authorized distributor, [DigiKey](#), or by contacting [Bourns Customer Service/Inside Sales](#).*

N2402

Obsolete Part Numbers	Replacement Part Numbers*
PWR2010W1001FE	No replacement
PWR2615WR005J	S2-R005J
PWR2615WR005JE	S2-R005J
PWR2615WR010F	S2-R010F
PWR2615WR010FE	S2-R010F
PWR2615WR010J	S2-R010J
PWR2615WR010JE	S2-R010J
PWR2615WR015F	S2-R015F
PWR2615WR015FE	S2-R015F
PWR2615WR015J	S2-R015J
PWR2615WR015JE	S2-R015J
PWR2615WR020F	S2-R020F
PWR2615WR020FE	S2-R020F
PWR2615WR020J	S2-R020J
PWR2615WR020JE	S2-R020J
PWR2615WR024J	S2-R024J

Obsolete Part Numbers	Replacement Part Numbers*
PWR2615WR024JE	S2-R024J
PWR2615WR027J	S2-R027J
PWR2615WR027JE	S2-R027J
PWR2615WR030F	S2-R030F
PWR2615WR030FE	S2-R030F
PWR2615WR030J	S2-R030J
PWR2615WR030JE	S2-R030J
PWR2615WR033F	S2-R033F
PWR2615WR033FE	S2-R033F
PWR2615WR036J	S2-R036J
PWR2615WR036JE	S2-R036J
PWR2615WR039F	S2-R039F
PWR2615WR039FE	S2-R039F
PWR2615WR047F	S2-R047F
PWR2615WR047FE	S2-R047F
PWR2615WR050FE	S2-R050F

Obsolete Part Numbers	Replacement Part Numbers*
PWR2615WR050J	S2-R050J
PWR2615WR050JE	S2-R050J
PWR4318W6801F	No replacement
PWR4525W1202JE	S4-12K0J
PWR4525W1502J	S4-15K0J
PWR4525W1502JE	S4-15K0J
PWR4525WR000J	No replacement
PWR4525WR000JE	No replacement
PWR4525WR005J	No replacement
PWR4525WR005JE	No replacement
PWR4525WR010J	S4-R010J
PWR4525WR010JE	S4-R010J
PWR4525WR015J	S4-R015J
PWR4525WR015JE	S4-R015J
PWR4525WR018F	S4-R018F
PWR4525WR020J	S4-R020J

Obsolete Part Numbers	Replacement Part Numbers*
PWR4525WR020JE	S4-R020J
PWR4525WR024J	S4-R024J
PWR4525WR024JE	S4-R024J
PWR4525WR027J	S4-R027J
PWR4525WR027JE	S4-R027J
PWR4525WR030J	S4-R030J
PWR4525WR030JE	S4-R030J
PWR4525WR036J	S4-R036J
PWR4525WR036JE	S4-R036J
PWR4525WR047JE	S4-R047J
PWR4525WR050J	S4-R050J
PWR4525WR050JE	S4-R050J
PWR5322W1502JE	No replacement

\*In April 2023, Bourns acquired substantially all of the assets of Riedon, Inc. The replacement part numbers listed in this Product Obsolescence Memo, solely for ease of customer transition, currently maintain the part number designations previously used by Riedon, Inc. As of the date of this memo, these replacement parts can be ordered on [Riedon.com](http://Riedon.com), through Bourns' authorized distributor, [DigiKey](https://www.digikey.com), or by contacting [Bourns Customer Service/Inside Sales](mailto:CustomerService@bourns.com).