



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 96138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

PCN #: A0807-02 DATE: July 31, 2008 Product Affected: 300 mil SSOP 48, 56 150 mil SOIC 8, 14, 16 300 mil SOIC 16, 18, 20, 24, 28, 32 4.4 mm TSSOP 8, 14, 16, 20, 24, 28 6.1 mm TSSOP 48, 56, 64 Date Effective: October 31, 2008	MEANS OF DISTINGUISHING CHANGED DEVICES: <input type="checkbox"/> Product Mark <input checked="" type="checkbox"/> Back Mark Lot # will have a "Y" suffix <input type="checkbox"/> Date Code <input type="checkbox"/> Other
---	---

Contact: Geoffrey Cortes Title: Product Quality Phone #: (408) 284-8321 Fax #: (408) 284-1450 E-mail: Geoffrey.Cortes@idt.com	Attachment: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Samples: Contact your local IDT sales representative for sample requests.
---	--

DESCRIPTION AND PURPOSE OF CHANGE:

<input type="checkbox"/> Die Technology <input type="checkbox"/> Wafer Fabrication Process <input type="checkbox"/> Assembly Process <input type="checkbox"/> Equipment <input checked="" type="checkbox"/> Material <input type="checkbox"/> Testing <input type="checkbox"/> Manufacturing Site <input type="checkbox"/> Data Sheet <input type="checkbox"/> Other	<p>This notification is to advise our customers that IDT is evaluating Copper Bond Wire for 300 mil SSOP 48, 56, 150 mil SOIC 8, 14, 16, 300 mil SOIC 16, 18, 20, 24, 28, 32, 4.4 mm TSSOP 8, 14, 16, 20, 24, 28 and 6.1 mm TSSOP 48, 56, 64 at OSET, Taiwan ; OSEP, Philippines ; ATP, Philippines ; Unisem, Indonesia ; UTL, Thailand and plans to ship product assembled with copper bond wire process in October 2008.</p> <p>A follow-up notification with complete qualification data will be sent prior to first customer shipment.</p> <p>Attachment 1 outlines the qualification plans and results. Attachment 2 shows all the affected part numbers, except 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia. Attachment 2a shows the affected part numbers on 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.</p>
--	--

RELIABILITY/QUALIFICATION SUMMARY:

There is no expected change to the product quality or reliability performance.

CUSTOMER ACKNOWLEDGMENT OF RECEIPT:

IDT records indicate that you require written notification of this change. Please use the acknowledgement below or E-Mail to grant approval or request additional information. If IDT does not receive acknowledgement within 30 days of this notice it will be assumed that this change is acceptable.

IDT reserves the right to ship either version manufactured after the process change effective date until the inventory on the earlier version has been depleted.

Customer: _____	<input type="checkbox"/> <i>Approval for shipments prior to effective date.</i>
Name/Date: _____	E-Mail Address: _____
Title: _____	Phone# /Fax# : _____

CUSTOMER COMMENTS: _____

IDT ACKNOWLEDGMENT OF RECEIPT:

RECD. BY: _____ DATE: _____



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 96138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT 1 - PCN # : A0807-02

PCN Type: Assembly Material Change - Gold wire to Copper wire

Data Sheet Change: None

Detail Of Change:

This notification is to advise our customers that IDT is evaluating Copper Bond Wire for 300 mil SSOP 48, 56, 150 mil SOIC 8, 14, 16, 300 mil SOIC 16, 18, 20, 24, 28, 32, 4.4 mm TSSOP 8, 14, 16, 20, 24, 28 and 6.1 mm TSSOP 48, 56, 64 at OSET, Taiwan ; OSEP, Philippines ; ATP, Philippines ; Unisem, Indonesia ; UTL, Thailand and plans to ship copper bond wire process in October 2008.

Copper bond process is presently used by selective semiconductor suppliers due to the following key advantages:

- A. Better electrical performance- higher current handling capability - 18% improvement in resistance for 1 mil bond wire.
- B. Better high temperature bake performance. Minimal intermettalic compound build up.
- C. Higher Ball shear and wire pull test result- smaller bond pad real estate is now possible.
- D. Stiffer Wire- minimize wire swaying , longer wires than gold is now possible.

IDT has already successfully qualified Copper wire bond process and has shipped million of units assembled at Carsem, Malaysia for VFQFP-N-72 (PCN# A0709-02R1), and Unisem, Indonesia for VFQFP-N-64, 72, 6.1 mm TSSOP 56, 64 (PCN# A0802-01R1).

Attachment 1 - outlines the qualification plans and results.

Attachment 2 - shows all the affected part numbers, except 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

Attachment 2a - shows the affected part numbers on 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

A follow-up notification with complete qualification data will be sent prior to first customer shipment.

Customers may expect to receive shipments with Cu wire process no sooner than 90 days from the date of this notification, July 31, 2008. Product assembled with Au and Cu wire will be shipped during the transition period or until the Au wire inventory has been depleted. Please note that product assembled with Au and Cu wire will not be mixed in one tray stack, or tape and reel.

We request you acknowledge receipt of this notification with the 30 days of the date of this PCN notification. If you require samples to conduct and evaluation, please make your sample request within 30 days as samples are not built ahead of the change for all device options. You may contact your local sales representative to acknowledge this PCN and request samples.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 96138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT 1 - PCN # : A0807-02

	Samples Availability	Production Shipments
Package Family :	300 mil SSOP	Now
	150 mil SOIC	Now
	300 mil SOIC	Now
	4.4 mm TSSOP	Now
	6.1 mm TSSOP	Now

Assembly Material : The material set used in assembly is in compliance with ROHS 6 (green products) and ROHS 5 (standard products) requirement.

Sample Availability : Samples are not built ahead of the change for all device types and may not be available for all affected device types.

Please contact your local IDT sales representative for your sample request and availability.

Qualification Test Result :

The following tests were successfully completed for TSSOP package family. Test results for SSOP and SOIC will be advised upon qualification completions.

Test Description	Test Method	TSSOP	SSOP	SOIC
		Test Results (SS / Rej)	Test Results (SS / Rej)	Test Results (SS / Rej)
* High Accelerated Stress Test (Biased, 130 °C/85% RH, 100 Hrs)	JESD22-A110-B	45/0	Expected completion date September 2008	Expected completion date September 2008
* Temperature Cycle / Condition B (-55 °C to +125 °C, 1000 Cyc)	JESD22-A104-B	45/0		
High Temp. Storage (150 °C, 1000 Hrs)	JESD22-A103-B	¹ 76/0		
Ball Shear Test	JESD22-B116	5/0		
Bond Pull Test	IDT Spec, MAC-3010	5/0		
X-ray Examination	IDT Spec, MAC-3012	45/0		

Note:

* Test requires moisture pre-conditioning sequence per JESD22-A113C and will use the existing moisture sensitivity level that has been qualified for this material set.

¹ 1 unit mechanical reject - broken lead.

ATTACHMENT 2 - PCN # : A0807-02

Affected Part Number, except 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

ICS25210AG	IDT74ALVCH162245PAG8	IDT74ALVCH16901PAG8	IDT74CBTLV3245PG
ICS25210AGT	IDT74ALVCH162373PA	IDT74ALVCH16903PA	IDT74CBTLV3245PG8
IDT71256SA12SOG1	IDT74ALVCH162373PA8	IDT74ALVCH16903PA8	IDT74CBTLV3245PGG
IDT71256SA12SOG18	IDT74ALVCH162373PAG	IDT74ALVCH16903PAG	IDT74CBTLV3245PGG8
IDT71256SA15SOG1	IDT74ALVCH162373PAG8	IDT74ALVCH16903PAG8	IDT74CBTLV3251PG
IDT71256SA15SOG18	IDT74ALVCH162373PV	IDT74ALVCHR162245PA	IDT74CBTLV3251PG8
IDT71256SA20SOG1	IDT74ALVCH162373PV8	IDT74ALVCHR162245PA8	IDT74CBTLV3251PGG
IDT71256SA20SOG18	IDT74ALVCH162373PVG	IDT74ALVCHR162245PAG	IDT74CBTLV3251PGG8
IDT71256SA35SOG1	IDT74ALVCH162373PVG8	IDT74ALVCHR162245PAG8	IDT74CBTLV3253PGG
IDT71256SA35SOG18	IDT74ALVCH162374PA	IDT74ALVCHR16601PA	IDT74CBTLV3253PGG8
IDT71256SA55SOG1	IDT74ALVCH162374PA8	IDT74ALVCHR16601PA8	IDT74CBTLV3257PG
IDT71256SA55SOG18	IDT74ALVCH162374PAG	IDT74ALVCHR16601PAG	IDT74CBTLV3257PG8
IDT71256SA55SOGI	IDT74ALVCH162374PAG8	IDT74ALVCHR16601PAG8	IDT74CBTLV3257PGG
IDT71256SA55SOGI8	IDT74ALVCH16244PA	IDT74CBTLV16210PA	IDT74CBTLV3257PGG8
IDT74ALVC162244PA	IDT74ALVCH16244PA8	IDT74CBTLV16210PA8	IDT74CBTLV3384PG
IDT74ALVC162244PA8	IDT74ALVCH16244PAG	IDT74CBTLV16210PAG	IDT74CBTLV3384PG8
IDT74ALVC162244PAG	IDT74ALVCH16244PAG8	IDT74CBTLV16210PAG8	IDT74CBTLV3384PGG
IDT74ALVC162244PAG8	IDT74ALVCH16245PA	IDT74CBTLV16211PA	IDT74CBTLV3384PGG8
IDT74ALVC162245PA	IDT74ALVCH16245PA8	IDT74CBTLV16211PA8	IDT74CBTLV3861PG
IDT74ALVC162245PA8	IDT74ALVCH16245PAG	IDT74CBTLV16211PAG	IDT74CBTLV3861PG8
IDT74ALVC162245PAG	IDT74ALVCH16245PAG8	IDT74CBTLV16211PAG8	IDT74CBTLV3861PGG
IDT74ALVC162245PAG8	IDT74ALVCH16245PV8/C	IDT74CBTLV16212PA	IDT74CBTLV3861PGG8
IDT74ALVC162334PA	IDT74ALVCH16260PA	IDT74CBTLV16212PA8	IDT74CBTLV3862PG
IDT74ALVC162334PA8	IDT74ALVCH16260PA8	IDT74CBTLV16212PAG	IDT74CBTLV3862PG8
IDT74ALVC162334PAG	IDT74ALVCH16260PAG	IDT74CBTLV16212PAG8	IDT74CBTLV3862PGG
IDT74ALVC162334PAG8	IDT74ALVCH16260PAG8	IDT74CBTLV16245PA	IDT74CBTLV3862PGG8
IDT74ALVC16244APA	IDT74ALVCH162820PA	IDT74CBTLV16245PA8	IDT74CBTLV6800PG
IDT74ALVC16244APA8	IDT74ALVCH162820PA8	IDT74CBTLV16245PAG	IDT74CBTLV6800PG8
IDT74ALVC16244APAG	IDT74ALVCH162820PAG	IDT74CBTLV16245PAG8	IDT74CBTLV6800PGG
IDT74ALVC16244APAG8	IDT74ALVCH162820PAG8	IDT74CBTLV16292PA	IDT74CBTLV6800PGG8
IDT74ALVC16245PA	IDT74ALVCH16501PA	IDT74CBTLV16292PA8	IDT74FCT157ATSO
IDT74ALVC16245PA8	IDT74ALVCH16501PA8	IDT74CBTLV16292PAG	IDT74FCT157ATSO8
IDT74ALVC16245PAG	IDT74ALVCH16501PAG	IDT74CBTLV16292PAG8	IDT74FCT157ATSO8
IDT74ALVC16245PAG8	IDT74ALVCH16501PAG8	IDT74CBTLV16800PA	IDT74FCT157ATSO8
IDT74ALVC164245PA	IDT74ALVCH16501PV	IDT74CBTLV16800PA8	IDT74FCT157CTSO
IDT74ALVC164245PA8	IDT74ALVCH16501PV8	IDT74CBTLV16800PAG	IDT74FCT157CTSO8
IDT74ALVC164245PAG	IDT74ALVCH16501PVG	IDT74CBTLV16800PAG8	IDT74FCT157CTSO8/E
IDT74ALVC164245PAG8	IDT74ALVCH16501PVG8	IDT74CBTLV16800PV	IDT74FCT157CTSO8
IDT74ALVC164245PV	IDT74ALVCH16721PA	IDT74CBTLV16800PV8	IDT74FCT157CTSO8
IDT74ALVC164245PV8	IDT74ALVCH16721PA8	IDT74CBTLV16800PVG	IDT74FCT157DTSO
IDT74ALVC164245PVG	IDT74ALVCH16721PAG	IDT74CBTLV16800PVG8	IDT74FCT157DTSO8
IDT74ALVC164245PVG8	IDT74ALVCH16721PAG8	IDT74CBTLV3125PG	IDT74FCT157DTSO8
IDT74ALVCH162244PA	IDT74ALVCH16823PA	IDT74CBTLV3125PG8	IDT74FCT157DTSO8
IDT74ALVCH162244PA8	IDT74ALVCH16823PA8	IDT74CBTLV3125PGG	IDT74FCT162244ATPA
IDT74ALVCH162244PAG	IDT74ALVCH16823PAG	IDT74CBTLV3125PGG8	IDT74FCT162244ATPA8
IDT74ALVCH162244PAG8	IDT74ALVCH16823PAG8	IDT74CBTLV3126PG	IDT74FCT162244ATPAG
IDT74ALVCH162244PV	IDT74ALVCH16863PA	IDT74CBTLV3126PG8	IDT74FCT162244ATPAG8
IDT74ALVCH162244PV8	IDT74ALVCH16863PA8	IDT74CBTLV3126PGG	IDT74FCT162244ATPV
IDT74ALVCH162244PVG	IDT74ALVCH16863PAG	IDT74CBTLV3126PGG8	IDT74FCT162244ATPV8
IDT74ALVCH162244PVG8	IDT74ALVCH16863PAG8	IDT74CBTLV3244PG	IDT74FCT162244ATPV8
IDT74ALVCH162245PA	IDT74ALVCH16901PA	IDT74CBTLV3244PG8	IDT74FCT162244ATPV8
IDT74ALVCH162245PA8	IDT74ALVCH16901PA8	IDT74CBTLV3244PGG	IDT74FCT162244CTPA
IDT74ALVCH162245PAG	IDT74ALVCH16901PAG	IDT74CBTLV3244PGG8	IDT74FCT162244CTPA8

ATTACHMENT 2 - PCN # : A0807-02

Affected Part Number, except 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

IDT74FCT162244CTPAG	IDT74FCT162373ETPVG8	IDT74FCT16245CTPVG	IDT74FCT162823ATPAG8
IDT74FCT162244CTPAG8	IDT74FCT162374ATPA	IDT74FCT16245CTPVG8	IDT74FCT162823ATPV
IDT74FCT162244CTPV	IDT74FCT162374ATPA8	IDT74FCT16245ETPA	IDT74FCT162823ATPV8
IDT74FCT162244CTPV8	IDT74FCT162374ATPAG	IDT74FCT16245ETPA8	IDT74FCT162823ATPVG
IDT74FCT162244CTPVG	IDT74FCT162374ATPAG8	IDT74FCT16245ETPAG	IDT74FCT162823ATPVG8
IDT74FCT162244CTPVG8	IDT74FCT162374ATPV	IDT74FCT16245ETPAG8	IDT74FCT162823CTPA
IDT74FCT162244ETPA	IDT74FCT162374ATPV8	IDT74FCT16245ETPV	IDT74FCT162823CTPA8
IDT74FCT162244ETPA8	IDT74FCT162374ATPVG	IDT74FCT16245ETPV8	IDT74FCT162823CTPAG
IDT74FCT162244ETPAG	IDT74FCT162374ATPVG8	IDT74FCT16245ETPVG	IDT74FCT162823CTPAG8
IDT74FCT162244ETPAG8	IDT74FCT162374CTPA	IDT74FCT16245ETPVG8	IDT74FCT162823CTPV
IDT74FCT162244ETPV	IDT74FCT162374CTPA8	IDT74FCT162500ATPV	IDT74FCT162823CTPV8
IDT74FCT162244ETPV8	IDT74FCT162374CTPAG	IDT74FCT162500ATPV8	IDT74FCT162823CTPVG
IDT74FCT162244ETPVG	IDT74FCT162374CTPAG8	IDT74FCT162500ATPVG	IDT74FCT162823CTPVG8
IDT74FCT162244ETPVG8	IDT74FCT162374CTPV	IDT74FCT162500ATPVG8	IDT74FCT162827ATPA
IDT74FCT162245ATPA	IDT74FCT162374CTPV8	IDT74FCT162500CTPV	IDT74FCT162827ATPA8
IDT74FCT162245ATPA8	IDT74FCT162374CTPVG	IDT74FCT162500CTPV8	IDT74FCT162827ATPAG
IDT74FCT162245ATPAG	IDT74FCT162374CTPVG8	IDT74FCT162500CTPVG	IDT74FCT162827ATPAG8
IDT74FCT162245ATPAG8	IDT74FCT162374ETPA	IDT74FCT162500CTPVG8	IDT74FCT162827ATPV
IDT74FCT162245ATPV	IDT74FCT162374ETPA8	IDT74FCT162501ATPA	IDT74FCT162827ATPV8
IDT74FCT162245ATPV8	IDT74FCT162374ETPAG	IDT74FCT162501ATPA8	IDT74FCT162827ATPVG
IDT74FCT162245ATPVG	IDT74FCT162374ETPAG8	IDT74FCT162501ATPAG	IDT74FCT162827ATPVG8
IDT74FCT162245ATPVG8	IDT74FCT162374ETPV	IDT74FCT162501ATPAG8	IDT74FCT162827CTPA
IDT74FCT162245CTPA	IDT74FCT162374ETPV8	IDT74FCT162501ATPV	IDT74FCT162827CTPA8
IDT74FCT162245CTPA8	IDT74FCT162374ETPVG	IDT74FCT162501ATPV8	IDT74FCT162827CTPAG
IDT74FCT162245CTPAG	IDT74FCT162374ETPVG8	IDT74FCT162501ATPVG	IDT74FCT162827CTPAG8
IDT74FCT162245CTPAG8	IDT74FCT16244ATPA	IDT74FCT162501ATPVG8	IDT74FCT162827CTPV
IDT74FCT162245CTPV	IDT74FCT16244ATPA8	IDT74FCT162501CTPA	IDT74FCT162827CTPV8
IDT74FCT162245CTPV8	IDT74FCT16244ATPAG8	IDT74FCT162501CTPA8	IDT74FCT162827CTPV8/E
IDT74FCT162245CTPVG	IDT74FCT16244ATPAG8	IDT74FCT162501CTPAG	IDT74FCT162827CTPVG
IDT74FCT162245CTPVG8	IDT74FCT16244ATPV	IDT74FCT162501CTPAG8	IDT74FCT162827CTPVG8
IDT74FCT162260CTPVG	IDT74FCT16244ATPV8	IDT74FCT162501CTPV	IDT74FCT162H245ATPA
IDT74FCT162260CTPVG8	IDT74FCT16244ATPVG	IDT74FCT162501CTPV8	IDT74FCT162H245ATPA8
IDT74FCT162373ATPA	IDT74FCT16244ATPVG8	IDT74FCT162501CTPVG	IDT74FCT162H245ATPAG
IDT74FCT162373ATPA8	IDT74FCT16244CTPA	IDT74FCT162501CTPVG8	IDT74FCT162H245ATPAG8
IDT74FCT162373ATPAG	IDT74FCT16244CTPA8	IDT74FCT162511ATPA	IDT74FCT162H245ATPV
IDT74FCT162373ATPAG8	IDT74FCT16244CTPAG	IDT74FCT162511ATPA8	IDT74FCT162H245ATPV8
IDT74FCT162373ATPV	IDT74FCT16244CTPAG8	IDT74FCT162511ATPAG	IDT74FCT162H245ATPVG
IDT74FCT162373ATPV8	IDT74FCT16244CTPV	IDT74FCT162511ATPAG8	IDT74FCT162H245ATPVG8
IDT74FCT162373ATPVG	IDT74FCT16244CTPV8	IDT74FCT162511ATPV	IDT74FCT162H245CTPA
IDT74FCT162373ATPVG8	IDT74FCT16244CTPVG	IDT74FCT162511ATPV8	IDT74FCT162H245CTPA8
IDT74FCT162373CTPA	IDT74FCT16244CTPVG8	IDT74FCT162511ATPVG	IDT74FCT162H245CTPAG
IDT74FCT162373CTPA8	IDT74FCT16245ATPA	IDT74FCT162511ATPVG8	IDT74FCT162H245CTPAG8
IDT74FCT162373CTPAG	IDT74FCT16245ATPA8	IDT74FCT162511CTPA	IDT74FCT162H245CTPV
IDT74FCT162373CTPAG8	IDT74FCT16245ATPAG8	IDT74FCT162511CTPA8	IDT74FCT162H245CTPV8
IDT74FCT162373CTPV	IDT74FCT16245ATPAG8	IDT74FCT162511CTPAG	IDT74FCT162H245CTPVG
IDT74FCT162373CTPV8	IDT74FCT16245ATPV	IDT74FCT162511CTPAG8	IDT74FCT162H245CTPVG8
IDT74FCT162373CTPVG	IDT74FCT16245ATPV8	IDT74FCT162511CTPV	IDT74FCT162H501ATPV8C
IDT74FCT162373CTPVG8	IDT74FCT16245ATPVG	IDT74FCT162511CTPV8	IDT74FCT163244APA
IDT74FCT162373ETPA	IDT74FCT16245ATPVG8	IDT74FCT162511CTPVG	IDT74FCT163244APA8
IDT74FCT162373ETPA8	IDT74FCT16245CTPA	IDT74FCT162511CTPVG8	IDT74FCT163244APAG
IDT74FCT162373ETPAG	IDT74FCT16245CTPA8	IDT74FCT162646CTPVG	IDT74FCT163244APAG8
IDT74FCT162373ETPAG8	IDT74FCT16245CTPAG	IDT74FCT162646CTPVG8	IDT74FCT163244APV
IDT74FCT162373ETPV	IDT74FCT16245CTPAG8	IDT74FCT162823ATPA	IDT74FCT163244APV8
IDT74FCT162373ETPV8	IDT74FCT16245CTPV	IDT74FCT162823ATPA8	IDT74FCT163244APVG
IDT74FCT162373ETPVG	IDT74FCT16245CTPV8	IDT74FCT162823ATPAG	IDT74FCT163244APVG8

ATTACHMENT 2 - PCN # : A0807-02

Affected Part Number, except 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

IDT74FCT163244CPA	IDT74FCT163374CPA8	IDT74FCT164245TPAG	IDT74FCT16952ATPVG8
IDT74FCT163244CPA8	IDT74FCT163374CPAG	IDT74FCT164245TPAG8	IDT74FCT16952CTPA
IDT74FCT163244CPAG	IDT74FCT163374CPAG8	IDT74FCT164245TPV	IDT74FCT16952CTPA8
IDT74FCT163244CPAG8	IDT74FCT163374CPV	IDT74FCT164245TPV8	IDT74FCT16952CTPAG
IDT74FCT163244CPV	IDT74FCT163374CPV8	IDT74FCT164245TPVG	IDT74FCT16952CTPAG8
IDT74FCT163244CPV8	IDT74FCT163374CPVG	IDT74FCT164245TPVG8	IDT74FCT16952CTPV
IDT74FCT163244CPVG	IDT74FCT163374CPVG8	IDT74FCT16500ATPV	IDT74FCT16952CTPV8
IDT74FCT163244CPVG8	IDT74FCT16373ATPA	IDT74FCT16500ATPV8	IDT74FCT16952CTPVG
IDT74FCT163245APA	IDT74FCT16373ATPA8	IDT74FCT16500ATPVG	IDT74FCT16952CTPVG8
IDT74FCT163245APA8	IDT74FCT16373ATPAG	IDT74FCT16500ATPVG8	IDT74FCT16952CTPA
IDT74FCT163245APAG	IDT74FCT16373ATPAG8	IDT74FCT16500CTPV	IDT74FCT16952ETPA8
IDT74FCT163245APAG8	IDT74FCT16373ATPV	IDT74FCT16500CTPV8	IDT74FCT16952ETPAG
IDT74FCT163245APV	IDT74FCT16373ATPV8	IDT74FCT16500CTPVG	IDT74FCT16952ETPAG8
IDT74FCT163245APV8	IDT74FCT16373ATPVG	IDT74FCT16500CTPVG8	IDT74FCT16952ETPV
IDT74FCT163245APVG	IDT74FCT16373ATPVG8	IDT74FCT16501ATPA	IDT74FCT16952ETPV8
IDT74FCT163245APVG8	IDT74FCT16373CTPA	IDT74FCT16501ATPA8	IDT74FCT16952ETPVG
IDT74FCT163245CPA	IDT74FCT16373CTPA8	IDT74FCT16501ATPAG	IDT74FCT16952ETPVG8
IDT74FCT163245CPA8	IDT74FCT16373CTPAG	IDT74FCT16501ATPAG8	IDT74FCT2244ATSO
IDT74FCT163245CPAG	IDT74FCT16373CTPAG8	IDT74FCT16501CTPA	IDT74FCT2244ATSO8
IDT74FCT163245CPAG8	IDT74FCT16373CTPV	IDT74FCT16501CTPA8	IDT74FCT2244ATSOG
IDT74FCT163245CPV	IDT74FCT16373CTPV8	IDT74FCT16501CTPAG	IDT74FCT2244ATSOG8
IDT74FCT163245CPV8	IDT74FCT16373CTPVG	IDT74FCT16501CTPAG8	IDT74FCT2244CTSO
IDT74FCT163245CPVG	IDT74FCT16373CTPVG8	IDT74FCT16501CTPV8/E	IDT74FCT2244CTSO8
IDT74FCT163245CPVG8	IDT74FCT16374ATPA	IDT74FCT16543ATPAG	IDT74FCT2244CTSOG
IDT74FCT163344APA	IDT74FCT16374ATPA8	IDT74FCT16543ATPAG8	IDT74FCT2244CTSOG8
IDT74FCT163344APA8	IDT74FCT16374ATPAG	IDT74FCT16543ATPV	IDT74FCT2245ATSO
IDT74FCT163344APAG	IDT74FCT16374ATPAG8	IDT74FCT16543ATPV8	IDT74FCT2245ATSO8
IDT74FCT163344APAG8	IDT74FCT16374ATPV	IDT74FCT16543ATPVG	IDT74FCT2245ATSOG
IDT74FCT163344CPA	IDT74FCT16374ATPV8	IDT74FCT16543ATPVG8	IDT74FCT2245ATSOG8
IDT74FCT163344CPA8	IDT74FCT16374ATPVG	IDT74FCT16543CTPAG	IDT74FCT2245CTSO
IDT74FCT163344CPAG	IDT74FCT16374ATPVG8	IDT74FCT16543CTPAG8	IDT74FCT2245CTSO8
IDT74FCT163344CPAG8	IDT74FCT16374CTPA	IDT74FCT16543CTPV	IDT74FCT2245CTSOG
IDT74FCT163373APA	IDT74FCT16374CTPA8	IDT74FCT16543CTPV8	IDT74FCT2245CTSOG8
IDT74FCT163373APA8	IDT74FCT16374CTPAG	IDT74FCT16543CTPVG	IDT74FCT2373CTSO
IDT74FCT163373APAG	IDT74FCT16374CTPAG8	IDT74FCT16543CTPVG8	IDT74FCT2373CTSO8
IDT74FCT163373APAG8	IDT74FCT16374CTPV	IDT74FCT16543ETPAG	IDT74FCT240ATSO
IDT74FCT163373APV	IDT74FCT16374CTPV8	IDT74FCT16543ETPAG8	IDT74FCT240ATSO8
IDT74FCT163373APV8	IDT74FCT16374CTPVG	IDT74FCT16543ETPV	IDT74FCT240ATSOG
IDT74FCT163373APVG	IDT74FCT16374CTPVG8	IDT74FCT16543ETPV8	IDT74FCT240ATSOG8
IDT74FCT163373APVG8	IDT74FCT16374ETPA	IDT74FCT16543ETPVG	IDT74FCT240CTSO
IDT74FCT163373CPA	IDT74FCT16374ETPA8	IDT74FCT16543ETPVG8	IDT74FCT240CTSO8
IDT74FCT163373CPA8	IDT74FCT16374ETPAG	IDT74FCT166244ATPV	IDT74FCT240CTSOG
IDT74FCT163373CPAG	IDT74FCT16374ETPAG8	IDT74FCT166244ATPV8	IDT74FCT240CTSOG8
IDT74FCT163373CPAG8	IDT74FCT16374ETPV	IDT74FCT166244ATPVG	IDT74FCT244ATPG
IDT74FCT163373CPV	IDT74FCT16374ETPV8	IDT74FCT166244ATPVG8	IDT74FCT244ATPG8
IDT74FCT163373CPV8	IDT74FCT16374ETPVG	IDT74FCT166244CTPV	IDT74FCT244ATPGG
IDT74FCT163373CPVG	IDT74FCT16374ETPVG8	IDT74FCT166244CTPV8	IDT74FCT244ATPGG8
IDT74FCT163373CPVG8	IDT74FCT163827APA	IDT74FCT166244CTPV8/E	IDT74FCT244ATSO
IDT74FCT163374APA	IDT74FCT163827APA8	IDT74FCT166244CTPVG	IDT74FCT244ATSO8
IDT74FCT163374APA8	IDT74FCT163827APAG	IDT74FCT166244CTPVG8	IDT74FCT244ATSOG
IDT74FCT163374APAG	IDT74FCT163827APAG8	IDT74FCT16952ATPA	IDT74FCT244ATSOG8
IDT74FCT163374APAG8	IDT74FCT163827CPA	IDT74FCT16952ATPA8	IDT74FCT244CTPG
IDT74FCT163374APV	IDT74FCT163827CPA8	IDT74FCT16952ATPAG	IDT74FCT244CTPG8
IDT74FCT163374APV8	IDT74FCT163827CPAG	IDT74FCT16952ATPAG8	IDT74FCT244CTPGG
IDT74FCT163374APVG	IDT74FCT163827CPAG8	IDT74FCT16952ATPV	IDT74FCT244CTPGG8
IDT74FCT163374APVG8	IDT74FCT164245TPA	IDT74FCT16952ATPV8	IDT74FCT244CTSO
IDT74FCT163374CPA	IDT74FCT164245TPA8	IDT74FCT16952ATPVG	IDT74FCT244CTSO8

ATTACHMENT 2 - PCN # : A0807-02

Affected Part Number, except 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

IDT74FCT244CTSO	IDT74FCT373ATSO	IDT74FCT543DTSOG	IDT74FST6800PGG8
IDT74FCT244CTSOG8	IDT74FCT373ATSO8	IDT74FCT543DTSOG8	IDT74LVC162244APA
IDT74FCT245ATPG	IDT74FCT373ATSOG	IDT74FCT573ATSO	IDT74LVC162244APA8
IDT74FCT245ATPG8	IDT74FCT373ATSOG8	IDT74FCT573ATSO8	IDT74LVC162244APAG
IDT74FCT245ATPGG	IDT74FCT373CTSO	IDT74FCT573ATSOG	IDT74LVC162244APAG8
IDT74FCT245ATPGG8	IDT74FCT373CTSO8	IDT74FCT573ATSOG8	IDT74LVC162244APV
IDT74FCT245ATSO	IDT74FCT373CTSOG	IDT74FCT573CTSO	IDT74LVC162244APV8
IDT74FCT245ATSO8	IDT74FCT373CTSOG8	IDT74FCT573CTSO8	IDT74LVC162244APVG
IDT74FCT245ATSOG	IDT74FCT374ATSO	IDT74FCT573CTSOG	IDT74LVC162244APVG8
IDT74FCT245ATSOG8	IDT74FCT374ATSO8	IDT74FCT573CTSOG8	IDT74LVC162245APA
IDT74FCT245CTPG	IDT74FCT374ATSOG	IDT74FCT574ATSO	IDT74LVC162245APA8
IDT74FCT245CTPG8	IDT74FCT374ATSOG8	IDT74FCT574ATSO8	IDT74LVC162245APAG
IDT74FCT245CTPGG	IDT74FCT374CTSO	IDT74FCT574ATSOG	IDT74LVC162245APAG8
IDT74FCT245CTPGG8	IDT74FCT374CTSO8	IDT74FCT574ATSOG8	IDT74LVC162245APV
IDT74FCT245CTSO	IDT74FCT374CTSOG	IDT74FCT574CTSO	IDT74LVC162245APV8
IDT74FCT245CTSO8	IDT74FCT374CTSOG8	IDT74FCT574CTSO8	IDT74LVC162245APVG
IDT74FCT245CTSOG	IDT74FCT377ATSO	IDT74FCT574CTSOG	IDT74LVC162245APVG8
IDT74FCT245CTSOG8	IDT74FCT377ATSO8	IDT74FCT574CTSOG8	IDT74LVC16244APA
IDT74FCT257ATSO	IDT74FCT377ATSOG	IDT74FCT621ATSO	IDT74LVC16244APA8
IDT74FCT257ATSO8	IDT74FCT377ATSOG8	IDT74FCT621ATSOG8	IDT74LVC16244APAG
IDT74FCT257ATSOG	IDT74FCT377CTSO	IDT74FCT621TSG	IDT74LVC16244APAG8
IDT74FCT257ATSOG8	IDT74FCT377CTSO8	IDT74FCT621TSG8	IDT74LVC16244APV
IDT74FCT257CTSO	IDT74FCT377CTSOG	IDT74FCT823ATSO	IDT74LVC16244APV8
IDT74FCT257CTSO8	IDT74FCT377CTSOG8	IDT74FCT823ATSO8	IDT74LVC16244APVG
IDT74FCT257CTSOG	IDT74FCT377DTSO	IDT74FCT823ATSOG	IDT74LVC16244APVG8
IDT74FCT257CTSOG8	IDT74FCT377DTSO8	IDT74FCT823ATSOG8	IDT74LVC16245APA
IDT74FCT257DTSO	IDT74FCT377DTSOG	IDT74FCT823CTSO	IDT74LVC16245APA8
IDT74FCT257DTSO8	IDT74FCT377DTSOG8	IDT74FCT823CTSO8	IDT74LVC16245APAG
IDT74FCT257DTSOG	IDT74FCT521ATSO	IDT74FCT823CTSOG	IDT74LVC16245APAG8
IDT74FCT257DTSOG8	IDT74FCT521ATSO8	IDT74FCT823CTSOG8	IDT74LVC16245APV
IDT74FCT3244APG	IDT74FCT521ATSOG	IDT74FCT827CTSO8/E	IDT74LVC16245APV8
IDT74FCT3244APG8	IDT74FCT521ATSOG8	IDT74FST163244PA	IDT74LVC16245APVG
IDT74FCT3244APGG	IDT74FCT521CTSO	IDT74FST163244PA8	IDT74LVC16245APVG8
IDT74FCT3244APGG8	IDT74FCT521CTSO8	IDT74FST163244PAG	IDT74LVC16344APA
IDT74FCT3244ASO	IDT74FCT521CTSOG	IDT74FST163244PAG8	IDT74LVC16344APA8
IDT74FCT3244ASO8	IDT74FCT521CTSOG8	IDT74FST163245PA	IDT74LVC16344APAG
IDT74FCT3244ASOG	IDT74FCT540ATSO	IDT74FST163245PA8	IDT74LVC16344APAG8
IDT74FCT3244ASOG8	IDT74FCT540ATSO8	IDT74FST163245PAG	IDT74LVC16344APV
IDT74FCT3244PG	IDT74FCT540ATSOG	IDT74FST163245PAG8	IDT74LVC16344APV8
IDT74FCT3244PG8	IDT74FCT540ATSOG8	IDT74FST1632861PA	IDT74LVC16344APVG
IDT74FCT3244PGG	IDT74FCT540CTSO	IDT74FST1632861PA8	IDT74LVC16344APVG8
IDT74FCT3244PGG8	IDT74FCT540CTSO8	IDT74FST1632861PAG	IDT74LVC16373APA
IDT74FCT3244SO	IDT74FCT540CTSOG	IDT74FST1632861PAG8	IDT74LVC16373APA8
IDT74FCT3244SO8	IDT74FCT540CTSOG8	IDT74FST32XL2384PA	IDT74LVC16373APAG
IDT74FCT3244SOG	IDT74FCT543ATSO	IDT74FST32XL2384PA8	IDT74LVC16373APAG8
IDT74FCT3244SOG8	IDT74FCT543ATSO8	IDT74FST32XL2384PAG	IDT74LVC16373APV
IDT74FCT3245APG	IDT74FCT543ATSOG	IDT74FST32XL2384PAG8	IDT74LVC16373APV8
IDT74FCT3245APG8	IDT74FCT543ATSOG8	IDT74FST32XL384PA	IDT74LVC16373APVG
IDT74FCT3245APGG	IDT74FCT543CTSO	IDT74FST32XL384PA8	IDT74LVC16373APVG8
IDT74FCT3245APGG8	IDT74FCT543CTSO8	IDT74FST32XL384PAG	IDT74LVC16374APA
IDT74FCT3245PG	IDT74FCT543CTSOG	IDT74FST32XL384PAG8	IDT74LVC16374APA8
IDT74FCT3245PG8	IDT74FCT543CTSOG8	IDT74FST6800PG	IDT74LVC16374APAG
IDT74FCT3245PGG	IDT74FCT543DTSO	IDT74FST6800PG8	IDT74LVC16374APAG8
IDT74FCT3245PGG8	IDT74FCT543DTSO8	IDT74FST6800PGG	IDT74LVC16374APV

ATTACHMENT 2 - PCN # : A0807-02

Affected Part Number, except 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

IDT74LVC16374APV8	IDT74LVC4245APGG	IDT74LVCH16245APAG8	ICS9107C-05CS08LFT
IDT74LVC16374APVG	IDT74LVC4245APGG8	IDT74LVCH16245APV	ICS9107C-05CS08T
IDT74LVC16374APVG8	IDT74LVC4245ASO	IDT74LVCH16245APV8	ICS9107C-05CS08T-MT0
IDT74LVC16501APA	IDT74LVC4245ASO8	IDT74LVCH16245APV8/C	ICS9107C-10CS08
IDT74LVC16501APAG8	IDT74LVC4245ASOG	IDT74LVCH16245APVG	ICS9107C-10CS08LF
IDT74LVC16501APAG	IDT74LVC4245ASOG8	IDT74LVCH16245APVG8	ICS9107C-10CS08LFT
IDT74LVC16501APAG8	IDT74LVCC3245APG	IDT74LVCH16373APA	ICS9107C-10CS08T
IDT74LVC16501APV	IDT74LVCC3245APG8	IDT74LVCH16373APA8	ICS9107C-17CS08
IDT74LVC16501APV8	IDT74LVCC3245APGG	IDT74LVCH16373APAG	ICS9107C-17CS08LF
IDT74LVC16501APVG	IDT74LVCC3245APGG8	IDT74LVCH16373APAG8	ICS9107C-17CS08LFT
IDT74LVC16501APVG8	IDT74LVCC3245ASO	IDT74LVCH16374APA	ICS9107C-17CS08T
IDT74LVC16601APA	IDT74LVCC3245ASO8	IDT74LVCH16374APA8	ICS9110-01CS14
IDT74LVC16601APAG8	IDT74LVCC3245ASOG	IDT74LVCH16374APAG	ICS9110-01CS14LF
IDT74LVC16601APAG	IDT74LVCC3245ASOG8	IDT74LVCH16374APAG8	ICS9110-01CS14LFT
IDT74LVC16601APAG8	IDT74LVCH162244APA	IDT74LVCH16374APV	ICS9110-01CS14T
IDT74LVC16601APV	IDT74LVCH162244APA8	IDT74LVCH16374APV8	ICS9110-01CS14T-A
IDT74LVC16601APV8	IDT74LVCH162244APAG	IDT74LVCH16374APVG	ICS9110-02CS14
IDT74LVC16601APVG	IDT74LVCH162244APAG8	IDT74LVCH16374APVG8	ICS9110-02CS14LF
IDT74LVC16601APVG8	IDT74LVCH162245APA	IDT74LVCH16543APA	ICS9110-02CS14LFT
IDT74LVC16823APA	IDT74LVCH162245APA8	IDT74LVCH16543APA8	ICS9110-02CS14T
IDT74LVC16823APAG8	IDT74LVCH162245APAG	IDT74LVCH16543APAG	ICS9110-02CS14T-DE0
IDT74LVC16823APAG	IDT74LVCH162245APAG8	IDT74LVCH16543APAG8	ICS9110-02CS14T-IB0
IDT74LVC16823APAG8	IDT74LVCH162245APV	IDT74LVCH16601APV	ICS9111M-04
IDT74LVC16823APV	IDT74LVCH162245APV8	IDT74LVCH16601APV8	ICS9111M-04T
IDT74LVC16823APV8	IDT74LVCH162245APVG	IDT74LVCH16601APVG	ICS9112AG-16
IDT74LVC16823APVG	IDT74LVCH162245APVG8	IDT74LVCH16601APVG8	ICS9112AG-16LF
IDT74LVC16823APVG8	IDT74LVCH162373APA	IDT74LVCH16646APA	ICS9112AG-16LFT
IDT74LVC16827APA	IDT74LVCH162373APA8	IDT74LVCH16646APA8	ICS9112AG-16T
IDT74LVC16827APAG8	IDT74LVCH162373APAG	IDT74LVCH16646APAG	ICS9112AG-26
IDT74LVC16827APAG	IDT74LVCH162373APAG8	IDT74LVCH16646APAG8	ICS9112AG-26LF
IDT74LVC16827APAG8	IDT74LVCH162373APV	IDT74LVCHR162245APA	ICS9112AG-26LFT
IDT74LVC244APG	IDT74LVCH162373APV8	IDT74LVCHR162245APA8	ICS9112AG-26T
IDT74LVC244APG8	IDT74LVCH162373APVG	IDT74LVCHR162245APAG	ICS9112AG-26T-INO
IDT74LVC244APGG	IDT74LVCH162373APVG8	IDT74LVCHR162245APAG8	ICS9112AG-27
IDT74LVC244APGG8	IDT74LVCH162374APA	IDT74LVCHR16646APA	ICS9112AG-27LF
IDT74LVC244ASO	IDT74LVCH162374APA8	IDT74LVCHR16646APA8	ICS9112AG-27LFT
IDT74LVC244ASO8	IDT74LVCH162374APAG	IDT74LVCHR16646APAG	ICS9112AG-27T
IDT74LVC244ASOG	IDT74LVCH162374APAG8	IDT74LVCHR16646APAG8	ICS9112AG-28
IDT74LVC244ASOG8	IDT74LVCH162374APV	IDT74LVCR162245APA	ICS9112AG-28T
IDT74LVC245APG	IDT74LVCH162374APV8	IDT74LVCR162245APA8	ICS9112AM-16
IDT74LVC245APG8	IDT74LVCH162374APVG	IDT74LVCR162245APAG	ICS9112AM-16LF
IDT74LVC245APGG	IDT74LVCH162374APVG8	IDT74LVCR162245APAG8	ICS9112AM-16LFT
IDT74LVC245APGG8	IDT74LVCH16244APA	IDT74LVCR162245APV	ICS9112AM-16LNT
IDT74LVC245ASO	IDT74LVCH16244APA8	IDT74LVCR162245APV8	ICS9112AM-16LNT-INO
IDT74LVC245ASO8	IDT74LVCH16244APAG	IDT74LVCR162245APVG	ICS9112AM-16T
IDT74LVC245ASOG	IDT74LVCH16244APAG8	IDT74LVCR162245APVG8	ICS9112AM-16T-IB0
IDT74LVC245ASOG8	IDT74LVCH16244APV	ICS9107C-03CS14	ICS9112AM-16T-INO
IDT74LVC273APG	IDT74LVCH16244APV8	ICS9107C-03CS14T	ICS9112AM-16TV0
IDT74LVC273APG8	IDT74LVCH16244APVG	ICS9107C-03CS14T-IB0	ICS9112AM-17
IDT74LVC273APGG	IDT74LVCH16244APVG8	ICS9107C-03CS14T-IB1	ICS9112AM-17LF
IDT74LVC273APGG8	IDT74LVCH16245APA	ICS9107C-03CS14T-INT	ICS9112AM-17LFT
IDT74LVC4245APG	IDT74LVCH16245APA8	ICS9107C-05CS08	ICS9112AM-17T
IDT74LVC4245APG8	IDT74LVCH16245APAG	ICS9107C-05CS08LF	ICS9112AM-26

ATTACHMENT 2 - PCN # : A0807-02

Affected Part Number, except 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

ICS9112AM-26LF	ICS91309AGLF	ICS9148F-02	ICS9161A-01CW16T
ICS9112AM-26LFT	ICS91309AGLFT	ICS9148F-02LF	ICS9161A-01CW16T-IB0
ICS9112AM-26T	ICS91309AM	ICS9148F-12	ICS9161A-01CW16T-IB1
ICS9112AM-27	ICS91309AMI	ICS9148F-12LF	ICS9161A-01CW16T-INO
ICS9112AM-27LF	ICS91309AMILF	ICS9148F-12LFT	ICS9169AM-70
ICS9112AM-27LFT	ICS91309AMILFT	ICS9148F-12T	ICS9169AM-70T
ICS9112AM-27T	ICS91309AMIT	ICS9148F-20	ICS9169CM-23LF
ICS9112AM-28	ICS91309AMLF	ICS9148F-25	ICS9169CM-23LFT
ICS9112AM-28LF	ICS91309AMLFT	ICS9148F-25T	ICS9169M-01
ICS9112AM-28LFT	ICS91309AMT	ICS9154-16CS16	ICS9169M-01LF
ICS9112AM-28T	ICS9131-01CS16	ICS9154A-04CS16	ICS9169M-01LFT
ICS9112AM-76LF	ICS91315BM	ICS9154A-04CS16LF	ICS9169M-01T
ICS9112AM-76LFT	ICS91315BMLF	ICS9154A-04CS16LFT	ICS9170-01CS08
ICS9112BG-17	ICS91315BMLFT	ICS9154A-04CS16T	ICS9170-01CS08LF
ICS9112BG-17T	ICS91315BMT	ICS9154A-10CS16	ICS9170-01CS08LFT
ICS9112BM-17	ICS9148AF-32LF	ICS9154A-10CS16LF	ICS9170-01CS08T
ICS9112BM-17LF	ICS9148AF-32LFT	ICS9154A-10CS16LFT	ICS9170-02CS08
ICS9112BM-17LFT	ICS9148AF-32T	ICS9154A-10CS16T	ICS9170-02CS08LF
ICS9112BM-17T	ICS9148AF-58	ICS9154A-27CS16	ICS9170-02CS08LFT
ICS9112M-06	ICS9148AF-58T	ICS9154A-27CS16LF	ICS9170-02CS08T
ICS9112M-06T	ICS9148AF-75	ICS9154A-27CS16LFT	ICS9170-04CS08
ICS9112M-07	ICS9148AG-12	ICS9154A-27CS16T	ICS9170-04CS08LF
ICS9112M-07LF	ICS9148AG-12LF	ICS9154A-42CS16	ICS9170-04CS08LFT
ICS9112M-07LFT	ICS9148AG-12LFT	ICS9154A-42CS16T	ICS9170-04CS08T
ICS9112M-07T	ICS9148AG-12T	ICS9154A-43CS16LF	ICS9170-04CS08T-A
ICS9112M-22	ICS9148AM-60	ICS9154A-43CS16LFT	ICS9170-04CS08T-HP0
ICS9112M-22LF	ICS9148AM-60LF	ICS9154A-57CS16	ICS9170-05CS08
ICS9112M-22LFT	ICS9148AM-60LFT	ICS9154A-57CS16T	ICS9170-05CS08T
ICS9112M-22T	ICS9148AM-60T	ICS9155-01CW20	ICS91717AM
ICS9120-08CS08	ICS9148BF-04	ICS9155-01CW20T	ICS91718AM
ICS9120-08CS08T	ICS9148BF-04LF	ICS9155-02CW20	ICS91718AMT
ICS9120M-45	ICS9148BF-04LFT	ICS9155-02CW20T	ICS91718AMT-INO
ICS9120M-45T	ICS9148BF-04T	ICS9155C-01CW20	ICS91718BG
ICS91305AG	ICS9148BF-17	ICS9155C-01CW20LF	ICS91718BGT
ICS91305AGI	ICS9148BF-17LF	ICS9155C-01CW20LFT	ICS91718BM
ICS91305AGILF	ICS9148BF-17LFT	ICS9155C-01CW20T	ICS91718BMLF
ICS91305AGILFT	ICS9148BF-17T	ICS9155C-02CW20	ICS91718BMLFT
ICS91305AGIT	ICS9148BF-26LF	ICS9155C-02CW20T	ICS91718BMT
ICS91305AGLF	ICS9148BF-26LFT	ICS9155C-23CW20LF	ICS91718CG
ICS91305AGLFT	ICS9148BF-26T	ICS9155C-23CW20LFT	ICS91718CGLF
ICS91305AGT	ICS9148BF-36	ICS9159C-02CW28	ICS91718CGLFT
ICS91305AM	ICS9148BF-36LF	ICS9159C-02CW28LF	ICS91718CGT
ICS91305AMI	ICS9148BF-36T	ICS9159C-02CW28LFT	ICS91718CM
ICS91305AMILF	ICS9148BF-37	ICS9159C-02CW28T	ICS91718CMLF
ICS91305AMILFT	ICS9148BF-37LF	ICS9159M-05	ICS91718CMLFT
ICS91305AMIT	ICS9148BF-37LFT	ICS9159M-05LF	ICS91718CMT
ICS91305AMLF	ICS9148BF-37T	ICS9159M-05LFT	ICS91719AG
ICS91305AMLFT	ICS9148CF-10	ICS9159M-05T	ICS91719AG-SC0
ICS91305AMT	ICS9148CF-10LF	ICS9159M-14	ICS91719AGLF
ICS91309AGI	ICS9148CF-10T	ICS9159M-14T	ICS91719AGLF-SC0
ICS91309AGILF	ICS9148CF-20	ICS9161A-01CW16	ICS91719AGLFT
ICS91309AGILFT	ICS9148CF-20T	ICS9161A-01CW16LF	ICS91719AGLFT-SC0
ICS91309AGIT	ICS9148CF-20T-INO	ICS9161A-01CW16LFT	ICS91719AGT

ATTACHMENT 2 - PCN # : A0807-02

Affected Part Number, except 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

ICS91719AGT-SC0	ICS9220BGILF	ICS9248AG-150T	ICS9248BF-81T
ICS91719BG	ICS9220BGILFT	ICS9248AG-150T-INO	ICS9248BF-87
ICS91719BGLF	ICS9222AG-01LF	ICS9248AG-185T	ICS9248BF-87T
ICS91719BGLFT	ICS9222AG-01LFT	ICS9248AG-192	ICS9248BF-96
ICS91719BGT	ICS9222AG-01T-INO	ICS9248AG-192LF	ICS9248BF-96LF
ICS9172-01CW16	ICS9248AF-101	ICS9248AG-192LFT	ICS9248BF-96LFT
ICS9172-01CW16LF	ICS9248AF-101T	ICS9248AG-192T	ICS9248BF-96T
ICS9172-01CW16LFT	ICS9248AF-107	ICS9248AG-195	ICS9248BF-99
ICS9172-01CW16T	ICS9248AF-114	ICS9248AG-195LF	ICS9248CF-126
ICS9172-03CS16	ICS9248AF-114T	ICS9248AG-195LFT	ICS9248CF-126LF
ICS9172-03CS16T	ICS9248AF-120	ICS9248AG-198	ICS9248CF-126LFT
ICS9172-07CS16	ICS9248AF-127	ICS9248AG-198LF	ICS9248CF-126T
ICS9172-07CS16T	ICS9248AF-127T	ICS9248AG-198LFT	ICS9248CF-172
ICS9172-07CW16	ICS9248AF-128	ICS9248AG-198T	ICS9248CF-172LF
ICS91720AM	ICS9248AF-128LF	ICS9248AG-92	ICS9248CF-172LFT
ICS91720BG	ICS9248AF-128LFT	ICS9248AG-92LF	ICS9248CF-98
ICS91720BGLF	ICS9248AF-128T	ICS9248AG-92LFT	ICS9248CF-98LF
ICS91720BGLFT	ICS9248AF-136	ICS9248AG-92T	ICS9248CF-98LFT
ICS91720BGT	ICS9248AF-138	ICS9248AG-92T-IB0	ICS9248CF-98T
ICS91720BM	ICS9248AF-143	ICS9248AG-92T-INO	ICS9248CG-172LF
ICS91720BMT	ICS9248AF-150	ICS9248AM-100	ICS9248DF-179
ICS9173-01CS08	ICS9248AF-150LF	ICS9248BF-102	ICS9248DF-39
ICS9173-01CS08LF	ICS9248AF-150LFT	ICS9248BF-102LF	ICS9248DF-39LF
ICS9173-01CS08LFT	ICS9248AF-150T	ICS9248BF-102LFT	ICS9248DF-39LFT
ICS9173-01CS08T	ICS9248AF-150T-IB0	ICS9248BF-102T	ICS9248DF-39T
ICS9173-15CS08	ICS9248AF-151	ICS9248BF-131	ICS9248DF-39T-IB0
ICS9173-15CS08LF	ICS9248AF-151LF	ICS9248BF-138	ICS9248DF-54
ICS9173-15CS08LFT	ICS9248AF-151LFT	ICS9248BF-138LF	ICS9248DF-54T
ICS9173-15CS08T	ICS9248AF-151T	ICS9248BF-138LFT	ICS9250AF-10
ICS91730AM	ICS9248AF-173	ICS9248BF-138T	ICS9250AF-10T
ICS91730AMLF	ICS9248AF-173T	ICS9248BF-146	ICS9250AF-10T-INO
ICS91730AMLF-PAC	ICS9248AF-189	ICS9248BF-146LF	ICS9250AF-23
ICS91730AMLFT	ICS9248AF-195LF	ICS9248BF-146LFT	ICS9250AF-23T
ICS91730AMLFT-PAC	ICS9248AF-195LFT	ICS9248BF-146T	ICS9250AF-25
ICS91730AMT	ICS9248AF-64	ICS9248BF-164	ICS9250AF-25LF
ICS9176M-01	ICS9248AF-64LFT	ICS9248BF-168	ICS9250AF-25LFT
ICS9179AF-06	ICS9248AF-64T	ICS9248BF-195	ICS9250AF-25T
ICS9179AM-12	ICS9248AF-95	ICS9248BF-195LF	ICS9250AF-29
ICS9179AM-12LF	ICS9248AF-95LF	ICS9248BF-195LFT	ICS9250AF-29T
ICS9179AM-12LFT	ICS9248AF-95LFT	ICS9248BF-195T	ICS9250AF-30
ICS9179BF-01	ICS9248AF-95T	ICS9248BF-20	ICS9250AF-30LF
ICS9179BF-01LF	ICS9248AF-95T-IB0	ICS9248BF-20LF	ICS9250AF-30LFT
ICS9179BF-01LFT	ICS9248AF-96	ICS9248BF-20LFT	ICS9250AF-30T
ICS9179BF-01T	ICS9248AF-96LF	ICS9248BF-20T	ICS9250AF-31
ICS9179CF-06	ICS9248AF-96LFT	ICS9248BF-55	ICS9250AF-51
ICS9179CF-06T	ICS9248AF-96T	ICS9248BF-55T	ICS9250AF-51LF
ICS9179CF-06T-IB0	ICS9248AG-101	ICS9248BF-64	ICS9250AF-51LFT
ICS9179CF-06T-INO	ICS9248AG-101LF	ICS9248BF-64T	ICS9250AF-51T
ICS9219AGLF	ICS9248AG-101LFT	ICS9248BF-77	ICS9250AG-31
ICS9219BGLF	ICS9248AG-101T	ICS9248BF-77T	ICS9250AG-31T
ICS9219BGLFT	ICS9248AG-150	ICS9248BF-81	ICS9250AG-33
ICS9220AGLF	ICS9248AG-150LN	ICS9248BF-81LF	ICS9250BF-09
ICS9220AGLFT	ICS9248AG-150LNT	ICS9248BF-81LFT	ICS9250BF-09T

ATTACHMENT 2 - PCN # : A0807-02

Affected Part Number, except 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

ICS9250BF-10	ICS9250DF-30LFT	ICS93738AFLF	ICS94252BFT
ICS9250BF-10T	ICS9250DF-38	ICS93738AFLFT	ICS94258BF
ICS9250BF-12	ICS9250DF-38T	ICS93738AFT	ICS94258BFT
ICS9250BF-12LF	ICS9250EG-38T	ICS94201CF	ICS94258BG
ICS9250BF-12LFT	ICS9279BF-01	ICS94201DF	ICS94258BGT
ICS9250BF-12T	ICS9279BF-01T	ICS94201DF-995	ICS950003DF
ICS9250BF-16	ICS9341AF	ICS94201DF-995LF	ICS950003DFT
ICS9250BF-16LF	ICS9341AFLF	ICS94201DF-995LFT	ICS950104AF
ICS9250BF-16LFT	ICS9341AFLFT	ICS94201DF-995T	ICS950201AF
ICS9250BF-16T	ICS9341AFT	ICS94201DFLF	ICS950201AFLF
ICS9250BF-18LF	ICS9341AFT-IB0	ICS94201DFLFT	ICS950201AFLFT
ICS9250BF-18LFT	ICS9342AF	ICS94201DFT	ICS950201AFLFT-INO
ICS9250BF-19	ICS9342AFLF	ICS94203AF	ICS950201AFT
ICS9250BF-19T	ICS9342AFLFT	ICS94203AFT	ICS950201AG
ICS9250BF-24	ICS9342AFT	ICS94206BF	ICS950201AGLF
ICS9250BF-24T	ICS93701BG	ICS94206BFT	ICS950201AGLFT
ICS9250BF-27	ICS93701BGT	ICS94211AF	ICS950201AGT
ICS9250BF-27LF	ICS93705AF	ICS94211AFLF	ICS950202CF
ICS9250BF-27LFT	ICS93705AFLF	ICS94211AFLFT	ICS950202CFLF
ICS9250BF-27T	ICS93705AFLFT	ICS94211AFT	ICS950202CFLFT
ICS9250BF-28	ICS93705AFT	ICS94215AF	ICS950202CFT
ICS9250BF-28LF	ICS93705CF	ICS94215AF-010	ICS950209CF
ICS9250BF-28LFT	ICS93705CFLF	ICS94215AFT	ICS950209CFT
ICS9250BF-28T	ICS93705CFLFT	ICS94220AF-010	ICS950211AG
ICS9250BF-50	ICS93705CFT	ICS94222AF	ICS950211AGT
ICS9250BF-50LF	ICS93715DF	ICS94227AF	ICS950211BF
ICS9250BF-50LFT	ICS93718CF	ICS94227AFLF	ICS950211BFLF
ICS9250BF-50T	ICS93718CFLF	ICS94227AFLFT	ICS950211BFLFT
ICS9250BG-24	ICS93718CFLFT	ICS94227AFT	ICS950211BFT
ICS9250BG-24LF	ICS93718CFT	ICS94228BF	ICS950211BGLF
ICS9250BG-24LFT	ICS93718DF	ICS94228BFLF	ICS950211BGLFT
ICS9250BG-24T	ICS93718DFLF	ICS94228BFLFT	ICS950213AF
ICS9250BG-24T-INO	ICS93718DFLFT	ICS94228BFT	ICS950213AFT
ICS9250BGI-24LF	ICS93718DFT	ICS94230BF	ICS950218AF
ICS9250BGI-24LFT	ICS93725AF	ICS94230BFLF	ICS950218AFLF
ICS9250BGI-27LFT	ICS93725AFLF	ICS94230BFLFT	ICS950218AFLFT
ICS9250CF-08	ICS93725AFLFT	ICS94230BFT	ICS950218AFT
ICS9250CF-08LF	ICS93725AFT	ICS94230EF	ICS950219BF
ICS9250CF-08LFT	ICS93732AG	ICS94230EFT	ICS950219BFLF
ICS9250CF-08T	ICS93732AGT	ICS94231AF	ICS950219BFLFT
ICS9250CF-09	ICS93733CF	ICS94231AFLF	ICS950219BFT
ICS9250CF-09LF	ICS93733CFLF	ICS94231AFLFT	ICS950219BFT-CQ0
ICS9250CF-09LFT	ICS93733CFLFT	ICS94231AFT	ICS950220AF
ICS9250CF-09T	ICS93733CFT	ICS94235AF	ICS950220AFLF
ICS9250CF-09T-IB0	ICS93733DF	ICS94239CG	ICS950220AFLFT
ICS9250CF-09T-INO	ICS93734BFLF	ICS94239CGT	ICS950220AFT
ICS9250CF-10	ICS93734BFLFT	ICS94241AF	ICS950220BF
ICS9250CF-10LF	ICS93734BFT	ICS94241AFLF	ICS950220BFLF
ICS9250CF-10LFT	ICS93735AF	ICS94241AFLFT	ICS950220BFLFT
ICS9250CF-10T	ICS93735AFLF	ICS94241AFT	ICS950220BFT
ICS9250CF-16	ICS93735AFLFT	ICS94252BF	ICS950223BF
ICS9250CG-38	ICS93735AFT	ICS94252BFLF	ICS950223BFLF
ICS9250DF-30LF	ICS93738AF	ICS94252BFLFT	ICS950223BFLFT

ATTACHMENT 2 - PCN # : A0807-02

Affected Part Number, except 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

ICS950223BFT	ICS950602CGLF	ICS950813CGLFT	ICS950913CGT
ICS950224AFLF	ICS950602CGLFT	ICS950813CGT	ICS950916BF
ICS950224AFLFT	ICS950602CGT	ICS950816AGLFT	ICS950916BFT
ICS950225CFLF	ICS950605AFLF	ICS950818AG	ICS950917AF
ICS950225CFLFT	ICS950605AFLFT	ICS950818AGT	ICS950917AFLF
ICS950227AF	ICS950802AF	ICS950819AGLF	ICS950917AFLFT
ICS950227AFT	ICS950802AFLF	ICS950819AGLFT	ICS950917AFT
ICS950227AFT-INO	ICS950802AFLFT	ICS950822AG	ICS950927AFLF
ICS950401CF	ICS950802AFT	ICS950822AGLF	ICS950927AFLFT
ICS950401CFLF	ICS950805AF	ICS950822AGLFT	ICS950951AGLF
ICS950401CFLFT	ICS950805AFLF	ICS950822AGT	ICS950951AGLFT
ICS950401CFT	ICS950805AFLFT	ICS950826AG	ICS950951BGLF
ICS950401CG	ICS950805AFT	ICS950826AGLF	ICS950951BGLFT
ICS950401CGLF	ICS950805AG	ICS950826AGLFT	ICS950951CGLF
ICS950401CGLFT	ICS950805AGLF	ICS950901BF	ICS950951CGLFT
ICS950401CGT	ICS950805AGLFT	ICS950901BFLF	ICS950952AGLF
ICS950402AF	ICS950805AGT	ICS950901BFLFT	ICS950952AGLFT
ICS950402AFLF	ICS950805AGT-IBO	ICS950901BFT	ICS950952BGLF
ICS950402AFLFT	ICS950810BF	ICS950902DF	ICS950952BGLFT
ICS950402AFT	ICS950810BFT	ICS950902DFLF	ICS951001AF
ICS950402AG	ICS950810BG	ICS950902DFLFT	ICS951001AFLF
ICS950402AGLF	ICS950810BGT	ICS950902DFT	ICS951001AFLFT
ICS950402AGLFT	ICS950810CF	ICS950902DGT	ICS951001AFT
ICS950402AGT	ICS950810CFLF	ICS950902DGLF	ICS951104BGLF
ICS950403CF	ICS950810CFLFT	ICS950902DGLFT	ICS951104BGLFT
ICS950403CFLF	ICS950810CFT	ICS950902DGT	ICS951402AF
ICS950403CFLFT	ICS950810CG	ICS950905AF	ICS951402AFLF
ICS950403CFT	ICS950810CGLF	ICS950905AFT	ICS951402AFLFT
ICS950405AF	ICS950810CGLFT	ICS950908AF	ICS951402AFT
ICS950405AFLF	ICS950810CGT	ICS950908AFT	ICS951402AG
ICS950405AFLF-DT0	ICS950810CGT-INO	ICS950908AG	ICS951402AGLF
ICS950405AFLFT	ICS950810PG	ICS950908AGT	ICS951402AGLFT
ICS950405AFLFT-DT0	ICS950810PGLF	ICS950908BF	ICS951402AGT
ICS950405AFT	ICS950810PGLFT	ICS950908BFLF	ICS951403CF
ICS950407AF	ICS950810PGT	ICS950908BFLFT	ICS951403CFT
ICS950407AFT	ICS950810PGT-IBO	ICS950908BFT	ICS951403CG
ICS950410AF	ICS950811AFLF	ICS950908BG	ICS951403CGT
ICS950410AFLF	ICS950811AFLFT	ICS950908BGLF	ICS951405CG
ICS950410AFLFT	ICS950811AG	ICS950908BGLFT	ICS951406AG
ICS950410AFT	ICS950811AGLF	ICS950908BGT	ICS951411BGLF
ICS950410AG	ICS950811AGLFT	ICS950909AFLF	ICS951411BGLFT
ICS950410AGLF	ICS950811AGT	ICS950909AFLFT	ICS951411CGLF
ICS950410AGLFT	ICS950812CG	ICS950910AF	ICS951411CGLFT
ICS950410AGT	ICS950812CGLF	ICS950910AFLF	ICS951412AF
ICS950503AFLF	ICS950812CGLFT	ICS950910AFLFT	ICS951412AFLF
ICS950503AFLFT	ICS950812CGLFT-IBO	ICS950910AFT	ICS951412AFLFT
ICS950508BFLF	ICS950812CGT	ICS950913CF	ICS951412AFT
ICS950508BFLFT	ICS950813BG	ICS950913CFLF	ICS951412AG
ICS950602CF	ICS950813BGLF	ICS950913CFLFT	ICS951412AGLF
ICS950602CFLF	ICS950813BGLFT	ICS950913CFT	ICS951412AGLFT
ICS950602CFLFT	ICS950813BGT	ICS950913CG	ICS951412AGT
ICS950602CFT	ICS950813CG	ICS950913CGLF	ICS951412BFLF
ICS950602CG	ICS950813CGLF	ICS950913CGLFT	ICS951412BFLFT

ATTACHMENT 2 - PCN # : A0807-02

Affected Part Number, except 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

ICS951412BGLF	ICS951461BGLFT	ICS952004AF	ICS952505AFLFT
ICS951412BGLFT	ICS951461CGLF	ICS952004AFLF	ICS952505AFT
ICS951413CFLF	ICS951461CGLFT	ICS952004AFLFT	ICS952508BFLF
ICS951413CFLFT	ICS951462AGLF	ICS952004AFT	ICS952508BFLFT
ICS951413CG	ICS951462AGLF-DT0	ICS952005CF	ICS952508BGLF
ICS951413CGLF	ICS951462AGLFT	ICS952005CFLF	ICS952508BGLFT
ICS951413CGLFT	ICS951462AGLFT-DT0	ICS952005CFLFT	ICS952601EF
ICS951413CGT	ICS951462BGLF	ICS952005CFT	ICS952601EFLF
ICS951416AF	ICS951462BGLFT	ICS952007AF	ICS952601EFLFT
ICS951416AFLF	ICS951463BFLF	ICS952007AFLF	ICS952601EFLFT-INO
ICS951416AFLFT	ICS951463BFLFT	ICS952007AFLFT	ICS952601EFLN
ICS951416AFT	ICS951463BGLF	ICS952007AFT	ICS952601EFLNT
ICS951416AG	ICS951463BGLFT	ICS952011AF	ICS952601EFLNT-INO
ICS951416AGLF	ICS951463CFLF	ICS952011BF	ICS952601EFT
ICS951416AGLFT	ICS951463CFLFT	ICS952011BFLF	ICS952601EFT-IB0
ICS951416AGT	ICS951463CGLF	ICS952011BFLFT	ICS952601EFT-INO
ICS951417AF	ICS951463CGLFT	ICS952011BFT	ICS952601EG
ICS951417AFLF	ICS951464AFLF	ICS952013CF	ICS952601EGLF
ICS951417AFLFT	ICS951464AFLFT	ICS952013CFLF	ICS952601EGLFT
ICS951417AFT	ICS951464AGLF	ICS952013CFLFT	ICS952601EGT
ICS951417AGLF	ICS951464AGLFT	ICS952013CFT	ICS952603DF
ICS951417AGLFT	ICS951464BFLF	ICS952017AF	ICS952603DFLF
ICS951418AG	ICS951464BFLFT	ICS952017AFLF	ICS952603DFLFT
ICS951418AGT	ICS951464BGLF	ICS952017AFLFT	ICS952603DFT
ICS951418BFLF	ICS951464BGLFT	ICS952017AFT	ICS952606PF
ICS951418BFLFT	ICS951601AF	ICS952018AF	ICS952606PFLF
ICS951418BG	ICS951601AFLF	ICS952018AFLF	ICS952606PFLFT
ICS951418BGLF	ICS951601AFLFT	ICS952018AFLFT	ICS952606PFT
ICS951418BGLFT	ICS951601AFT	ICS952018AFT	ICS952607EF
ICS951418BGT	ICS951702AGI	ICS952019AF	ICS952607EFLF
ICS951418CFLF	ICS951702AGIT	ICS952019AFLF	ICS952607EFLFT
ICS951418CFLFT	ICS951702AGLF	ICS952019AFLFT	ICS952607EFT
ICS951418CGLF	ICS951702AGLFT	ICS952019AFT	ICS952611BF
ICS951418CGLFT	ICS951703AG	ICS952023CG	ICS952611BFLF
ICS951419AFLF	ICS951703AGT	ICS952023CGLF	ICS952611BFLFT
ICS951419AFLFT	ICS951704AG	ICS952023CGLFT	ICS952611BFT
ICS951420AF	ICS951704AGT	ICS952023CGT	ICS952617BF
ICS951420AFLF	ICS951808BFLF	ICS952101CF	ICS952617BFLF
ICS951420AFLFT	ICS951808BFLFT	ICS952101CF-EM0	ICS952617BFLFT
ICS951420AFT	ICS951808CF	ICS952101CFLF	ICS952617BFT
ICS951420AGLF	ICS951901AF	ICS952101CFLFT	ICS952618BF
ICS951420AGLFT	ICS951901AFLF	ICS952101CFT	ICS952618BFLF
ICS951421AFLF	ICS951901AFLFT	ICS952101CFT-EM0	ICS952618BFLFT
ICS951421AFLFT	ICS951901AFT	ICS952201AF	ICS952618BFT
ICS951421AGLF	ICS952001AF	ICS952302AG	ICS952618BFT-INO
ICS951421AGLFT	ICS952001AFLF	ICS952302AGLF	ICS952619CF
ICS951422AG	ICS952001AFLFT	ICS952302AGLFT	ICS952619CFLF
ICS951422AGLF	ICS952001AFT	ICS952302AGT	ICS952619CFLFT
ICS951422AGLFT	ICS952001AG	ICS952501BF	ICS952619CFT
ICS951422AGT	ICS952001AGT	ICS952501BFT	ICS952620CF
ICS951446AGLF	ICS952003AF	ICS952502AF	ICS952620CFLF
ICS951446AGLFT	ICS952003AFT	ICS952505AF	ICS952620CFLFT
ICS951461BGLF	ICS952003AG	ICS952505AFLF	ICS952620CFT

ATTACHMENT 2 - PCN # : A0807-02

Affected Part Number, except 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

ICS952621CF	ICS952803AF	ICS953002DF	ICS953805CGT
ICS952621CFLF	ICS952803AFLF	ICS953002DFLF	ICS954101DF
ICS952621CFLFT	ICS952803AFLFT	ICS953002DFLFT	ICS954101DFLF
ICS952621CFT	ICS952803AFT	ICS953002DFT	ICS954101DFLFT
ICS952621CG	ICS952803AG	ICS953005BFLF	ICS954101DFLN
ICS952621CGT	ICS952803AGT	ICS953005BFLFT	ICS954101DFLNT
ICS952623CG	ICS952805BF	ICS953006AF	ICS954101DFT
ICS952623CGLF	ICS952805BFLF	ICS953007AF	ICS954101DFT-INO
ICS952623CGLFT	ICS952805BFLFT	ICS953008BF	ICS954101DG
ICS952623CGT	ICS952805BFT	ICS953008BFLF	ICS954101DGLF
ICS952624AFLF	ICS952903AF	ICS953008BFLFT	ICS954101DGLFT
ICS952624AFLFT	ICS952903AFLF	ICS953008BFT	ICS954101DGT
ICS952628AFLF	ICS952903AFLFT	ICS953009AF	ICS954102AF
ICS952628AFLFT	ICS952903AFT	ICS953009AFLF	ICS954102AFLN
ICS952635AF	ICS952903BF	ICS953009AFLFT	ICS954102AFLNT
ICS952635AFLF	ICS952906AF	ICS953009AFT	ICS954102AFLNT-INO
ICS952635AFLFT	ICS952906AFLF	ICS953009AGLF	ICS954102AFT
ICS952635AFT	ICS952906AFLFT	ICS953009AGLFT	ICS954102AFT-INO
ICS952635BF	ICS952906AFT	ICS953201BF	ICS954103EFLN
ICS952635BFLF	ICS952906AGLF	ICS953201BFLF	ICS954103EFLNT
ICS952635BFLFT	ICS952906AGLFT	ICS953201BFLFT	ICS954103EFLNT-INO
ICS952635BFT	ICS952906BFLF	ICS953201BFT	ICS954105BF
ICS952638AF	ICS952906BFLFT	ICS953201BGLF	ICS954105BFLF
ICS952638AFT	ICS952906BGLF	ICS953201BGLFT	ICS954105BFLFT
ICS952642AF	ICS952906BGLFT	ICS953202BF	ICS954105BFT
ICS952642AFLF	ICS952911BF	ICS953202BFLF	ICS954108CF
ICS952642AFLFT	ICS952911BFLF	ICS953202BFLFT	ICS954108CFLF
ICS952642AFT	ICS952911BFLFT	ICS953202BFT	ICS954108CFLFT
ICS952643AF	ICS952911BFT	ICS953202BG	ICS954108CFLFT-INO
ICS952643AFLF	ICS952911BGLF	ICS953202BGT	ICS954108CFT
ICS952643AFLFT	ICS952911BGLFT	ICS953203AF	ICS954110BF
ICS952643AFT	ICS952926AFLF	ICS953203BFLF	ICS954110BFLF
ICS952647AF	ICS952926AFLFT	ICS953203BFLFT	ICS954110BFLFT
ICS952647AFLF	ICS952926AGLF	ICS953401CF	ICS954110BFT
ICS952647AFLFT	ICS952926AGLFT	ICS953401CFLF	ICS954119AF
ICS952647AFT	ICS952926BFLF	ICS953401CFLFT	ICS954119DF
ICS952671AG	ICS952926BFLFT	ICS953401CFT	ICS954119DFLF
ICS952702BF	ICS952926BGLF	ICS953401CG	ICS954119DFLFT
ICS952702BFLF	ICS952926BGLFT	ICS953401CGT	ICS954119DFT
ICS952702BFLFT	ICS952926CFLF	ICS953402AFLF	ICS954120EF
ICS952702BFT	ICS952926CFLFT	ICS953402AFLFT	ICS954120EFLF
ICS952703BF	ICS952926CGLF	ICS953406AF	ICS954120EFLFT
ICS952703BFLF	ICS952926CGLFT	ICS953801AF	ICS954120EFT
ICS952703BFLFT	ICS952930HF	ICS953803AF	ICS954123BF
ICS952703BFT	ICS952930HFT	ICS953803AFT	ICS954123BFLF
ICS952801CF	ICS953001DF	ICS953805AF	ICS954123BFLFT
ICS952801CFLF	ICS953001DFT	ICS953805CF	ICS954123BFT
ICS952801CFLFT	ICS953001EFLF	ICS953805CFLF	ICS954123CG
ICS952801CFT	ICS953001EFLFT	ICS953805CFLFT	ICS954123CGLF
ICS952802AF	ICS953002CF	ICS953805CFT	ICS954123CGLFT
ICS952802AFLF	ICS953002CFLF	ICS953805CG	ICS954123CGT
ICS952802AFLFT	ICS953002CFLFT	ICS953805CGLF	ICS954124AF
ICS952802AFT	ICS953002CFT	ICS953805CGLFT	ICS954124AFLF

ATTACHMENT 2 - PCN # : A0807-02

Affected Part Number, except 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

ICS954124AFLFT	ICS954148AFT	ICS954206BG	ICS954321AGLFT
ICS954124AFT	ICS954148AGLF	ICS954206BGLF	ICS954511AF
ICS954124BF	ICS954148AGLFT	ICS954206BGLFT	ICS954511AFLF
ICS954124BFLFT	ICS954158CFLF	ICS954206BGT	ICS954511AFLFT
ICS954124BFT	ICS954158CFLFT	ICS954211AF	ICS954511BF
ICS954127BF	ICS954201AG	ICS954211AFLF	ICS954511BFLF
ICS954127BFLF	ICS954201AGLN	ICS954211AFLFT	ICS954511BFLFT
ICS954127BFLFT	ICS954201AGLNT	ICS954211AFT	ICS954511BFT
ICS954127BFT	ICS954201AGT	ICS954213AG	ICS954519BGLF
ICS954127BG	ICS954201BF	ICS954213AGLF	ICS954519BGLFT
ICS954127BGLF	ICS954201BFLF	ICS954213AGLFT	ICS954550AG
ICS954127BGLFT	ICS954201BFLFT	ICS954213AGT	ICS954550AGT
ICS954127BGT	ICS954201BFT	ICS954215AG	ICS954550CGLF
ICS954128AF	ICS954201BG	ICS954215AGLF	ICS954550CGLFT
ICS954128AFLF	ICS954201BGLF	ICS954215AGLFT	ICS954552CGLF
ICS954128AFLFT	ICS954201BGLFT	ICS954215AGT	ICS954552CGLFT
ICS954128AFT	ICS954201BGT	ICS954217AG	ICS954553EGLF
ICS954129BF	ICS954201CG	ICS954217AGLF	ICS954553EGLFT
ICS954129BFLF	ICS954201CGT	ICS954217AGLFT	ICS954557EGLF
ICS954129BFLFT	ICS954203AG	ICS954217AGT	ICS954557EGLFT
ICS954129BFT	ICS954203AGLF	ICS954218AG	ICS960001AF
ICS954130BF	ICS954203AGLFT	ICS954218BG	ICS960001AFLF
ICS954130BFLF	ICS954203AGT	ICS954218BGLF	ICS960001AFLFT
ICS954130BFLFT	ICS954203BG	ICS954218BGLFT	ICS960001AFT
ICS954130BFT	ICS954203BGLF	ICS954218BGT	ICS960006AFLF
ICS954135AF	ICS954203BGLFT	ICS954226AG	ICS960006AFLFT
ICS954135AFLF	ICS954203BGT	ICS954226AGLF	ICS960009CFLF
ICS954135AFLFT	ICS954204AG	ICS954226AGLFT	ICS960009CFLFT
ICS954135AFT	ICS954204AGLF	ICS954226AGT	ICS960013AFLF
ICS954137AF	ICS954204AGLFT	ICS954227AG	ICS960013BFLF
ICS954141AF	ICS954204AGLN	ICS954227AGLF	ICS960013BFLFT
ICS954141AFLF	ICS954204AGLNT	ICS954227BGLF	ICS9E4101AFILF
ICS954141AFLFT	ICS954204AGT	ICS954227CGLF	ICS9E4101AFILFT
ICS954141AFT	ICS954204BG	ICS954227CGLFT	ICS9LP208AG
ICS954141AG	ICS954204BGLF	ICS954229AG	ICS9LP208AGLF
ICS954141AGLF	ICS954204BGLFT	ICS954229AGLF	ICS9LP208AGLFT
ICS954141AGLFT	ICS954204BGLN	ICS954229AGLFT	ICS9LP208AGT
ICS954141AGT	ICS954204BGLNT	ICS954229AGT	ICS9LP306BGLF
ICS954141BF	ICS954204BGT	ICS954230AGLF	ICS9LP306BGLFT
ICS954141BFLF	ICS954204CG	ICS954230AGLFT	ICS9LP505-1HGLF
ICS954141BFLFT	ICS954204CGLF	ICS954238AGLF	ICS9LP505-1HGLFT
ICS954141BFT	ICS954204CGLFT	ICS954238AGLFT	ICS9LP505-2CFILF
ICS954141BG	ICS954204CGLN	ICS954270AGLF	ICS9LP505-2CFILFT
ICS954141BGLF	ICS954204CGLNT	ICS954270AGLFT	ICS9LP505-2EFLF
ICS954141BGLFT	ICS954204CGT	ICS954306BG	ICS9LP505-2EFLFT
ICS954141BGT	ICS954206AG	ICS954306BGLF	ICS9LP505-2EGLF
ICS954141CFLF	ICS954206AGLF	ICS954306BGLFT	ICS9LP505-2EGLFT
ICS954141CFLFT	ICS954206AGLFT	ICS954306BGT	ICS9LP505-2HFLF
ICS954147BFLF	ICS954206AGT	ICS954310BGLF	ICS9LP505-2HFLFT
ICS954147BFLFT	ICS954206BF	ICS954310BGLFT	ICS9LP505-2HGLF
ICS954148AF	ICS954206BFLF	ICS954310CGLF	ICS9LP505-2HGLFT
ICS954148AFLF	ICS954206BFLFT	ICS954310CGLFT	ICS9LP505-2JGLF
ICS954148AFLFT	ICS954206BFT	ICS954321AGLF	ICS9LP505-2JGLFT

ATTACHMENT 2 - PCN # : A0807-02

Affected Part Number, except 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

ICS9LP505-2PFLF	ICS9LPR501CGLFT	ICS9LPR730AFLF	ICS9LPRS418DGLFT
ICS9LP505-2PFLFT	ICS9LPR501HGLF	ICS9LPR730AFLFT	ICS9LPRS419BFLF
ICS9LP505-2PGLF	ICS9LPR501HGLFT	ICS9LPR730AGLF	ICS9LPRS419BFLFT
ICS9LP505-2PGLFT	ICS9LPR501PGLF	ICS9LPR730AGLFT	ICS9LPRS419BGLF
ICS9LP525AG-1LF	ICS9LPR501PGLFT	ICS9LPR780BFLF	ICS9LPRS419BGLFT
ICS9LP525AG-1LFT	ICS9LPR501SGLF	ICS9LPR780BFLFT	ICS9LPRS419CFLF
ICS9LPR229AGLF	ICS9LPR501SGLFT	ICS9LPR780BGLF	ICS9LPRS419CFLFT
ICS9LPR229AGLFT	ICS9LPR502CGLF	ICS9LPR780BGLFT	ICS9LPRS419DFLF
ICS9LPR306AGLF	ICS9LPR502CGLFT	ICS9LPR781BFLF	ICS9LPRS419DFLFT
ICS9LPR306AGLFT	ICS9LPR502HFLF	ICS9LPR781BFLFT	ICS9LPRS419DGLF
ICS9LPR310BGLF	ICS9LPR502HFLFT	ICS9LPR800BGLF	ICS9LPRS419DGLFT
ICS9LPR310BGLFT	ICS9LPR502HGLF	ICS9LPR800BGLFT	ICS9LPRS420DGLF
ICS9LPR316AGLF	ICS9LPR502HGLFT	ICS9LPR803AFLF	ICS9LPRS420DGLFT
ICS9LPR316AGLFT	ICS9LPR502SGLF	ICS9LPR803AFLFT	ICS9LPRS424DGLF
ICS9LPR358AGLF	ICS9LPR502SGLFT	ICS9LPR803AGLF	ICS9LPRS424DGLFT
ICS9LPR358AGLFT	ICS9LPR515AGLF	ICS9LPR803AGLFT	ICS9LPRS427AGLF
ICS9LPR362AGLF	ICS9LPR515AGLFT	ICS9LPRS1111AGLF	ICS9LPRS427AGLFT
ICS9LPR362AGLFT	ICS9LPR515BGLF	ICS9LPRS1111AGLFT	ICS9LPRS429AGLF
ICS9LPR363AGLF	ICS9LPR515BGLFT	ICS9LPRS136AGLF	ICS9LPRS430AGLF
ICS9LPR363AGLFT	ICS9LPR515CGLF	ICS9LPRS136AGLFT	ICS9LPRS434AGLF
ICS9LPR363BGLF	ICS9LPR515CGLFT	ICS9LPRS136BGLF	ICS9LPRS434AGLFT
ICS9LPR363BGLFT	ICS9LPR600AGLF	ICS9LPRS136BGLFT	ICS9LPRS437AFLF
ICS9LPR363CGLF	ICS9LPR600AGLFT	ICS9LPRS137AGLF	ICS9LPRS437AFLFT
ICS9LPR363CGLFT	ICS9LPR600BGLF	ICS9LPRS137AGLFT	ICS9LPRS437AGLF
ICS9LPR363DGLF	ICS9LPR600BGLFT	ICS9LPRS146AGLF	ICS9LPRS437AGLFT
ICS9LPR363DGLFT	ICS9LPR600CGLF	ICS9LPRS146AGLFT	ICS9LPRS438AFLF
ICS9LPR363EGLF	ICS9LPR600CGLFT	ICS9LPRS154AGLF	ICS9LPRS438AFLFT
ICS9LPR363EGLFT	ICS9LPR600DGLF	ICS9LPRS154AGLFT	ICS9LPRS438AGLF
ICS9LPR364AGLF	ICS9LPR600DGLFT	ICS9LPRS355AGLF	ICS9LPRS438AGLFT
ICS9LPR364AGLFT	ICS9LPR601BGLF	ICS9LPRS355AGLFT	ICS9LPRS439AFLF
ICS9LPR364BGLF	ICS9LPR601BGLFT	ICS9LPRS355BGLF	ICS9LPRS439AFLFT
ICS9LPR364BGLFT	ICS9LPR603AFLF	ICS9LPRS355BGLFT	ICS9LPRS439AGLF
ICS9LPR367AGLF	ICS9LPR603AFLFT	ICS9LPRS355CGLF	ICS9LPRS439AGLFT
ICS9LPR367AGLFT	ICS9LPR603AGLF	ICS9LPRS355CGLFT	ICS9LPRS462AGLF
ICS9LPR367BGLF	ICS9LPR603AGLFT	ICS9LPRS355DGLF	ICS9LPRS462AGLFT
ICS9LPR367BGLFT	ICS9LPR604AFLF	ICS9LPRS355DGLFT	ICS9LPRS464AGLF
ICS9LPR410AFLF	ICS9LPR604AFLFT	ICS9LPRS359AGLF	ICS9LPRS464AGLFT
ICS9LPR410AFLFT	ICS9LPR608BGLF	ICS9LPRS359AGLFT	ICS9LPRS473CGLF
ICS9LPR412AFLF	ICS9LPR608BGLFT	ICS9LPRS365AGLF	ICS9LPRS473CGLFT
ICS9LPR412AFLFT	ICS9LPR700BGLF	ICS9LPRS365AGLFT	ICS9LPRS475AGLF
ICS9LPR426AGLF	ICS9LPR700BGLFT	ICS9LPRS365BGLF	ICS9LPRS475AGLFT
ICS9LPR426AGLFT	ICS9LPR700CGLF	ICS9LPRS365BGLFT	ICS9LPRS479BGLF
ICS9LPR426BGLF	ICS9LPR700CGLFT	ICS9LPRS365CGLF	ICS9LPRS479BGLFT
ICS9LPR426BGLFT	ICS9LPR700DGLF	ICS9LPRS365CGLFT	ICS9LPRS480AGLF
ICS9LPR461AGLF	ICS9LPR700DGLFT	ICS9LPRS365DGLF	ICS9LPRS480AGLFT
ICS9LPR461AGLFT	ICS9LPR700EGLF	ICS9LPRS365DGLFT	ICS9LPRS480BGLF
ICS9LPR462AGLF	ICS9LPR700EGLFT	ICS9LPRS412AFLF	ICS9LPRS480BGLFT
ICS9LPR462AGLFT	ICS9LPR701AGLF	ICS9LPRS412AFLFT	ICS9LPRS485AGLF
ICS9LPR463AGLF	ICS9LPR701AGLFT	ICS9LPRS412BFLF	ICS9LPRS485AGLFT
ICS9LPR463AGLFT	ICS9LPR701BGLF	ICS9LPRS412BFLFT	ICS9LPRS485BGLF
ICS9LPR464AGLF	ICS9LPR701BGLFT	ICS9LPRS412DFLF	ICS9LPRS485BGLFT
ICS9LPR464AGLFT	ICS9LPR704AGLF	ICS9LPRS412DFLFT	ICS9LPRS485CGLF
ICS9LPR501CGLF	ICS9LPR704AGLFT	ICS9LPRS418DGLF	ICS9LPRS485CGLFT

ATTACHMENT 2 - PCN # : A0807-02

Affected Part Number, except 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

ICS9LPRS489CGLF	ICS9LPRS512JGLFT	ICS9LPRS908DGLF	ICS9P944AF
ICS9LPRS489CGLFT	ICS9LPRS513CGLF	ICS9LPRS908DGLFT	ICS9P946AFLF
ICS9LPRS501PGLF	ICS9LPRS513CGLFT	ICS9LPRS916BGLF	ICS9P946AFLFT
ICS9LPRS501PGLFT	ICS9LPRS513EGLF	ICS9LPRS916BGLFT	ICS9P946BFLF
ICS9LPRS501SGLF	ICS9LPRS513EGLFT	ICS9LPRS916CGLF	ICS9P946BFLFT
ICS9LPRS501SGLFT	ICS9LPRS513HGLF	ICS9LPRS916CGLFT	ICS9P951AF
ICS9LPRS502HGLF	ICS9LPRS513HGLFT	ICS9LPRS916HGLF	ICS9P952DFLF
ICS9LPRS502HGLFT	ICS9LPRS513JGLF	ICS9LPRS916HGLFT	ICS9P952DFLFT
ICS9LPRS502PFLF	ICS9LPRS513JGLFT	ICS9LPRS916JGLF	ICS9P956AGLF
ICS9LPRS502PFLFT	ICS9LPRS514EGLF	ICS9LPRS916JGLFT	ICS9P956AGLFT
ICS9LPRS502PGLF	ICS9LPRS514EGLFT	ICS9LPRS917CGLF	ICS9P960AFLF
ICS9LPRS502PGLFT	ICS9LPRS514HGLF	ICS9LPRS917CGLFT	ICS9P960AFLFT
ICS9LPRS502SFLF	ICS9LPRS514JGLF	ICS9LPRS917JGLF	ICS9P961AFLF
ICS9LPRS502SFLFT	ICS9LPRS514JGLFT	ICS9LPRS917JGLFT	ICS9P961AFLFT
ICS9LPRS502SGLF	ICS9LPRS535AFLF	ICS9LPRS926AGLF	ICS9UM700AGLF
ICS9LPRS502SGLFT	ICS9LPRS552AGLF	ICS9LPRS926AGLFT	ICS9UM700AGLFT
ICS9LPRS508EGLF	ICS9LPRS552AGLFT	ICS9LPRS926EGLF	ICS9UM700BGLF
ICS9LPRS508EGLFT	ICS9LPRS552BGLF	ICS9LPRS926EGLFT	ICS9UM700BGLFT
ICS9LPRS509CGLF	ICS9LPRS552BGLFT	ICS9LPRS926HGLF	ICS9UM700CGLF
ICS9LPRS509CGLFT	ICS9LPRS582AGLF	ICS9LPRS926HGLFT	ICS9UM700CGLFT
ICS9LPRS509EGLF	ICS9LPRS582AGLFT	ICS9LPRS954AGLF	ICS9UM707AGLF
ICS9LPRS509EGLFT	ICS9LPRS587AGLF	ICS9LPRS954AGLFT	ICS9UM707AGLFT
ICS9LPRS509HGLF	ICS9LPRS587AGLFT	ICS9LPRS954BGLF	ICSCLK756J40F
ICS9LPRS509HGLFT	ICS9LPRS587BGLF	ICS9LPRS954BGLFT	ICSCLK756J40FLF
ICS9LPRS509JGLF	ICS9LPRS587BGLFT	ICS9LPRS954CGLF	ICSCLK756J40FLFT
ICS9LPRS509JGLFT	ICS9LPRS587CGLF	ICS9LPRS954CGLFT	ICSCLK756J40FT
ICS9LPRS509PGLF	ICS9LPRS587CGLFT	ICS9LPRS954DGLF	ICSCLK865J02F
ICS9LPRS509PGLFT	ICS9LPRS587DGLF	ICS9LPRS954DGLFT	ICSCLK865J02FLF
ICS9LPRS510CGLF	ICS9LPRS587DGLFT	ICS9LPRS987BGLF	ICSCLK865J02FLFT
ICS9LPRS510CGLFT	ICS9LPRS587EGLF	ICS9LPRS987BGLFT	ICSCLK865J02FT
ICS9LPRS510EGLF	ICS9LPRS587EGLFT	ICS9LPRS988AGLF	IDTCV107EPVG
ICS9LPRS510EGLFT	ICS9LPRS588CGLF	ICS9LPRS988AGLFT	IDTCV107EPVG8
ICS9LPRS510HGLF	ICS9LPRS588CGLFT	ICS9LRS954A3GLF	IDTCV110JPA
ICS9LPRS510HGLFT	ICS9LPRS588DGLF	ICS9LRS954A3GLFT	IDTCV110JPA8
ICS9LPRS510JGLF	ICS9LPRS588DGLFT	ICS9LRS954A4GLF	IDTCV110JPV
ICS9LPRS510JGLFT	ICS9LPRS590AGLF	ICS9LRS954A4GLFT	IDTCV110JPV8
ICS9LPRS511CGLF	ICS9LPRS590AGLFT	ICS9P750CGLF	IDTCV110JPVG
ICS9LPRS511CGLFT	ICS9LPRS608BGLF	ICS9P750CGLFT	IDTCV110JPVG8
ICS9LPRS511EG-SM0LF	ICS9LPRS608BGLFT	ICS9P932BF	IDTCV110LPV
ICS9LPRS511EG-SM0LFT	ICS9LPRS704AGLF	ICS9P932CF	IDTCV110LPV8
ICS9LPRS511EGLF	ICS9LPRS704AGLFT	ICS9P932CFLF	IDTCV110LPVG
ICS9LPRS511EGLFT	ICS9LPRS808AFLF	ICS9P932CFLFT	IDTCV110LPVG8
ICS9LPRS511HGLF	ICS9LPRS808AFLFT	ICS9P932CFT	IDTCV110NPAG
ICS9LPRS511HGLFT	ICS9LPRS808AGLF	ICS9P933DF	IDTCV110NPAG8
ICS9LPRS511JGLF	ICS9LPRS808AGLFT	ICS9P933DFLF	IDTCV110NPV
ICS9LPRS511JGLFT	ICS9LPRS900AGLF	ICS9P933DFLFT	IDTCV110NPV8
ICS9LPRS512CGLF	ICS9LPRS900AGLFT	ICS9P933DFT	IDTCV110NPVG
ICS9LPRS512CGLFT	ICS9LPRS906BGLF	ICS9P935AGLF	IDTCV110NPVG8
ICS9LPRS512EGLF	ICS9LPRS906BGLFT	ICS9P935AGLFT	IDTCV111IPAG
ICS9LPRS512EGLFT	ICS9LPRS906CGLF	ICS9P936AGLF	IDTCV112-3PGG
ICS9LPRS512HGLF	ICS9LPRS906CGLFT	ICS9P936AGLFT	IDTCV112-3PGG8
ICS9LPRS512HGLFT	ICS9LPRS908CGLF	ICS9P939AGLF	IDTCV115-2PV
ICS9LPRS512JGLF	ICS9LPRS908CGLFT	ICS9P939AGLFT	IDTCV115-2PV8

ATTACHMENT 2 - PCN # : A0807-02

Affected Part Number, except 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

IDTCV115-2PVG	IDTCV146PV8	IDTCV190APAG8	IDTQS3257S18
IDTCV115-2PVG8	IDTCV146PVG	IDTCV190BPAG	IDTQS3257S1G
IDTCV115-4PV	IDTCV146PVG8	IDTCV190BPAG8	IDTQS3257S1G8
IDTCV115-4PV8	IDTCV147PAG	IDTCV190CPAG	IDTQS3306AS1
IDTCV115-4PVG	IDTCV147PAG8	IDTCV190CPAG8	IDTQS3306AS18
IDTCV115-4PVG8	IDTCV147PVG	IDTCV193APAG	IDTQS3306AS1G
IDTCV115CPV	IDTCV147PVG8	IDTCV193APAG8	IDTQS3306AS1G8
IDTCV115CPV8	IDTCV149PA	IDTCV193BPAG	IDTQS3384PA
IDTCV115CPVG	IDTCV149PA8	IDTCV193BPAG8	IDTQS3384PA8
IDTCV115CPVG8	IDTCV149PAG	IDTCV193CPAG	IDTQS3384PAG
IDTCV115FPV	IDTCV149PAG8	IDTCV193CPAG8	IDTQS3384PAG8
IDTCV115FPV8	IDTCV163CPAG	IDTCV194APAG	IDTQS3390SO
IDTCV115FPVG	IDTCV163CPAG8	IDTCV194APAG8	IDTQS3390SO8
IDTCV115FPVG8	IDTCV165PAG	IDTCV194BPAG	IDTQS3390SOG
IDTCV122CPVG	IDTCV165PAG8	IDTCV194BPAG8	IDTQS3390SOG8
IDTCV122CPVG8	IDTCV166PAG	IDTCV194CPAG	IDTQS3861PA
IDTCV122DPVG	IDTCV166PAG8	IDTCV194CPAG8	IDTQS3861PA8
IDTCV122DPVG8	IDTCV174CPAG	IDTCV195APAG	IDTQS3861PAG
IDTCV123PV	IDTCV174CPAG8	IDTCV195APAG8	IDTQS3861PAG8
IDTCV123PV8	IDTCV174CPVG	IDTNW6005AS	IDTQS3L384PA
IDTCV123PVG	IDTCV174CPVG8	IDTNW6006AS	IDTQS3L384PA8
IDTCV123PVG8	IDTCV179CPAG	IDTNW6006ASG	IDTQS3L384PAG
IDTCV125PA	IDTCV179CPAG8	IDTQS3125S1	IDTQS3L384PAG8
IDTCV125PA8	ICSCV181APAG	IDTQS3125S18	IDTQS3VH125S1
IDTCV125PAG	IDTCV181CPAG	IDTQS3125S1G	IDTQS3VH125S18
IDTCV125PAG8	IDTCV181CPAG8	IDTQS3125S1G8	IDTQS3VH125S1G
IDTCV132APV	IDTCV181EPAG	IDTQS3126S1	IDTQS3VH125S1G8
IDTCV132APV8	IDTCV181EPAG8	IDTQS3126S18	IDTQS3VH126S1
IDTCV132APVG	ICSCV182APAG	IDTQS3126S1G	IDTQS3VH126S18
IDTCV132APVG8	ICSCV182APVG	IDTQS3126S1G8	IDTQS3VH126S1G
IDTCV132BPVG	IDTCV182EPAG	IDTQS32245PA	IDTQS3VH126S1G8
IDTCV132BPVG8	IDTCV182EPAG8	IDTQS32245PA8	IDTQS3VH16210PA
IDTCV133PA	IDTCV183-1APAG	IDTQS32245PAG	IDTQS3VH16210PA8
IDTCV133PA8	IDTCV183-1APAG8	IDTQS32245PAG8	IDTQS3VH16210PAG
IDTCV133PAG	IDTCV183-1CPAG	IDTQS3244PAG	IDTQS3VH16210PAG8
IDTCV133PAG8	IDTCV183-1CPAG8	IDTQS3244PAG8	IDTQS3VH16211PA
IDTCV136PA	IDTCV183-2APAG	IDTQS3244SO	IDTQS3VH16211PA8
IDTCV136PA8	IDTCV183-2APAG8	IDTQS3244SO8	IDTQS3VH16211PAG
IDTCV136PAG	IDTCV183-2BPAG	IDTQS3244SOG	IDTQS3VH16211PAG8
IDTCV136PAG8	IDTCV183-2BPAG8	IDTQS3244SOG8	IDTQS3VH16212PA
IDTCV137PA	IDTCV183-2CPAG	IDTQS3245SO	IDTQS3VH16212PA8
IDTCV137PA8	IDTCV183-2CPAG8	IDTQS3245SO8	IDTQS3VH16212PAG
IDTCV137PAG	IDTCV184-2APAG	IDTQS3245SOG	IDTQS3VH16212PAG8
IDTCV137PAG8	IDTCV184-2APAG8	IDTQS3245SOG8	IDTQS3VH16233PA
IDTCV142PA	IDTCV185APAG	IDTQS3251S1	IDTQS3VH16233PA8
IDTCV142PA8	IDTCV185APAG8	IDTQS3251S18	IDTQS3VH16233PAG
IDTCV142PAG	IDTCV186-2APAG	IDTQS3251S1G	IDTQS3VH16233PAG8
IDTCV142PAG8	IDTCV186-2APAG8	IDTQS3251S1G8	IDTQS3VH16244PA
IDTCV144PA	IDTCV186-2BPAG	IDTQS3253S1	IDTQS3VH16244PA8
IDTCV144PA8	IDTCV186-2BPAG8	IDTQS3253S18	IDTQS3VH16244PAG
IDTCV144PAG	IDTCV189BPAG	IDTQS3253S1G	IDTQS3VH16244PAG8
IDTCV144PAG8	IDTCV189BPAG8	IDTQS3253S1G8	IDTQS3VH16245PA
IDTCV146PV	IDTCV190APAG	IDTQS3257S1	IDTQS3VH16245PA8

ATTACHMENT 2 - PCN # : A0807-02

Affected Part Number, except 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

IDTQS3VH16245PAG	IDTQS3VH2245PA	IDTQS3VH245SOG	IDTQS3VH257S1
IDTQS3VH16245PAG8	IDTQS3VH2245PA8	IDTQS3VH245SOG8	IDTQS3VH257S18
IDTQS3VH16800PA	IDTQS3VH2245PAG	IDTQS3VH251PA	IDTQS3VH257S1G
IDTQS3VH16800PA8	IDTQS3VH2245PAG8	IDTQS3VH251PA8	IDTQS3VH257S1G8
IDTQS3VH16800PAG	IDTQS3VH244PA	IDTQS3VH251PAG	IDTQS3VH384PAG
IDTQS3VH16800PAG8	IDTQS3VH244PA8	IDTQS3VH251PAG8	IDTQS3VH384PAG8
IDTQS3VH16861PA	IDTQS3VH244PAG	IDTQS3VH253PA	IDTQS3VH800PA
IDTQS3VH16861PA8	IDTQS3VH244PAG8	IDTQS3VH253PA8	IDTQS3VH800PA8
IDTQS3VH16861PAG	IDTQS3VH245PA	IDTQS3VH253PAG	IDTQS3VH800PAG
IDTQS3VH16861PAG8	IDTQS3VH245PA8	IDTQS3VH253PAG8	IDTQS3VH800PAG8
IDTQS3VH16862PA	IDTQS3VH245PAG	IDTQS3VH257PA	IDTSP0001AS
IDTQS3VH16862PA8	IDTQS3VH245PAG8	IDTQS3VH257PA8	IDTSP306DC
IDTQS3VH16862PAG	IDTQS3VH245SO	IDTQS3VH257PAG	
IDTQS3VH16862PAG8	IDTQS3VH245SO8	IDTQS3VH257PAG8	

ATTACHMENT 2a - PCN # : A0807-02

Affected Part Number on 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

ICS9250BGI-27LFT	ICS954127BGLFT	ICS9LPR600AGLFT	ICS9LPRS512EGLF
ICS950810CGLF	ICS954141AGLF	ICS9LPR600BGLF	ICS9LPRS512EGLFT
ICS950810CGLFT	ICS954141BGLF	ICS9LPR600BGLFT	ICS9LPRS512HGLF
ICS950810PGLF	ICS954148AGLF	ICS9LPR600CGLF	ICS9LPRS512HGLFT
ICS950812CGLFT-IB0	ICS954148AGLFT	ICS9LPR600DGLF	ICS9LPRS512JGLF
ICS950813CGLF	ICS954201AGLN	ICS9LPR601BGLF	ICS9LPRS512JGLFT
ICS950813CGLFT	ICS954201AGLNT	ICS9LPR601BGLFT	ICS9LPRS513CGLF
ICS950819AGLF	ICS954201BGLF	ICS9LPR780BGLF	ICS9LPRS513CGLFT
ICS950819AGLFT	ICS954201BGLFT	ICS9LPR780BGLFT	ICS9LPRS513EGLF
ICS950822AGLF	ICS954204AGLN	ICS9LPR803AGLF	ICS9LPRS513HGLF
ICS950822AGLFT	ICS954204AGLNT	ICS9LPR803AGLFT	ICS9LPRS513HGLFT
ICS950826AGLF	ICS954204BGLF	ICS9LPRS136BGLF	ICS9LPRS513JGLF
ICS950826AGLFT	ICS954204BGLFT	ICS9LPRS136BGLFT	ICS9LPRS513JGLFT
ICS950913CGLF	ICS954204BGLN	ICS9LPRS137AGLF	ICS9LPRS808AGLFT
ICS951104BGLF	ICS954204BGLNT	ICS9LPRS137AGLFT	ICS9LPRS954AGLF
ICS951411BGLF	ICS954204CGLF	ICS9LPRS146AGLF	ICS9LPRS954AGLFT
ICS951411CGLF	ICS954204CGLFT	ICS9LPRS146AGLFT	ICS9LPRS954BGLF
ICS951411CGLFT	ICS954206BGLF	ICS9LPRS154AGLF	ICS9LPRS954CGLF
ICS951412AGLF	ICS954215AGLF	ICS9LPRS154AGLFT	ICS9LPRS954CGLFT
ICS951413CGLF	ICS954217AGLF	ICS9LPRS418DGLF	ICS9LPRS954DGLF
ICS951413CGLFT	ICS954217AGLFT	ICS9LPRS418DGLFT	ICS9LPRS954DGLFT
ICS951416AGLF	ICS954218BGLF	ICS9LPRS419BGLF	ICS9LPRS988AGLF
ICS951417AGLF	ICS954226AGLF	ICS9LPRS419BGLFT	ICS9LPRS988AGLFT
ICS951417AGLFT	ICS954226AGLFT	ICS9LPRS419DGLF	ICS9LRS954A3GLF
ICS951418BGLF	ICS954227AGLF	ICS9LPRS419DGLFT	ICS9LRS954A3GLFT
ICS951418CGLF	ICS954227BGLF	ICS9LPRS420DGLF	ICS9LRS954A4GLF
ICS951421AGLF	ICS954227CGLF	ICS9LPRS420DGLFT	ICS9LRS954A4GLFT
ICS951421AGLFT	ICS954229AGLF	ICS9LPRS424DGLF	ICS9UM700AGLF
ICS951422AGLF	ICS954230AGLF	ICS9LPRS424DGLFT	ICS9UM700AGLFT
ICS951446AGLF	ICS954230AGLFT	ICS9LPRS427AGLFT	ICS9UM700BGLFT
ICS951446AGLFT	ICS954238AGLF	ICS9LPRS434AGLF	ICS9UM700CGLF
ICS951461BGLF	ICS954238AGLFT	ICS9LPRS434AGLFT	ICSCV182APAG
ICS951461BGLFT	ICS954270AGLF	ICS9LPRS437AGLFT	IDT74ALVCH16260PAG
ICS951462AGLF-DT0	ICS954270AGLFT	ICS9LPRS438AGLFT	IDT74ALVCH16260PAG8
ICS951462AGLFT-DT0	ICS9LP208AGLF	ICS9LPRS439AGLFT	IDT74ALVCH162820PAG
ICS951463BGLF	ICS9LP505-2EGLF	ICS9LPRS475AGLF	IDT74ALVCH162820PAG8
ICS951463BGLFT	ICS9LP505-2EGLFT	ICS9LPRS475AGLFT	IDT74ALVCH16501PAG
ICS951463CGLF	ICS9LP505-2HGLF	ICS9LPRS479BGLF	IDT74ALVCH16501PAG8
ICS951464AGLF	ICS9LP505-2HGLFT	ICS9LPRS479BGLFT	IDT74ALVCH16721PAG
ICS951464AGLFT	ICS9LP505-2JGLF	ICS9LPRS485AGLF	IDT74ALVCH16721PAG8
ICS951464BGLF	ICS9LP505-2JGLFT	ICS9LPRS485AGLFT	IDT74ALVCH16823PAG
ICS951464BGLFT	ICS9LP505-2PGLF	ICS9LPRS485BGLF	IDT74ALVCH16823PAG8
ICS951702AGLF	ICS9LP505-2PGLFT	ICS9LPRS485CGLF	IDT74ALVCH16863PAG
ICS951702AGLFT	ICS9LPR229AGLF	ICS9LPRS485CGLFT	IDT74ALVCH16863PAG8
ICS952508BGLF	ICS9LPR362AGLF	ICS9LPRS502HGLF	IDT74ALVCH16901PAG
ICS952508BGLFT	ICS9LPR362AGLFT	ICS9LPRS502PGLF	IDT74ALVCH16901PAG8
ICS952601EGLF	ICS9LPR426BGLFT	ICS9LPRS502SGLF	IDT74ALVCH16903PAG
ICS952601EGLFT	ICS9LPR463AGLF	ICS9LPRS502SGLFT	IDT74ALVCH16903PAG8
ICS953009AGLF	ICS9LPR463AGLFT	ICS9LPRS508EGLF	IDT74ALVCHR16601PAG
ICS953805CGLF	ICS9LPR502CGLF	ICS9LPRS508EGLFT	IDT74ALVCHR16601PAG8
ICS953805CGLFT	ICS9LPR502CGLFT	ICS9LPRS509PGLF	IDT74CBTLV16211PAG
ICS954123CGLF	ICS9LPR502SGLFT	ICS9LPRS509PGLFT	IDT74CBTLV16211PAG8
ICS954127BGLF	ICS9LPR600AGLF	ICS9LPRS512CGLFT	IDT74CBTLV16212PAG

ATTACHMENT 2a - PCN # : A0807-02

Affected Part Number on 6.1 mm TSSOP 56 and 64 at Unisem, Indonesia.

IDT74CBTLV16212PAG8	IDT74FCT163827CPAG	IDT74LVC16823APAG8	IDTCV182EPAG8
IDT74CBTLV16292PAG	IDT74FCT163827CPAG8	IDT74LVC16827APAG	IDTCV184-2APAG
IDT74CBTLV16292PAG8	IDT74FCT16501ATPAG	IDT74LVC16827APAG8	IDTCV184-2APAG8
IDT74FCT162501ATPAG	IDT74FCT16501ATPAG8	IDT74LVCH16543APAG	IDTCV185APAG
IDT74FCT162501ATPAG8	IDT74FCT16501CTPAG	IDT74LVCH16543APAG8	IDTCV185APAG8
IDT74FCT162501CTPAG	IDT74FCT16501CTPAG8	IDT74LVCH16646APAG	IDTCV186-2BPAG
IDT74FCT162501CTPAG8	IDT74FCT16543ATPAG	IDT74LVCH16646APAG8	IDTCV186-2BPAG8
IDT74FCT162511ATPAG	IDT74FCT16543ATPAG8	IDT74LVCHR16646APAG	IDTCV190APAG
IDT74FCT162511ATPAG8	IDT74FCT16543CTPAG	IDT74LVCHR16646APAG8	IDTCV190APAG8
IDT74FCT162511CTPAG	IDT74FCT16543CTPAG8	IDTCV110NPAG	IDTCV190BPAG
IDT74FCT162511CTPAG8	IDT74FCT16543ETPAG	IDTCV110NPAG8	IDTCV190BPAG8
IDT74FCT162823ATPAG	IDT74FCT16543ETPAG8	IDTCV133PAG	IDTCV194APAG
IDT74FCT162823ATPAG8	IDT74FCT16952ATPAG	IDTCV136PAG	IDTCV194APAG8
IDT74FCT162823CTPAG	IDT74FCT16952ATPAG8	IDTCV137PAG	IDTCV194BPAG
IDT74FCT162823CTPAG8	IDT74FCT16952CTPAG	IDTCV142PAG	IDTCV194BPAG8
IDT74FCT162827ATPAG	IDT74FCT16952CTPAG8	IDTCV142PAG8	IDTCV194CPAG
IDT74FCT162827ATPAG8	IDT74FCT16952ETPAG	IDTCV144PAG	IDTCV194CPAG8
IDT74FCT162827CTPAG	IDT74FCT16952ETPAG8	IDTCV144PAG8	IDTQS3VH16211PAG
IDT74FCT162827CTPAG8	IDT74LVC16344APAG	IDTCV147PAG	IDTQS3VH16211PAG8
IDT74FCT163344APAG	IDT74LVC16344APAG8	IDTCV147PAG8	IDTQS3VH16212PAG
IDT74FCT163344APAG8	IDT74LVC16501APAG	IDTCV149PAG	IDTQS3VH16212PAG8
IDT74FCT163344CPAG	IDT74LVC16501APAG8	IDTCV149PAG8	IDTQS3VH16233PAG
IDT74FCT163344CPAG8	IDT74LVC16601APAG	IDTCV174CPAG	IDTQS3VH16233PAG8
IDT74FCT163827APAG	IDT74LVC16601APAG8	IDTCV174CPAG8	
IDT74FCT163827APAG8	IDT74LVC16823APAG	IDTCV182EPAG	