

May 25, 2018

PCN

Relocation of EPCOS plant within Hongqi

The Hongqi plant – EPCOS (Zhuhai) Co., Ltd. – will be relocated to a new production site within the same Jinwan district (Zhuhai City) from North Honghui Second Road, Hongqi Town, to Liangang Industrial Zone, Hongqi Town. The new Liangang Building is located approximately five kilometers from the current site.

Affected products see Annex

Scheduled date of introduction: August 1, 2019

Shipments of the components produced in new plant are scheduled to begin on September 2, 2019. EPCOS does not expect any effect on the specified electrical and mechanical parameters of the products.

Product families will be qualified based on representative types according to the qualification plan.

In a first step the representative lines will be transferred. Qualification and release procedures will be performed completely based on these lines. The transfer and release of all remaining lines will take place under the responsibility of EPCOS.

Enclosure PCN (ID No. MAG-506150518)

Contact René Steinbrecher, MAG TF T PM, Munich

Customers are asked to address inquiries directly to their sales contacts.

Product / Process Change Notification

| | | | |
|---|--|--|------------------------------|
| 1. ID No.: MAG-506150518 | | 2. Date of announcement: May 25, 2018 | |
| 3. Product / product group: Transformers Wound inductors Signal EMC components Power EMC filters | Old ordering code: See enclosure | New ordering code: No change | Customer part number: |
| 4. Description of change: The Hongqi plant – EPCOS (Zhuhai) Co., Ltd. – will be relocated to a new production site within the same Jinwan district (Zhuhai City) from North Honghui Second Road, Hongqi Town, to Liangang Industrial Zone, Hongqi Town. The new Liangang Building is located approximately five kilometers from the current site. | | | |
| 5. Effect on the product or for the customer (benefit, quality, specification, lead time): EPCOS does not expect any effect on the specified electrical and mechanical parameters of the products. Shipments from new location can be identified by product label. | | | |
| 6. Quality assurance measures / risk assessment: Requalification of product families based on representative types according to the qualification plan. All quality related processes and regulation will be unchanged at the new location. | | | |
| 7. Scheduled date of change: August 1, 2019 | | | |
| 8. Estimated date of first delivery of changed product: September 2, 2019 If EPCOS does not receive notification to the contrary within a period of 10 weeks, EPCOS assumes that the customer agrees to the change. For an interim period we cannot rule out that old as well as new products will be shipped. | | | |
| Quality Management Name Wolfgang Woitsch, 2018-05-15 | | Signature signed Woitsch | |
| Product Marketing Name René Steinbrecher Tel. +49 89 54020-3205 Email Rene.Steinbrecher@epcos.com | | Signature signed Steinbrecher | |
| Customer feedback | | | |
| Customer acknowledgement | | Signature | |

**Annex to UPtoDATE 180525IN1 of May 25, 2018 /
Relocation of EPCOS plant within Hongqi**

Affected products

| Ordering code | Ordering code | Ordering code | Ordering code | Ordering code | Ordering code | Ordering code |
|---------------|---------------|---------------|---------------|---------------|---------------|---------------|
| B78030S* | B78364A* | B78528P* | B82559A* | B82802A* | B84742J* | B86914P* |
| B78302A* | B78381A* | B78529P* | B82559B* | B82804A* | B84742K* | B86923L* |
| B78304A* | B78381B* | B78536P* | B82559C* | B82805A* | B84743A* | ACM12* |
| B78304B* | B78381P* | B78545A* | B82559S* | B82806D* | B84743B* | ACM15* |
| B78306A* | B78384P* | B78546A* | B82600C* | B82891S* | B84743C* | ACM70* |
| B78307A* | B78386P* | B78546P* | B82602C* | B84111F* | B84743D* | ACM90* |
| B78307P* | B78387A* | B78547A* | B82602S* | B84111S* | B84743F* | |
| B78308A* | B78387P* | B78547P* | B82603S* | B84112A* | B84743K* | |
| B78308P* | B78388P* | B78547Q* | B82604S* | B84112G* | B84743M* | |
| B78308Q* | B78388R* | B78553P* | B82622A* | B84113H* | B84743T* | |
| B78310A* | B78390A* | B78555A* | B82622S* | B84131M* | B84743U* | |
| B78310B* | B78392P* | B78555P* | B82720A* | B84132A* | B84744A* | |
| B78310P* | B78394P* | B78555Q* | B82720H* | B84132L* | B84771A* | |
| B78311A* | B78416A* | B78558P* | B82720K* | B84132M* | B84771C* | |
| B78311P* | B78416B* | B78559P* | B82720S* | B84132N* | B84771M* | |
| B78311Q* | B78416D* | B78559Q* | B82721S* | B84134A* | B84773A* | |
| B78313P* | B78417A* | B82451L* | B82722A* | B84142A* | B84773M* | |
| B78313Q* | B78417C* | B82451N* | B82722S* | B84142B* | B84776A* | |
| B78315P* | B78418A* | B82457R* | B82723A* | B84142C* | B84776M* | |
| B78319P* | B78419A* | B82459R* | B82723S* | B84142J* | B85121A* | |
| B78322A* | B78421A* | B82464P* | B82724N* | B84143A* | B85121B* | |
| B78324A* | B78421B* | B82471A* | B82724S* | B84143B* | B85321A* | |
| B78326A* | B78423P* | B82472G* | B82730G* | B84143C* | B85821B* | |
| B78326P* | B78432P* | B82472P* | B82730U* | B84143D* | B86132D* | |
| B78328P* | B78438P* | B82473A* | B82731T* | B84143G* | B86132E* | |
| B78332A* | B78446A* | B82473B* | B82732F* | B84143K* | B86134A* | |
| B78334A* | B78446B* | B82473M* | B82733F* | B84143N* | B86232G* | |
| B78334B* | B78450P* | B82475A* | B82733V* | B84143S* | B86301U* | |
| B78336A* | B78452P* | B82475B* | B82790C* | B84143U* | B86305A* | |
| B78337A* | B78476A* | B82475M* | B82790S* | B84143V* | B86305C* | |
| B78337P* | B78476B* | B82476A* | B82791G* | B84144A* | B86305H* | |
| B78338A* | B78476P* | B82476B* | B82791H* | B84144B* | B86305L* | |
| B78338P* | B78506A* | B82476S* | B82791K* | B84144E* | B86305P* | |
| B78338Q* | B78507P* | B82477B* | B82792C* | B84243A* | B86307P* | |
| B78342A* | B78508A* | B82477C* | B82792S* | B84246A* | B86310C* | |
| B78343A* | B78509A* | B82477D* | B82793C* | B84551A* | B86314P* | |
| B78343B* | B78510A* | B82477G* | B82793D* | B84712A* | B86334A* | |
| B78344A* | B78510P* | B82477P* | B82793F* | B84713A* | B86707P* | |
| B78345A* | B78512A* | B82477R* | B82793S* | B84713D* | B86714P* | |
| B78345B* | B78512P* | B82477U* | B82794C* | B84713H* | B86722B* | |
| B78346P* | B78513P* | B82478A* | B82794S* | B84732A* | B86732G* | |
| B78348A* | B78516P* | B82479A* | B82795A* | B84742A* | B86903L* | |
| B78360P* | B78518P* | B82479E* | B82801A* | B84742B* | B86904S* | |
| B78362A* | B78520A* | B82479G* | B82801B* | B84742C* | B86905L* | |
| B78363A* | B78522P* | B82479S* | B82801C* | B84742F* | B86907P* | |