

# Engineering Change Notice

Part No. <u>3002</u>	ECN No. <u>16-050</u>
Part Name <u>COIN CELL RETAINER</u>	Date <u>5.04.16</u>
Rev. <u>R</u>	ECR No. <u>—</u>

Description of Change:  Drawing Attached

POLARITY "PLUS" STAMP WAS POORLY VISIBLE ON THE PART.  
CUT PLUS STAMP THRU MATERIAL TO SOLVE THE PROBLEM

Solution:  Tooling Change Required

REVISE C+M DWGS

Disposition of Parts:

U.A.I.

Signed \_\_\_\_\_ Date 5.04.16

Required Distribution:

Engineering     Quality Control     Purchasing     Manufacturing/Supplier

Chief Engineer: \_\_\_\_\_ Remarks: \_\_\_\_\_

Signed \_\_\_\_\_ Date 5.04.16

Document Control: \_\_\_\_\_ Rev. S

Change Incorporated    Signed \_\_\_\_\_ Date 5.04.16