

Chi Lick Schurter Ltd.

7/F., Lin Fung Centre, No. 184-186 Texaco Road,
Tsuen Wan, N.T., Hong Kong

Tel: (852) 2408-7798
Fax: (852) 2408-7001
Internet: <http://www.chilickschurter.com>

致：客戶

由：自力迅達有限公司工程部

日期：01/11/2020

有關產品變更通知

我方產品有以下的工程變更，詳細如下：

產品：SBS 系列 BS1362 保險絲

P/N：8350.0001, 8350.0002, 8350.0003, 8350.0004, 8350.0005, 8350.0006, 8350.0007

變更：

1. NEMKO 及 HKSI 認證證書取消
2. 產品本體上的認證印字會把 NEMKO 及 HKSI 標誌取消

生效日期：2021 年 1 月 1 日開始生產

請客戶進行相關產品變更管流程。

以上請知悉！如對上述有任何疑問，或需要，請與業務部同事聯絡查詢，謝謝！

新



舊



Chi Lick Schurter Ltd.

7/F., Lin Fung Centre, No. 184-186 Texaco Road,
Tsuen Wan, N.T., Hong Kong

Tel: (852) 2408-7798
Fax: (852) 2408-7001
Internet: <http://www.chilickschurter.com>

TO : Customer

FROM : Engineering Department/ Chi Lick Schurter Limited

DATE : 06/11/2020

Regarding the change of part number

Kindly please note that we will have an engineering change on our product, details as below.

Affected product: SBS series BS1362 Fuse

P/N: 8350.0001, 8350.0002, 8350.0003, 8350.0004, 8350.0005, 8350.0006, 8350.0007

Type of change:

1. Termination of NEMKO and HKSI approval certificates;
2. The NEMKO and HKSI approval mark will be removed from the fuse body..

Effective date: Release for production from Week1 2021

Customers please have the relevant ECN process for the change.

If there are further enquiries or samples are requested for ECN process, kindly please contact our salesmen. Thank you for your attention.

New marking



Old marking

