

End Of Life Notice
(Notification – PLC18018)
[06 July 2018]

To: Our Valued Customers

Overview: The purpose of this notification is to communicate that Renesas Electronics has begun the End-of-Life (EOL) Process on select part numbers.

Affected

Products: Attached is a list of products affected by this notification.

Part numbers given in the attached list are for active part numbers in the Renesas Electronics database at the time of this notification.

Key Dates:

Standard Product	
Final Last Time Buy (LTB) Orders placed after this date will not be processed.	06-Jan-19
Last Shipment (LTS)	06-July-19
Custom / Proprietary Product	
Final Last Time Buy (LTB) Orders placed after this date will not be processed.	06-July-19
Last Shipment (LTS)	06-Jan-20

Response: Please place LTB orders in a timely manner prior to the key dates listed to avoid product availability issues. Shipments between the LTB and LTS dates are Non-Cancelable and Non-Returnable (NCNR).

Any order resulting from this notice shall be governed by Renesas's General Terms and Conditions Available at: [General Term and Conditions](#) or the applicable legal terms covering the purchase and sale transaction.

Please work with your sales representative or Field Applications Engineer to determine suitable replacement devices.

Please contact your local sales representative or Central Applications @ 1-888-468-3774 for any questions or comments.

Thank you for your attention.

Sincerely,

Renesas Electronics

Exact Intersil Part # No other variation is being impacted.	Notice PLC18018 Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re-Design
CA5420AMZ96R5428	6-Jul-18	6-Jan-19	6-Jul-19	CA5420AMZ96
CA5420AMZR5428	6-Jul-18	6-Jan-19	6-Jul-19	CA5420AMZ
CD22M3494MQAZ	6-Jul-18	6-Jan-19	6-Jul-19	CD22M3494MQZ
CD22M3494MQAZ96	6-Jul-18	6-Jan-19	6-Jul-19	CD22M3494MQZ96
DG442DJZ	6-Jul-18	6-Jan-19	6-Jul-19	DG442DYZ
EL7232CNZ	6-Jul-18	6-Jan-19	6-Jul-19	EL7232CSZ
EL7242CNZ	6-Jul-18	6-Jan-19	6-Jul-19	EL7242CSZ
HC55183ECMZ	6-Jul-18	6-Jul-19	6-Jan-20	HC55185DIMZ
HC55183ECMZ96	6-Jul-18	6-Jul-19	6-Jan-20	HC55185DIMZ96
HC55184ECMZ	6-Jul-18	6-Jul-19	6-Jan-20	HC55185DIMZ
HC55184ECMZ96	6-Jul-18	6-Jul-19	6-Jan-20	HC55185DIMZ96
HC55184ECMZR4749	6-Jul-18	6-Jul-19	6-Jan-20	HC55184ECMZ96R4749
HC55185AIMZ	6-Jul-18	6-Jul-19	6-Jan-20	HC55185DIMZ
HC55185AIMZ96	6-Jul-18	6-Jul-19	6-Jan-20	HC55185DIMZ96
HC55185AIMZ96S2705	6-Jul-18	6-Jul-19	6-Jan-20	HC55185DIMZ96
HC55185BIMZ	6-Jul-18	6-Jul-19	6-Jan-20	HC55185DIMZ
HC55185BIMZ96	6-Jul-18	6-Jul-19	6-Jan-20	HC55185DIMZ96
HC55185FCMZ	6-Jul-18	6-Jul-19	6-Jan-20	HC55185DIMZ
HC55185FCMZ96	6-Jul-18	6-Jul-19	6-Jan-20	HC55185DIMZ96
HI3-0201HS-5Z	6-Jul-18	6-Jan-19	6-Jul-19	HI9P0201HS-5Z
HI3-0549-5Z	6-Jul-18	6-Jan-19	6-Jul-19	HI9P0549-9Z
HI3-5043-5Z	6-Jul-18	6-Jan-19	6-Jul-19	HI9P5043-5Z
HI7190IPZ	6-Jul-18	6-Jul-19	6-Jan-20	HI7190IBZ
HI7191IPZ	6-Jul-18	6-Jul-19	6-Jan-20	HI7191IBZ
HIN202CBNZ-TS2490	6-Jul-18	6-Jan-19	6-Jul-19	HIN202CBNZ-T
HIN202CBNZ-TS2705	6-Jul-18	6-Jul-19	6-Jan-20	HIN202CBNZ-T
HIN202CPZ	6-Jul-18	6-Jan-19	6-Jul-19	HIN202ECPZ
HIN202EIBNZ-TR5661	6-Jul-18	6-Jan-19	6-Jul-19	HIN202EIBNZ-T
HIN207ECAZ	6-Jul-18	6-Jan-19	6-Jul-19	HIN208EIAZ
HIN207ECAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	HIN208EIAZ-T
HIN207ECBZ	6-Jul-18	6-Jan-19	6-Jul-19	HIN208ECBZ
HIN207ECBZ-T	6-Jul-18	6-Jan-19	6-Jul-19	HIN208ECBZ-T
HIN207EIAZ	6-Jul-18	6-Jan-19	6-Jul-19	HIN208EIAZ
HIN207EIAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	HIN208EIAZ-T
HIN207EIBZ	6-Jul-18	6-Jan-19	6-Jul-19	HIN208EIBZ
HIN207EIBZ-T	6-Jul-18	6-Jan-19	6-Jul-19	HIN208EIBZ
HIN208ECAZA-TS2490	6-Jul-18	6-Jan-19	6-Jul-19	HIN208ECAZ-T

Exact Intersil Part # No other variation is being impacted.	Notice PLC18018 Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re-Design
HIN213ECAZR5194	6-Jul-18	6-Jan-19	6-Jul-19	HIN213EIAZ
HIN213ECAZ-TR5194	6-Jul-18	6-Jan-19	6-Jul-19	HIN213EIAZ-T
HIN232ACBZ	6-Jul-18	6-Jan-19	6-Jul-19	HIN232ECBZ
HIN232ACBZ-T	6-Jul-18	6-Jan-19	6-Jul-19	HIN232ECBZ-T
HIN232ECBNZ	6-Jul-18	6-Jan-19	6-Jul-19	HIN232ACBNZ
HIN232ECBNZ-T	6-Jul-18	6-Jan-19	6-Jul-19	HIN232ACBNZ-T
HIN238CBZ	6-Jul-18	6-Jan-19	6-Jul-19	HIN238IBZ
HIN238CBZ-T	6-Jul-18	6-Jan-19	6-Jul-19	HIN238IBZ-T
HIP6006CBZ	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6006CBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6006CBZ-TS2462	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6006CBZ-TS2705	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6006EVAL1	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6012CBZ	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6012CBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6012EVAL1	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6302CBZ	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6302CBZA	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6302CBZA-T	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6302CBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6302EVAL1	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6601BCBZ	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6601BCBZA	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6601BCBZA-T	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6601BCBZA-TS2568	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6601BCBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6601BCBZ-TS2705	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6603BCBZ	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6603BCBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	none
HIP6603BCBZ-TR5250	6-Jul-18	6-Jul-19	6-Jan-20	none
HVS1500A3	6-Jul-18	6-Jul-19	6-Jan-20	none
HVS1510A3	6-Jul-18	6-Jul-19	6-Jan-20	none
HVS1518A3	6-Jul-18	6-Jul-19	6-Jan-20	none
HVS1525A3	6-Jul-18	6-Jul-19	6-Jan-20	none
HVS1540A3	6-Jul-18	6-Jul-19	6-Jan-20	none
HVS1541A3	6-Jul-18	6-Jul-19	6-Jan-20	none
HVS1546A3	6-Jul-18	6-Jul-19	6-Jan-20	none

Exact Intersil Part # No other variation is being impacted.	Notice PLC18018 Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re-Design
ICL232CBEZTS2705	6-Jul-18	6-Jul-19	6-Jan-20	ICL232CBEZ
ICL3207CAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3207ECAZ
ICL3207CAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3207ECAZ-T
ICL3207CBZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3207ECBZ
ICL3207CBZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3207ECBZ-T
ICL3221CVZ-T7	6-Jul-18	6-Jan-19	6-Jul-19	ICL3221CVZ-T
ICL3222CAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3222ECAZ
ICL3222CAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3222ECAZ-T
ICL3222CBZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3222EIBZ
ICL3222CBZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3222EIBZ-T
ICL3222ECVZ-TS2705	6-Jul-18	6-Jul-19	6-Jan-20	ICL3222CVZ-TS2705
ICL3222IAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3222EIAZ
ICL3222IAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3222EIAZ-T
ICL3222IVZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3222EIVZ
ICL3222IVZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3222EIVZ-T
ICL3223CAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3223ECAZ
ICL3223CAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3223ECAZ-T
ICL3223CAZ-TS2490	6-Jul-18	6-Jan-19	6-Jul-19	ICL3223ECAZ-TS2490
ICL3223ECVZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3222EIVZ
ICL3223ECVZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3222EIVZ-T
ICL3224CAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3224EIAZ
ICL3224CAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3224EIAZ-T
ICL3224CAZ-TS2705	6-Jul-18	6-Jul-19	6-Jan-20	ICL3224EIAZ-T
ICL3224ECAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3224EIAZ
ICL3224ECAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3224EIAZ-T
ICL3224EIAZ-TS2705	6-Jul-18	6-Jul-19	6-Jan-20	ICL3224EIAZ-T
ICL3224IAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3224EIAZ
ICL3224IAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3224EIAZ-T
ICL3225CAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3225ECAZ
ICL3225CAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3225ECAZ-T
ICL3225IAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3225EIAZ
ICL3225IAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3225EIAZ-T
ICL3226CAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3226EIAZ
ICL3226CAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3226EIAZ-T
ICL3226ECAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3226EIAZ
ICL3226ECAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3226EIAZ-T
ICL3232CAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3232ECAZ

Exact Intersil Part # No other variation is being impacted.	Notice PLC18018 Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re-Design
ICL3232CAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3232ECAZ-T
ICL3232CBZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3232ECBZ
ICL3232CBZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3232ECBZ-T
ICL3232ECV-20Z	6-Jul-18	6-Jan-19	6-Jul-19	ICL3232EIV-16Z
ICL3232ECV-20ZT	6-Jul-18	6-Jan-19	6-Jul-19	ICL3232EIV-16Z-T
ICL3232EFV-16Z	6-Jul-18	6-Jan-19	6-Jul-19	ICL3232EIV-16Z
ICL3232EFV-16Z-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3232EIV-16Z-T
ICL3232IAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3232EIAZ
ICL3232IAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3232EIAZ-T
ICL3232IBZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3232EIBZ
ICL3232IBZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3232EIBZ-T
ICL3238CAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3238EIAZ
ICL3238CAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3238EIAZ-T
ICL3238ECAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3238EIAZ
ICL3238ECAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3238EIAZ-T
ICL3238IAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3238EIAZ
ICL3238IAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3238EIAZ-T
ICL3241CAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3241ECAZ
ICL3241CAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3241ECAZ-T
ICL3241CVZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3241ECVZ
ICL3241CVZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3241ECVZ-T
ICL3241EIAZ-TS2705A	6-Jul-18	6-Jul-19	6-Jan-20	ICL3241EIAZ-T
ICL3241IAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3241EIAZ
ICL3241IAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3241EIAZ-T
ICL3243CAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3243ECAZ
ICL3243CAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3243ECAZ-T
ICL3243CVZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3243ECVZ
ICL3243CVZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3243ECVZ-T
ICL3243IAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3243EIAZ
ICL3243IAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3243EIAZ-T
ICL3244ECAZ	6-Jul-18	6-Jan-19	6-Jul-19	ICL3244EIAZ
ICL3244ECAZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ICL3244EIAZ-T
ISL1533IRZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL15102IRZ-T13
ISL1533IRZ-T13	6-Jul-18	6-Jul-19	6-Jan-20	ISL15102IRZ-T13
ISL2111ABZR5568	6-Jul-18	6-Jan-19	6-Jul-19	ISL2111ABZ
ISL2111ABZ-TR5568	6-Jul-18	6-Jan-19	6-Jul-19	ISL2111ABZ-T
ISL28107FUZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL28207FBZ

Exact Intersil Part # No other variation is being impacted.	Notice PLC18018 Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re-Design
ISL28107FUZ-T7	6-Jul-18	6-Jul-19	6-Jan-20	ISL28207FBZ-T7
ISL28107FUZ-T7A	6-Jul-18	6-Jul-19	6-Jan-20	ISL28207FBZ-T7A
ISL28158EVAL1Z	6-Jul-18	6-Jan-19	6-Jul-19	
ISL28158FBZ	6-Jul-18	6-Jan-19	6-Jul-19	ISL28130FHZ-T7
ISL28158FBZ-T7	6-Jul-18	6-Jan-19	6-Jul-19	ISL28130FHZ-T7
ISL28158FHZ-T7	6-Jul-18	6-Jan-19	6-Jul-19	ISL28130FHZ-T7
ISL28158FHZ-T7A	6-Jul-18	6-Jan-19	6-Jul-19	ISL28130FHZ-T7
ISL28236FUZ	6-Jul-18	6-Jan-19	6-Jul-19	ISL28236FBZ
ISL28236FUZ-T7	6-Jul-18	6-Jan-19	6-Jul-19	ISL28236FBZ-T7
ISL28236FUZ-T7A	6-Jul-18	6-Jan-19	6-Jul-19	ISL28236FBZ-T7A
ISL28248FUZ-T7S2490	6-Jul-18	6-Jul-19	6-Jan-20	ISL28248FUZ-T7
ISL3152EIPZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL3152EIBZ
ISL3174EIBZ	6-Jul-18	6-Jan-19	6-Jul-19	ISL3177EIBZ
ISL3174EIBZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ISL3177EIBZ-T
ISL43140IBZ	6-Jul-18	6-Jan-19	6-Jul-19	none
ISL43140IBZ-T	6-Jul-18	6-Jan-19	6-Jul-19	none
ISL43140IVZ	6-Jul-18	6-Jan-19	6-Jul-19	none
ISL43140IVZ-T	6-Jul-18	6-Jan-19	6-Jul-19	none
ISL43144IVZR5172	6-Jul-18	6-Jan-19	6-Jul-19	ISL43144IVZ
ISL5761/2IAZ	6-Jul-18	6-Jul-19	6-Jan-20	none
ISL5761IAZ	6-Jul-18	6-Jul-19	6-Jan-20	none
ISL6306CRZA-TS2568	6-Jul-18	6-Jul-19	6-Jan-20	ISL6306CRZ-T
ISL6306CRZ-TS2705	6-Jul-18	6-Jul-19	6-Jan-20	ISL6306CRZ-T
ISL6306IRZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6306CRZ
ISL6306IRZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6306CRZ-T
ISL6439AIBZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6439IBZ
ISL6439AIBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6439IBZ-T
ISL6440IAZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6440IAZ-TK
ISL6526CBZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6526AIRZ
ISL6526CBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6526AIRZ-T
ISL6526IBZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6526AIRZ
ISL6526IBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6526AIRZ-T
ISL6527ACBZ	6-Jul-18	6-Jul-19	6-Jan-20	none
ISL6527ACBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	none
ISL6605CBZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6605IRZ
ISL6605CBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6605IRZ-T
ISL6605CBZ-TR5168	6-Jul-18	6-Jul-19	6-Jan-20	ISL6605IRZ-T

Exact Intersil Part # No other variation is being impacted.	Notice PLC18018 Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re-Design
ISL6605CRZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6605IRZ-T
ISL6605CRZ-TR5168	6-Jul-18	6-Jul-19	6-Jan-20	ISL6605IRZ-T
ISL6605CRZ-TR5453	6-Jul-18	6-Jan-19	6-Jul-19	ISL6605IRZ-T
ISL6605IBZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6605IRZ
ISL6605IBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6605IRZ-T
ISL6605IRZ-TR5453	6-Jul-18	6-Jan-19	6-Jul-19	ISL6605IRZ-T
ISL6605IRZ-TS2779	6-Jul-18	6-Jan-19	6-Jul-19	ISL6605IRZ-T
ISL6609CBZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6609IRZ
ISL6609CBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6609IRZ-T
ISL6609CBZ-TS2705	6-Jul-18	6-Jul-19	6-Jan-20	ISL6609IRZ-T
ISL6609CRZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6609IRZ
ISL6609CRZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6609IRZ-T
ISL6609IBZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6609IRZ
ISL6609IBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6609IRZ-T
ISL6610CBZ	6-Jul-18	6-Jul-19	6-Jan-20	none
ISL6610CBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	none
ISL6612ACBZA-TR5453	6-Jul-18	6-Jan-19	6-Jul-19	ISL6612ACBZA-T
ISL6612ACBZ-TS2568	6-Jul-18	6-Jul-19	6-Jan-20	ISL6612ACBZ-T
ISL6612ACRZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6612ACBZ-T
ISL6612ACRZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6612ACBZ-T
ISL6612AECBZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6612ACBZ-T
ISL6612AECBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6612ACBZ-T
ISL6612BCBZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6613BCRZ-T
ISL6612BCBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6613BCRZ-T
ISL6612BCRZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6613BCRZ-T
ISL6612BCRZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6613BCRZ-T
ISL6612BIRZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6613BCRZ-T
ISL6612BIRZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6613BCRZ-T
ISL6612BIRZ-TR5453	6-Jul-18	6-Jan-19	6-Jul-19	ISL6613BCRZ-T
ISL6612CBZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6612ACBZ-T
ISL6612CBZA	6-Jul-18	6-Jul-19	6-Jan-20	ISL6612ACBZ-T
ISL6612CBZA-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6612ACBZ-T
ISL6612CBZR5453	6-Jul-18	6-Jan-19	6-Jul-19	ISL6612ACBZ-T
ISL6612CBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6612ACBZ-T
ISL6612CRZ-TR5453	6-Jul-18	6-Jan-19	6-Jul-19	ISL6612CRZ-T
ISL6612CRZ-TS2568	6-Jul-18	6-Jul-19	6-Jan-20	ISL6612CRZ-T
ISL6612CRZ-TS2705	6-Jul-18	6-Jul-19	6-Jan-20	ISL6612CRZ-T

Exact Intersil Part # No other variation is being impacted.	Notice PLC18018 Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re-Design
ISL6612ECBZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6612ACBZ-T
ISL6612ECBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6612ACBZ-T
ISL6612EIBZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6612AIBZ-T
ISL6612EIBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6612AIBZ-T
ISL6613ACRZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6613BCRZ-T
ISL6613ACRZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6613BCRZ-T
ISL6613CRZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6613BCRZ-T
ISL6613CRZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6613BCRZ-T
ISL6613IRZ-TR5453	6-Jul-18	6-Jan-19	6-Jul-19	ISL6613BCRZ-T
ISL6615ACRZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6615AIRZ
ISL6615ACRZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6615AIRZ-T
ISL6615ACRZ-TR5453	6-Jul-18	6-Jan-19	6-Jul-19	ISL6615AIRZ-T
ISL6615ACRZ-TS2705	6-Jul-18	6-Jul-19	6-Jan-20	ISL6615AIRZ-T
ISL6615CRZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6615IRZ
ISL6615CRZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6615IRZ-T
ISL6620ACBZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6620ACRZ-T
ISL6620ACBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6620ACRZ-T
ISL6620CBZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6620CRZ-T
ISL6620CBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6620CRZ-T
ISL6622ACRZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6622AIRZ-T
ISL6622ACRZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL6622AIRZ-T
ISL6622ACRZ-TS2568	6-Jul-18	6-Jan-19	6-Jul-19	ISL6622AIRZ-T
ISL6622CBZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL6622CBZ-T
ISL6622CRZ-TS2568	6-Jul-18	6-Jul-19	6-Jan-20	ISL6622CRZ-T
ISL6622IRZS2705	6-Jul-18	6-Jul-19	6-Jan-20	ISL6622IRZ-TS2705
ISL68127IRA ZT7AR5761	6-Jul-18	6-Jan-19	6-Jul-19	ISL68127IRBZT7AR5761
ISL68127IRA Z-TR5761	6-Jul-18	6-Jan-19	6-Jul-19	ISL68127IRBZ-TR5761
ISL83202IPZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL83202IBZ
ISL83204AIBZ	6-Jul-18	6-Jul-19	6-Jan-20	none
ISL83204AIBZT	6-Jul-18	6-Jul-19	6-Jan-20	none
ISL83220ECVZ-TS2702	6-Jul-18	6-Jan-19	6-Jul-19	ISL83220ECVZ-T
ISL8392IBZ	6-Jul-18	6-Jan-19	6-Jul-19	none
ISL8392IBZ-T	6-Jul-18	6-Jan-19	6-Jul-19	none
ISL84053IVZ	6-Jul-18	6-Jan-19	6-Jul-19	ISL84053IBZ
ISL84053IVZ-T	6-Jul-18	6-Jan-19	6-Jul-19	ISL84053IBZ-T
ISL84521IBZ	6-Jul-18	6-Jan-19	6-Jul-19	none
ISL84521IBZ-T	6-Jul-18	6-Jan-19	6-Jul-19	none

Exact Intersil Part # No other variation is being impacted.	Notice PLC18018 Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re-Design
ISL84521IVZ	6-Jul-18	6-Jan-19	6-Jul-19	none
ISL84521IVZ-T	6-Jul-18	6-Jan-19	6-Jul-19	none
ISL8485CPZ	6-Jul-18	6-Jan-19	6-Jul-19	ISL8485ECBZ-T
ISL8485IPZ	6-Jul-18	6-Jan-19	6-Jul-19	ISL8485EIBZ-T
ISL8487EIPZ	6-Jul-18	6-Jan-19	6-Jul-19	ISL8487EIBZ-T
ISL8841AABZ	6-Jul-18	6-Jul-19	6-Jan-20	none
ISL8841AABZ-T	6-Jul-18	6-Jul-19	6-Jan-20	none
ISL8843ABZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL8843AABZ
ISL8843ABZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL8843AABZ-T
ISL8843MBZ	6-Jul-18	6-Jul-19	6-Jan-20	none
ISL8843MBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	none
ISL8845AMBZ	6-Jul-18	6-Jul-19	6-Jan-20	ISL8845AABZ
ISL8845AMBZ-T	6-Jul-18	6-Jul-19	6-Jan-20	ISL8845AABZ-T
ISL89400ABZ	6-Jul-18	6-Jan-19	6-Jul-19	none
ISL89400ABZ-T	6-Jul-18	6-Jan-19	6-Jul-19	none
ISL89400ABZ-TK	6-Jul-18	6-Jan-19	6-Jul-19	none
ISL89401ABZ-TK	6-Jul-18	6-Jan-19	6-Jul-19	ISL89401ABZ-T
ISL89411IPZ	6-Jul-18	6-Jan-19	6-Jul-19	none
X9221AWSZ	6-Jul-18	6-Jan-19	6-Jul-19	X9221AWSIZ
X9221AWSZT1	6-Jul-18	6-Jan-19	6-Jul-19	X9221AWSIZT1
X9241AMSZ	6-Jul-18	6-Jul-19	6-Jan-20	X9241AMSIZ
X9241AMSZT1	6-Jul-18	6-Jul-19	6-Jan-20	X9241AMSIZT1
X9241AUSZ	6-Jul-18	6-Jul-19	6-Jan-20	X9241AUSIZ
X9241AUSZT1	6-Jul-18	6-Jul-19	6-Jan-20	X9241AUSIZT1
X9241AYSIZ	6-Jul-18	6-Jul-19	6-Jan-20	X9241AYVIZ
X9241AYSIZT1	6-Jul-18	6-Jul-19	6-Jan-20	X9241AYVIZT1
X9241AYSZ	6-Jul-18	6-Jul-19	6-Jan-20	X9241AYVIZ
X9241AYSZT1	6-Jul-18	6-Jul-19	6-Jan-20	X9241AYVIZT1