



114 Old State Road
Ellisville, MO 63021
Phone: (636) 394-2877

Date: December 10th, 2012

Subject: End of Life Notice for TDC436 Fuses

Dear Valued Customer:

Effective immediately, Cooper Bussmann has discontinued the TDC436 Series of ¼" x 1-1/4" glass tube fuses.

Current ratings in the TDC436 Series included 800mA, 1A, 1.25A, 1.6A, 2A, 2.5A, 3.15A, 4A, 5A and 6.3A.

There are no recommended replacements for these parts.

If further information is required regarding your application's needs, please contact your Cooper Bussmann representative or FuseTech@cooperindustries.com.

We thank you for your continued support of the Cooper Bussmann brand of circuit protection products.

Regards,

Jim Chan

Senior Product Manager

Electronic Circuit Protection

Cooper Bussmann

Jim.Chan@CooperIndustries.com