

Sandall Road  
Wisbech  
PE13 2PS UK

**Tel:** +44 (0)1945 47 47 47  
**Fax:** +44 (0)1945 47 48 49

08 August 2008

Dear Customer

We have been advised by Taicom that the TMM72VSM device has been discontinued with immediate effect. The reason for this discontinuance is the mold tool has gone beyond its serviceable life, unfortunately due to low demand for this product it is not commercially viable to open a new mold tool.

There is no direct alternative available from Taicom, please contact our sales office to discuss other replacement options for this device.

Yours Sincerely

Anglia